


Rust House near Maysville Mason County Kentucky NOV 141977

Gloria Mills Kentucky Heritage Commission Frankfort, Kentucky March, 1977

Rust House Photo 1. Viewed from southwest. Original log barn on left. FEB 23 1978



Rust House near Maysville Mason County NOV 1 4 1977 Kentucky

Gloria Mills Kentucky Heritage Commission Frankfort, Kentucky March, 1977

Rust House Photo 2. Viewed from southwest.

FEB 2 3 1979



Rust House near Maysville Mason County Kentucky

MASON County NOV 1 4 1977 Daniel Kidd Kentucky Heritage Commission Frankfort, Kentucky July, 1977

Rust House Photo 3. Viewed from northeast.



Rust House near Maysville Mason County Kentucky MASON County Daniel Kidd Kentucky Heritage Commission Frankfort, Kentucky July, 1977

Rust House GG Photo 4. Open Stairway in central hall.

FLB 2 3 1978



Rust House near Maysville Mason County Kentucky

## NOV 1 4 1977

Daniel Kidd Kentucky Heritage Commission Frankfort, Kentucky July, 1977

Rust House Photo 5. Mantle and cupboards in east parlor.



Rust House near Maysville Mason County Kentucky NOV 1 4 1977

Gloria Mills Kentucky Heritage Commission Frankfort, Kentucky March, 1977

Rust House Photo 6. Mantle and cupboards in west parlor. FEB 2.3 1978



Rust House near Maysville Mason County Kentucky NOV 141977

Daniel Kidd Kentucky Heritage Commission Frankfort, Kentucky July, 1977

Rust House Photo 7. Second floor bedroom mantle.

FEB 2 3 1978



Rust House near Maysville Mason County NOV 141977 Kentucky

Daniel Kidd Kentucky Heritage Commission Frankfort, Kentucky July, 1977

Rust House Photo 8. Kitchen fireplace. FEB 2 3 1978