

KENTUCKY HISTORIC RESOURCES INVENTORY

Site No. Sc 334

✓
K 6
922

1. Historic Name(s) <u>(Matthew Henry) house</u>		22. ADD/County <u>Bluegrass 1 Sect</u> 105	
Original Owner <u>Matthew Henry</u>		23. U.S.G.S. Quadrant (15'/75') <u>Centerville v. c.</u> 047	
2. Present Name <u>Matthew Henry house</u>		24. UTM Reference	
3. Location <u>W side 922 at intersection w Johnson's Mill Road</u>		16	720480 4231380
4. Owner's Name <u>Joe Davis</u>		Zone Easting Northing	
5. Owner's Address <u>110 Clay Ingot Co, 914 Delaware, Lexington 40505</u>		25. Coordinate Accuracy <input type="checkbox"/>	
6. Open to Public Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	7. Visible from road Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	8. Ownership Private <input checked="" type="checkbox"/> Local <input type="checkbox"/> State <input type="checkbox"/> Federal <input type="checkbox"/>	
9. Local Contact/Organization		26. Prehistoric Site Object Historic Site Structure Building <input checked="" type="checkbox"/> Other	
10. Site Plan with North Arrow <u>see attached boundary form</u>		27. National Register District Name: 	
11. Architect		28. Significance Evaluation <input type="checkbox"/>	
12. Builder		29. Status <input type="checkbox"/> Date	
13. Date <u>c 1800?</u> A. <input checked="" type="checkbox"/> B. <input type="checkbox"/>		National Landmark <input type="checkbox"/>	
14. Style A. <u>Federal</u> <input checked="" type="checkbox"/> B. <input type="checkbox"/>		National Register <input type="checkbox"/>	
15. Original Use <u>residence</u> <input checked="" type="checkbox"/>		Landmark Certificate <input type="checkbox"/>	
16. Present use <u>vacant</u>		Kentucky Survey <input checked="" type="checkbox"/>	
17. Condition <u>fair</u> <input checked="" type="checkbox"/>		Local Landmark <input type="checkbox"/>	
18. Description <u>3 bay 1 1/2 story dry stone house w 1 room dry stone wing. Superior tooled masonry. 7 stone vousoirs (wide stones), quoins corners, simple painting, interior, 1 superior chimney w shoulders. Cornice returned on front, attic windows flanking</u> (Continue on Back) (over)		HABS/HAER <input type="checkbox"/>	
No. Stories <u>1 1/2</u> <input checked="" type="checkbox"/>		30. Historic Theme	
Single Pile <input checked="" type="checkbox"/> NA <input type="checkbox"/>		Primary <u>architecture</u> C	
Double Pile <input type="checkbox"/>		Secondary <u>settlement</u> K	
Floor Plan <u>hall-parlor</u> <input checked="" type="checkbox"/>		Other <u>milling industry</u> L	
Structural Fabric <u>stone</u> A. <input checked="" type="checkbox"/> B. <input type="checkbox"/>		31. Endangered Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
Decorative Fabric <u>vousoirs</u> A. <input checked="" type="checkbox"/> B. <input type="checkbox"/>		32. Preservation Project Status <input type="checkbox"/>	
Roof Form <u>gable</u>		Actual Cost in \$1,000s 	
19. History <u>House was built on 1000 acre land grant of Gen Wm Henry whose land included the mill below the house (now called Johnson's Mill) This house was the residence of Matthew</u> (over)		33. ATTACH PHOTO <u>in attached envelope</u>	
20. Significance <u>Very nice example early stone miller's house of prominent family; very visible location.</u>		Roll No. _____	
21. Source of Information <u>18. inspection</u> <u>19. 1970 inventory form</u>		Picture No. _____	
		Direction _____	
		34. Prepared by: <u>C.M. Wooley</u>	
		35. Organization _____	
		36. Date <u>1982</u>	
		37. Revision Dates _____	
		38. Staff Review _____	

18. cont.:

Chimney. Window frames and trim are carved from single piece of wood; nice 9 panel front door (frame here not pegged, but others are). *

(photo 4)

Two bay, 1 1/2 story wing on S end of house has exterior chimney; pegged frames w applied ooloo trim; 1 window on rear, 2 attic windows; 4 put log holes in S wall, but no door. Front wall of wing has been reworked, brick chimney tops added, dormer added on rear.

House located on top of drop to head in N. Elkhorn Creek. Picturesque iron bridge & mill dam on creek. Mill recently torn down.

19. cont.:

Henry. Subsequent owners were Mayruder, Cooper, Haun, Smith, Graves, Williams, Bryan, & Davis.

* Interior partition wall is of adged 3x4, split lathes, and plaster. Enclosed winding corner stair arises from rear of hall (S room) w space taken from parlor.

VERBAL BOUNDARY DESCRIPTION & JUSTIFICATION

Beginning at A at a fence corner NE of the house, thence with fence S 140 ft to another corner B, thence W with fence 145 ft to road C, thence with road 190 ft to D, thence leaving road 85 ft E to the beginning enclosing the stone house and about 1/2 acre. No other significant buildings at site.

SKETCH MAP OF SITE SHOWING BOUNDARIES AND KEY BUILDINGS AND FEATURES WITH NORTH ARROW.

