

El Paso and Southwestern Railway Water Supply System (Bonito Pipeline) NOV-2 | 1979 vicinity of Nogal, Lincoln Co., New Mexcio Lane Ittelson, August, 1978 SEP 18 1979

exposed section of pipeline showing 1908 flat steel wrapped pipe, c. 1914 round wire wrapped replacement pipe, and currently used metal pipe Photo #143



El Paso & Southwestern Railway Water Supply System (Bonito Pipeline) vicinity of Nogal, Lincoln Co., New Mexico Lane Ittelson, August, 1978 NOV 2 1979 exposed section of 1908 flat steel wrapped pipe; photo looking south Photo #293 SEP 18 1979



El Paso & Southwestern Railway Water Supply System (Bonito Pipeline) vicinity of Nogal, Lincoln Co., New Mexico 2000 Lane Ittelson, August, 1978 NOV **2 1** 1979

exposed section of 1908 flat steel wrapped pipe and c. 1914 round wire wrapped replacement pipe SEP + 8 1979 Photo #3/3