United States Department of the interior National Park Service

National Register of Historic Places Continuation Sheet

Section number Page		
SUPPLEMENTARY	LISTING RECORD	.:
NRIS Reference Number: 94000074	Date Listed	3/11/94
Hi Wo Company Grocery Property Name	<u>Cochise</u> County	<u>ID</u> State
<u>Historic Architectural Properties</u> Multiple Name	in Benson, Arizona	a, MPS
This property is listed in the National accordance with the attached not the following exceptions, exclusion the National Park Service certification.	mination documenta ns, or amendments	ation subject to , notwithstanding
Signature of the Keeper	3/11/94 Date of Act:	ion
Amended Items in Nomination: Function:		

<u>Commerce</u> is added as the main category for Historic Function. [This reflects a minor technical correction to reflect consistency with NR Bulletin 16A requirements that call for both main categories and subcategories for each selection.]

Materials:

Add Other: Metal to note the second floor exterior sheating.

Significance:

The box for Criterion C needs to be checked at the top of the page.

This information was confirmed with Reba Grandrud of the AZ SHPO.

DISTRIBUTION:

National Register property file
Nominating Authority (without nomination attachment)

OUB No. 1024-0018

United States Department of the Interior National Park Service

JAN 2 7 1994

RECEIVED

National Register of Historic Places Registration Form

NATIONAL REGISTER

This form is for use in nominating or requesting determinations of eligibility for individual properties or districts. See instructions in Guigelines for Completing National Register Forms (National Register Bulletin 16). Complete each item by marking "x" in the appropriate box or by entering the requested information. If an item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, styles, materials, and areas of significance, enter only the categories and subcategories listed in the instructions. For additional space use continuation sheets (Form 10-900a). Type all entries.

(Form 10-900a). Type all entries.						
1. Name of Property			· · · · · · · · · · · · · · · · · · ·	***		
	any Gro	cery		······································		······································
other names/site number						
2. Location						
	th Stre	et	· · · · · · · · · · · · · · · · · · ·		for publicatio	n
city, town Benson				NA vic	inity	
state Arizona code	AZ	county Cochise	code	003	zip code	85602
3. Classification						
Ownership of Property	Catagon	of Property	Number of E	lesources v	vithin Property	
X private	¥buildi		Contributing		contributing	,
public-local	distric		Contributing 1	NON	buildings	
public-rocar	site	- (buildings	
public-Federal	struct	····			sites structures	
		- · · -			objects	•
	objec	t .	1		Objects Total	
Name of colored multiple property that	:					والمناء
Name of related multiple property list Historic Architectura	ing: 1 Prope	rties in the	listed in the	_	resources pre	O
Benson, Arizona Surve			113100 117 1110		gister	
4. State/Federal Agency Certific	ation					
Signature of certifying official State or Federal agency and bureau In my opinion, the property med Signature of commenting or other official		not meet the National Regi	ster criteria. 🗌 s	Da Da	tion sheet.	
State or Federal agency and bureau						
5. National Park Service Certific	ation					
hereby, certify that this property is:						
entered in the National Register. See continuation sheet. determined eligible for the Nationa Register. See continuation sheet. determined not eligible for the National Register.	 	af R. Jusy	mi		3/11/94	
removed from the National Registe other, (explain:)						
		Signature of the	e Keeper		Date of A	ction

6. Function or Use	
Historic Functions (enter categories from instructions) Department Store	Current Functions (enter categories from instructions)Vacant
7. Description	•
Architectural Classification (enter categories from instructions)	Materials (enter categories from instructions)
	foundation adobe
No style Commercial	walls adobe, wood
	roof <u>metal</u>
	other

Describe present and historic physical appearance.

Summary: The Hi Wo Company Grocery, which opened in 1896, was one of Benson's first commercial buildings. Its exact construction date is unknown. It has been an integral part of the town's 4th Street commercial strip since the railroad era (1880-1910). Currently owned by the descendants of Hi Wo, an immigrant from China, the store was in operation until 1989, but the building is now vacant.

Location and Site: Located at 398 East 4th Street on the southwest corner of Gila and East 4th Streets, the Hi Wo Company Grocery occupies its original 25 X 150 ft. lot. The building was constructed along the front and side property lines, a typical practice of the era. At present, there is a vacant lot to the west.

Construction: The Hi Wo Company Grocery is a two-story structure with a basement. Massive adobe foundations support the exterior walls and redwood piers support the floors. The first-story walls are of adobe masonry and the lighter, second-story walls are of redwood frame construction sheathed with metal panels. The low pitched, gable roof is sheathed with corrugated metal. A stuccoed frame addition has been built to the south, probably in 1965.

Original Appearance: The rectangular adobe building had a large, high ceilinged, interior mercantile space with an addition to the rear which served as living quarters. These quarters eventually burned down. The East 4th Street facade was symmetrical with a centrally placed, one-light wood door which had wood storefront windows on either side and a transom above. The frame second story, which was added during Benson's historic period (before 1942), was sheathed in corrugated metal. The low pitched, front gable had a centrally placed vent door, directly above the entry. The interior mercantile space had wooden floors, plastered walls and corrugated metal ceilings. The staircases to the second story and basement were located at the south end. Built-in shelving, cabinetry and counters lined the east and west walls. The second story had redwood panelling throughout. The basement, which served as a storage area, featured a walk-in, wood-lined compartment for cheese storage.

Current Appearance: Although the condition of the exterior and interior of this building is poor, very few alterations have been made since the historic era. The building is still set up as a store with the original built-in features intact. Some of the original equipment, such as the meat grinder and cash register remain. The frame addition to the south (rear), which is not visible from East 4th Street, is compatible and, according to the niece of Hi Wo's daughter, probably replaces the living quarters which were destroyed by fire.

See continuation sheet

8. Statement of Significance		
Certifying official has considered the significance of this proper nationally	erty in relation to other properties: statewide X locally	
Applicable National Register Criteria A B C	D	
Criteria Considerations (Exceptions)	□D □E □F □G	
Areas of Significance (enter categories from instructions) Architecture	Period of Significance 1880-1942	Significant Dates 1896
	Cultural Affiliation	
Significant Person	Architect/Builder unknown	
State cimificance of property and justify exitoric enterior consi		Wasses rated about

State significance of property, and justify criteria, criteria considerations, and areas and periods of significance noted above Significance: The Hi Wo Company Store is locally significant under National Register Criterion C for its architectural contribution to Benson, Arizona, having been an integral part of Benson's commercial strip since the railroad era. Serving as a general merchandise store, it was part of this 4th Street spine which served as Benson's "Main Street" and focus of commercial development since the platting of the original townsite. Situated on a corner and adjacent to a vacant lot, this vernacular building has an unusual configuration of a frame attic story over adobe side walls. At this time the building is perceived as a free-standing object, differentiating it from the other commercial buildings along 4th Street, which share common walls.

Chain of Occupancy: The Hi Wo Company Grocery is located on the site of the original Rogers Brothers General Merchandise Store. Prior to its purchase in 1896 by Hi Wo,

the building is believed to have housed a lumber store.

Integrity: Very few alterations have been made to the Hi Wo Company Store. The historic integrity of this building is excellent, although its condition has seriously deteriorated over the years and stabilization is necessary.

See	continuat	ion s	heet
-----	-----------	-------	------

9. Major Bibliographical References	
"Grocery Opened in 1896," Centennia	al Feature.
"Sites Marked as Historical," <u>San F</u> p. 3.	Pedro Valley News, March 14, 1968,
Interview with Loretta Cellier, nied daughter of Hi Wo), February 11, 199	ce of Soledad Wo (owner and 92.
Hatch, Heather S. The Chinese in the In The Chinese Experience in Arizor (reprinted from Journal of Arizona Historical Society, Tucson.	the Southwest: A Photographic Recording and Northern Mexico, pp.31-48 History, Vol. 21). Arizona
	See continuation sheet
Previous documentation on file (NPS):	Discourse of a different days
preliminary determination of individual listing (36 CFR 67)	Primary location of additional data:
has been requested previously listed in the National Register	State historic preservation office Other State agency
previously determined eligible by the National Register	Federal agency
designated a National Historic Landmark	Local government
recorded by Historic American Buildings	☐ University
Survey #	Other
recorded by Historic American Engineering	Specify repository:
Record #	
0. Geographical Data	
Acreage of property086 acres	
JTM References	
12 [5] 3,61 8 5,01 [3,513,619,0,0]	B L L L L L L L L L L L L L L L L L L L
Zone Easting Northing	Zone Easting Northing
	D L L L L L L L L L L L L L L L L L L L
	See continuation sheet
Ashal Barradas Bassistina	
Verbal Boundary Description Boundaries are the same as those of further described as lot 17, Blk. 19 Historic Resource Map.	
	See continuation sheet
oundary Justification	
See accompanying Historic Resource	map.
	See continuation sheet
1. Form Prepared By	
	Janet H. Strittmatter (Partner)
rganization Johns & Strittmatter Inc.	date August 16, 1993
treet & number 2960 N. Swan, #217	telephone (602) 325-2591
city or town Tucson	state Arizona zip code 85712

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet


Section	number	Photos	Page	1
	HUHIDO		i ago	

THE FOLLOWING INFORMATION IS THE SAME FOR ALL PHOTOGRAPHS ACCOMPANYING THIS NOMINATION:

- 1). Hi Wo Company Grocery
- 2). Benson, Arizona
- 3). Janet Gibson
- 5). Johns & Strittmatter Inc.

INFORMATION FOR INDIVIDUAL PHOTOGRAPHS:

- 4). March 5, 1992
- 6). 3/4 view, facing southeast, of north (main) facade
- 7). #1
- 4). March 5, 1992
- 6). 3/4 view, facing southeast, of west facade
- 7). #2
- 4). March 5, 1992
- 6). 3/4 view, facing northwest, of east facade
- 7Ì. #3
- 4). February 11, 1992
- 6). Interior view, facing south, of cellar
- 7). #4
- 4). February 11, 1992
- 6). Interior view, facing north, of mercantile space
- 7). #
- 4). February 11, 1992
- 6). Interior view, facing south, of mercantile space
- 7). #6



Hi Wo Company Grocery 398 East 4th Street Benson, Arizona

