

Joan Hollowell November, 1984 Negatives in possession of owner

Northwest (facade) and northeast elevations, looking south.


Photo 1 of 8



Joan Hollowell November, 1984 Negative in Possession of owner

Interior: Livingroom fireplace

Photo 2 of 8.



Joan Hollowell November, 1984 Negative in possession of owner

Interior: Livingroom French doors

Photo 3 of 8



Joan Hollowell November, 1984 Negative in possession of owner

Interior: Waterfall light fixture/mitered box beams



Photo 5 of 8.

Joan Hollowell November, 1984 Negatives in possession of owner

Northeast elevation, looking southwest



November, 1984
Negative in possession of owner
Southeast elevation, facing northwest.

Photo 6 of 8

Joan Hollowell



Southwest elevation, facing northeast

Joan Hollowell November, 1984 Negatives in possession of owner

Photo 7 of 8



Leonard Grafield
April, 1985
State Office of Archaeology and Historic
Preservation

Garage, northwest facade Photo 8 of 8