

Photographer: Clifford M. Renshaw Date: October 1986 Negative filed at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, Rhode Island 02903

Exterior view facing south.

Photo #1

MAY 1 9 1987




Photographer: Clifford M. Renshaw Date: October 1986 Negative filed at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, Rhode Island 02903

Exterior view facing north.



Photographer: Clifford M. Renshaw Date: October 1986 Negative filed at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, Rhode Island 02903

Exterior view facing east showing rear ell.



Photographer: Clifford M. Renshaw Date: October 1986 Negative filed at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, Rhode Island 02903

Detail exterior view of front entrance.



Photographer: Clifford M. Renshaw Date: October 1986 Negative filed at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, Rhode Island 02903

Interior view of West Parlor, first floor, looking east.



Photographer: Clifford M. Renshaw Date: October 1986 Negative filed at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, Rhode Island 02903

Interior view of Front Stairhall, first floor, looking southeast. Photo #6



Photographer: Clifford M. Renshaw Date: October 1986 Negative filed at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, Rhode Island 02903

Interior view of Keeping Room, first floor, looking northeast.




Photographer: Clifford M. Renshaw Date: October 1986 Negative filed at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, Rhode Island 02903

Interior view of East Parlor, second floor, looking west.



Photographer: Clifford M. Renshaw Date: October 1986 Negative filed at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, Rhode Island 02903

Interior view of Rear Hall, first floor, looking west, showing original cell doors. Photo #9



Photographer: Clifford M. Renshaw Date: October 1986 Negative fileg at: Rhode Island Historical Preservation Commission 150 Benefit Street Providence, Rhode Island 02903

Interior view of typical cell, first floor, looking south.

Photo #10

MAY 19 1987