



ATHOL CAR. 10

CAROLINE CO. MD

PHOTO BY J.A. THOMPSON, NOV. 1988

NEG: MARYLAND SHPO

S. ELEVATION OF HOUSE

PHOTO #1 OF 19



ATHOL, CAR-10

CAROLINE CO., MD.

PHOTO BY J. A. THOMPSON

NOV. 1988

NEG: MARYLAND SHPO

LOOKING N.W. AT E, & S ELEVATIONS

PHOTO #2 OF 19



ATHOL, CAR-10

CAROLINE CO, MD.

PHOTO BY J. A. THOMPSON

NOV. 1988

NEGS; MARYLAND SHPO

LOOKING SE AT W + N ELEVATIONS

PHOTO #3 OF 19



ATHOL, CAR-10
CAROLINE CO., MD.
PHOTO BY J. A. THOMPSON
NOV. 1988
NEG: MARYLAND SHPO
NORTH ELEVATION
PHOTO # 4 OF 19



ATHOL, CAR-10

CAROLINE CO., MD.

PHOTO BY J.A. THOMPSON

NOV. 1988

NEG: MARYLAND SHPO

BRICK DETAIL, SW CORNER

PHOTO #5 OF 19



ATHOL, CAR-10

CAROLINE CO., MD


PHOTO BY J.A. THOMPSON

NOV. 1988

NEG: MARYLAND SHPO

BASEMENT WINDOW WITH WOOD GRILLS

PHOTO # 6 OF 19



ATHOL, CAR-10

CAROLINE CO., MD.

PHOTO BY J. A. THOMPSON

NOV. 1988

NEGO. MARYLAND SHPO

W. END OF BASEMENT SHOWING CHIMNEY BASE

PHOTO # 7 OF 19



ATHOL, - CAR-10

CAROLINE CO., MD.

PHOTO BY J. A. THOMPSON

NOV. 1988

NEG: MARYLAND SHPO

~~IS~~ LOOKING INTO W. ROOM FROM 1ST FLOOR

ENTRY HALL - MAIN ENTRANCE DOOR IS AT L.

PHOTO #8 OF 19



ATHOL, - CAR-10

CAROLINE CO, MD.

PHOTO BY J.A. THOMPSON

NOV, 1988

NEG: MARYLAND SHPO

LOOKING N. TOWARD REAR OF HOUSE IN FIRST
FLOOR ENTRY HALL SHOWING STAIRCASE

PHOTO # 9 OF 19



ATHOL, - CAR-10

CAROLINE CO, MD,

PHOTO BY J.A. THOMPSON

NOV, 1988

NEG: MARYLAND SHPO

LOOKING INTO E. ROOM FROM 1ST FLOOR
ENTRY HALL-

PHOTO #10 OF 19



ATHOL, CAR 10
CAROLINE CO., MD.
PHOTO BY J.A. THOMPSON
NOV. 1988
NEG. MARYLAND SHPO
LOOKING E. INTO 20TH C. ADDITION
FROM E ROOM, FIRST FLOOR

PHOTO #11 OF 19



ATHOL, CAR-10

CAROLINE CO., MD.

PHOTO BY J.A. THOMPSON

NOV. 1988

NEG: MARYLAND SHPO

ENTRANCE TO FIRST FLOOR HALL
ON NORTH SIDE (REAR)

PHOTO #12 OF 19



ATHOL, - CAR-10

CAROLINE CO., MD.

PHOTO BY J. A. THOMPSON

NOV. 1988

NEG: MARYLAND SHPO

UPPER SECTIONS OF STAIRS

FROM 1ST TO 2ND FLOOR - LOOKING NE

PHOTO #13 OF 19



ATNOL - CAR. - 10

CAROLINE CO, MD

PHOTO BY J. A. THOMPSON

NOV, 1988

NEG: MARYLAND SHPO

2ND FLOOR - LOOKING E AT STAIRS
FROM WEST ROOM SHOWING DOOR
FRAME AND LATH.

PHOTO #14 OF 19



ATHOL - CAR-10

CAROLINE CO., MD.

PHOTO BY J.A. THOMPSON

NOV. 1988

NEG: MARYLAND SHPD

STAIRS FROM 2ND FLOOR TO ATTIC

CROSSING WINDOW IN NORTH WALL

PHOTO #15 OF 19



ATHOL, - CAR-10

CAROLINE CO., MD.

PHOTO BY J. A. THOMPSON

NOV. 1988

NEG: MARYLAND SHPO

TOP OF STAIRS AT ATTIC LEVEL

LOOKING EAST AT WALL AND

DOOR^T EAST SECTION OF ATTIC

PHOTO #16 OF 19



ATHOL, - CAR-10

CAROLINE CO., MD.

PHOTO BY J. A. THOMPSON

NOV. 1988

NEG: MARYLAND SHPO

LOOKING EAST INTO EAST
SECTION OF ATTIC

PHOTO #17 OF 19



ATHOL, - CAR-10

CAROLINE CO., MD.

PHOTO BY J. A. THOMPSON

NOV. 1988

NEG: MARYLAND SHPO

NON-CONTRIBUTING OUTBUILDING
CAMERA FACING SW

PHOTO #18 OF 19



ATHOL, - CAR-10

CAROLINE CO, MD.

PHOTO BY J. A. THOMPSON

NOV. 1988

NEG: MARYLAND SHPO

NON-CONTRIBUTING OUTBUILDING
CAMERA FACING N.E

PHOTO #19 OF 19