| | KENTUCKY | Y HIS | TORIC RESOUR | CES IN | IVENTORY Ck-65 | |
|---|--|-------------------------|--|-----------------------|--|--|
| 1. Historic Name (s) Dailey/Milton Holliday House | | | | | 22. ADD/County Bluegrass/Clark | |
| Original Owner pro | bably Milton Holl | iday | 7 | | 23. Zoning Classification | |
| Present Name | | | | | Magisterial District 24. U.S.G. S. Quadrant (15'/75') | |
| 3. Owner's Name | | | | | Ford | |
| Nic | holas H. Rice | | | | 25, UTM Reference | |
| 4. Owner's Address | | | | | | |
| 10, Lexington 40511 5. Location | Jones Murser | y_Ro | L. | · · | Zone Easting Norming | |
| | es Nursery Road | | | | 26. Prehistoric Site Object Historic Site Structure | |
| 6. Open to Public | 7. Visible from road | | 8. Ownership | | Building | |
| Yes No | Yes No | | Private | x | 27. District Yes No | |
| 9. Local Contact/Organization | | | Local | 11 | Name: | |
| | | | Federal | | 28. Significance Evaluation | |
| 10. Site Plan with North Arrow | | 11. A | architect | 100 | | |
| | | | | . | 29. Status Date | |
| | | 12. Builder | | | National Landmark | |
| | | 13. D | late | | Landmark Certificate | |
| | | | | | Kentucky Survey . x2/17/77 | |
| | | 14. S | tyle | П | Local Landmark | |
| | | 15. Original Use | | | HABS/HAER | |
| · · · · · · | 15. Original Use 30. Theme <u>dwelling</u> Primary <u>architecture</u> 16. Present Use Secondary | | · · · · · · · · · · · · · · · · · · · | | | |
| | | 16. Present Use | | | Secondary | |
| | | | welling | <u> </u> | Other | |
| | | 17. Condition | | | 31. Endangered | |
| | | | ior terrible | | 32. | |
| 18 Description Log dog stone chimneys hav are the Greek deta pilasters. Guttae way (open string). | <pre>ils: Greek keys used for dentils</pre> | t si at t . G | gnificant feat he tops of flu reeks keys on | ures ted stair- | АТТАСН РНОТО | |
| Stephen L. Milton A. H | mily graveyard. Holliday b. 1824; olliday b. 1817; | d. 1 | | | | |
| - "М. Но | liday" 1877 Atlas | | | | Do11 / #11 20 | |
| M. Holiday or F. Jones 1860? | | | as | | Roll No. <u>Roll 4 #11-20</u> Picture No Direction | |
| 20 Significance Annaront | ly built by Milto | n Ho | liday, this wa | S | 33. Tape No. Negative No. | |
| originally a log de by an early owner w knowledge of the G include oversized a | ogtrot structure. who had an exjube reek Revival styl moldings, Greek k | Th rant e. eys | e house was sh and provincia Whimsical deta on the corner | eathed 1 ils | d 34. Prepared by: <u>ACW – CMT</u> 35. Organization | |
| pilasters, and a series of guttae on the contract than the more standard use of dentals. | | | | atner | 36. Date Fall 1976 | |
| 21. Source of Information | | | Picture No. Direction Direction 23. Tape No. Direction 33. Tape No. Negative No. | | | |