Form 10-300 (July 1969)		S DEPARTMENT OF		2	STATE: Maine		
N	NATIONAL REGISTER OF HISTORIC PLACES INVENTORY - NOMINATION FORM			CES	Cumberland FOR NPS USE ONLY		
					ENTRY NUMBER	DATE	
	(Type all entrie	s — complete app	licable sectio	ons)			
I. NAME	<del>•••••••</del>						
COMMON:	o Norma -						
AND/OR HI	La Mansion	····					
Morse-	100y House						
2. LOCATION							
STREET A	D NUMBER:						
109 Da	nforth Stree	t, at Park St	reet				
		i saf <b>u</b> ng sa ki ki ki					
Portla	10		CODE	COUNTY:	······································		
Maine			CODE	-	l a u d	COD	
3. CLASSIFIC				Cumber	Lano	I	
Land the second s	TEGORY		0000000		CT A TILC	ACCESSIBLE	
(0	heck One)		OWNERSHIP		STATUS	TO THE PUBLI	
District	🛛 Building	Public	Public Acquisi	tion:	🕱 Occupied	Yes:	
🗌 Site	Structure	🗶 Private	🗌 🗌 In Pro	cess	Unoccupied	Restricted	
( C	Object	🔲 Both	🗌 Being	Considered	Preservation wor		
					in progress	N∘	
PRESENT	SE (Check One or )	More as Appropriate)				-	
Agricul	vijal 🗋 G	overnment	Park		Transportation	Comments	
Commer	cial 🗌 Ir	ndustrial [	] Private Resid	ence	Other (Specify)		
🔲 Educati			Religious	-			
Enterta	nment 🗶 M	useum	Scientific	-			
P	PROPERTY						
OWNER'S N		Dec					
MIS. WI	D NUMBER:	President, Vi	ctoria Soc	clety of M	Maine Women		
	forth Stree	+			•		
CITY OR TO	and the second se	<u> </u>		STATE:	· · · · · · · · · · · · · · · · · · ·	CODE	
Portla	d			Mair	1e		
5. LOCATION	OF LEGAL DESC	CRIPTION					
COURTHOU	SE, REGISTRY OF	DEEDS, ETC:					
	and County (	Courthouse					
STREET AN	DNUMBER:						
CITY OR TO	WNI			STATE			
				STATE		CODE	
Portlar	a			Mair			
	TATION IN EXIS			Mali	<u>ie</u>		
TITLE OF	the second s						
Histori	c American I	Buildings Sur	vev (2 she	ets and ]	7 photos)		
DATE OF S	JRVEY: 1936		Federal	State		Local	
1	Y FOR SURVEY RE			2 82622			
Divisio	n of Prints	and Photogra		ry of Cor	igress		
JAIRCELAN	S NOMBER:	9.20 -		∑l in f£ i'	to retails or	per starocs	
CITY OR TO	WN:			STATE:		CODE	
Washing	ton	20540			D. C.		
Maonting	0011	<u> <u> </u> <u></u></u>					

STATE:

COUNTY:

FOR NPS USE ONLY

DATE

	1.00	
1	1.	
/	· · ·	

¢

7.	DESCRIPTION								
		(Check One)							
	CONDITION	Excellent	🗌 Good	🔀 Fair	🗌 Dete	eriorated	🗌 Ruins	Unexposed	
			(Check Or	ie)			(Che	ck One)	
		Alter	ed	😰 Unaltered			Moved	😰 Original Site	

DESCRIBE THE PRESENT AND ORIGINAL (If known) PHYSICAL APPEARANCE

Victoria Mansion is a large two-and-one-half brick structure with an irregular main block, a projecting central four-stage entrance tower, and a low hip roof with subsidary gables. The house is about 62 feet wide and 65 feet deep, with a service wing extending further to the rear. The walls are of brick stuccoed to resemble brownstone ashlar and the elaborate carved trim is of brownstone, except for the bracketed wooden cornice. The corners and angles of the house are prominently marked by rusticated quoins. The roofs are of metal.

The main (south) facade is five bays wide, with offset bays, and is dominated by a centrally-located, projecting square entrance tower that rises in four-stages. The round-arch door in the tower's first story is sheltered by a one-story portico with balustraded roof and two pairs of fully fluted Ionic columns. A larger one-story porch, with matching balustrade and two Ionic columns, extends across the face of the two bays which flank the tower to the west (left). The second-story front of the tower has a large flat-arch window decorated by a classical triangular pediment and framing pilasters. The second-stage of the tower on its west (side) face has a round-arch window. Both faces in the third stage have round windows and the fourth stage is comprised of a belfry story, with three narrow round arched and pilaster windows set in each elevation.

The wide bay to the east (right) of the tower projects forward from the tower and its first-story contains a narrower projecting bay with three narrow flat-arch windows grouped between corner pilasters. Another set of flat-arched triple windows appears in the second story above, the bay, this time crowned by a wide triangular pediment with elaborately carved consoles. The gable roof, which projects over this wide east bay, is bracketed like the main roof, and its end is treated as a pediment. First-story windows are full-length and, except on the south (main) facade, are generally topped by segmental arches and crowned by triangular pediments with consoles. Second story windows are round-arched and topped by prominent segmental pediments with carved brownstone consoles.

The house has a center hall plan. The entrance door in the tower opens into a vestibule, beyond which a 12-foot wide hall, open to the third floor, extends through the house to the rear. In the center of the hall, at about midpoint, is a lavishly carved flying staircase of San Domingo mahogany which rises to a landing lighted by a stained glass window, and then continues upward to the third floor. To the right (east) of the hall are the music room, the dining room with hand-carved panelled walls, and, in the rear, the library. The entire left side of the hall is occupied by a parlor which measures approximately 18 by 32 feet in size.

The interiors are generally decorated in the Louis XV style and are remarkably elaborate. Each room ) on the first floor is trimmed in a different wood - Brazilian rosewood, walnut, mahongany; every room has an S

SIGNIFICANCE				
PERIOD (Check One or More as A)	ppropriate)			
Pre-Columbian	16th Century		18th Century	20th Century
15th Century	17th Century		🕱 19th Century	
SPECIFIC DATE(S) (If Applicable	and Known) 1859-63		<u>`</u>	
AREAS OF SIGNIFICANCE (Check		e)		
Abor iginal	Education		Political	🔲 Urban Planning
Prehistoric	Engineering		Religion/Phi-	Other (Specify)
🔲 Historic	Industry		losophy	
Agriculture	Invention		Science	
X Architecture	Landscape		Sculpture	
Art	Architecture		Social/Human-	
	Literature		itarian	
Communications	Military		Theater	
Conservation	🗌 Music		Transportation	

STATEMENT OF SIGNIFICANCE

Designed by the architect Henry Austin and with extraordinary elaborate interiors by the artist-decorator Giovanni Guidirini, the Victoria Mansion, erected in 1859-63, is one of the finest and leastaltered examples in the United States of a large Italianate Villa-styled brick and brownstone town house.

## History

Plans for the house, originally intended as a summer residence, were prepared by Henry Austin, architect of New Haven, Connecticut. The elaborate interior ceiling and wall decorations were designed by Giovanni Guidirini, artist-decorator of New York City, who imported 11 Italian artists to execute his plans. Built for Ruggles Sylvester Morse, a New Orleans hotel owner, construction began in 1859 and due to delays caused by the Civil War, was not completed until 1863. Francis D. Little was the builder and the cost of construction is said to have amounted to \$400,000. In 1895 the house was acquired by J. R. Libby, a Portland merchant.

In 1943 the little-altered mansion was donated to the Victoria Society of Maine Women.

SEE INSTRUCTIONS

9. MAJOR BIBLIOGRAPHICAL REFERENCES						
Talbot F. Hamlin, Greek Revival Architecture in America (New York, 1944),						
161, 175. Dorothy and Richard Pratt, A Guide to Early American Homes - North (New York,						
1956), 67.	Early American Homes - North (New Yor	·k,				
Arnold Nicholson, American Houses in H	istory (New York, 1965), 52					
Current Scopher Tunnard and Henry H. Reed.	American Skuling (Dector JOEC) 311					
man down, images of American Living	(Philadelphia & New York, 1964), 318,					
322, 323. Wendell D. Garrett, Paul F. Norton, Al	an Gowang Joseph M. Butler Mt.					
In America, The 19th Century (New	York, 1969), 110-111					
IV. GEUGRAPHICAL DATA	LATITUDE AND LONGITUDE COORDINATES					
	DEFINING THE CENTER POINT OF A PROPERTY OF LESS THAN TEN ACRES					
CORNER LATITUDE LONGITUDE	LATITUDE LONGITUDE					
NW 0, " 0, "	Degrees Minutes Seconds Degrees Minutes Second 43° 39' 06' 70° 15' 40					
NF 0, , , , , , , , , , , , , , , , , , ,						
SE SE OUDAT SAVET ALL TROUBLING TRANSFER	orate interiors , the article-lecord i , are such as in the set is are of the	det n. Tra				
APPROVIMATE ACREACE OF NOMINATED PROPERTY.						
LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERL	APPING STATE OR COUNTY BOUNDARIES	S E				
STATE: CODE	COUNTY					
STATE: CODE	COUNTY: COE	E				
STATE: TO SELO .C. D. DOUDOURNO . D. G.	COTATA DOCTORS IN COLORADOR COL	Z S				
STATE: CODE	COUNTY: COD					
austic ) and s .sear & rosesvir ( asign for	act digt. Laure and a port of an	- π				
11. FORM PREPARED BIOS DO EVELOS OS DOS	I amper construction borgh in L''	⊂				
Charles W. Snell, Survey Historian		· · · O				
ORGANIZATION Division of History, Office	of Archeology and DATE					
Historic Preservation, National Park Se						
STREET AND NUMBER:		0				
801 19th Street, N. W.	STATE COD	<b>Z</b>				
Washington	D. C. NATIONAL REGISTER VERIFICATION	~				
Washington 12. STATE LIAISON OFFICER CERTIFICATION	NATIONAL REGISTER VERIFICATION					
As the designated State Liaison Officer for the Na-	I hereby certify that this property is included in the					
tional Historic Preservation Act of 1966 (Public Law 89-665), I hereby nominate this property for inclusion	National Register.					
in the National Register and certify that it has been						
evaluated according to the criteria and procedures set						
forth by the National Park Service. The recommended	Chief, Office of Archeology and Historic Preservati	on				
level of significance of this nomination is: National						
Name	Date	-				
Name	ATTEST:	ł				
Title						
	Keeper of The National Register					
Date	Date					
		,				

Form	10-300a
(July	1969)

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

## NATIONAL REGISTER OF HISTORIC PLACES

## **INVENTORY - NOMINATION FORM**

(Continuation Sheet)

Continued

Maine	
Cumberland	
FOR NPS USE ONL	Y
ENTRY NUMBER	DATE

(Number all entries) 7. Description

page 1

elaborate rocco plaster cornice gilded with gold leaf. The walls and ceilings are decorated with frescos comprised of painted medallions showing scenes of Italian peasant life. Seven of the fireplaces have intricately carved Carrara marble mantels. The carved panelled doors are 10 1/2 feet high and have silver-plated knobs and hinges. The original and elaborate gasoliers are also still in place.

The lavish decorations are continued on the second and even up through the third floor. The second floor has four bedrooms, a dressing room, and smoking room; the third story contains three more bedrooms and a large billiard room.

The exterior and interior of the house are unaltered. While the overall condition of the structure is excellent, a very serious condition has developed that will cause irremediable damage to the rich interiors unless quickly corrected: The original metal roofs have sprung a series of leaks and considerable amounts of water have begun to work downward. Some damage has already occured to the plaster on the third floor.

The Victoria Mansion is open to visitors as a furnished historic house exhibit.