	Form 10-300 (Rev. 6-72)		S DEPARTMENT OF		INTERIOR		New Jersey			]			
	NATIONAL REGISTER OF HISTORIC PLACES       Monmouth         INVENTORY - NOMINATION FORM       FOR NPS USE ONLY										H		
	(Type all entries - complete applicable sections)												
	1. NAME	/4	$\times$	)									
	C OMMON:	Alle Alle	en House							2			
	AND/OR HIS	TORIC:				<u> </u>	· · · · · · · · · · · · · · · · · · ·			2	Щ		
	2. LOCATION STREET AN		l Street an	id 'S;	ycamoj	re Ave.				2.65961	57966		
	CITY OR TO	wn: Shrewsbu	ıry			CONGRESSION Third	ONAL DISTRICT:				C.		
	STATE	New Jers	Sey		CODE 34	COUNTY:							
	3. CLASSIFICA	TION			۹				1				
l S	•	TEGORY neck One)		OWNER	RSHIP		STATUS	1	SSIBLE PUBLIC	]			
T I O N	District Site	🗶 Building 🗋 Structure ] Object	□ Public Ž Private □ Both	t	Acquisiti   In Proc   Being (		<ul> <li>Occupied</li> <li>Unoccupied</li> <li>Preservation worl in progress</li> </ul>	Yes: Restricted rk Unrestricted K No					
υ	PRESENT U	SE (Check One or M	l Iore as Appropriate)	Į		<u> </u>	4	<u> </u>		1			
STRU	<ul> <li>Agricult</li> <li>Commerce</li> <li>Education</li> <li>Entertain</li> </ul>	ial 🗌 Ind	dustrial [		ate Reside gious		] Transportation ] Other <i>(Specify)</i>	Comm	ents				
z	4. OWNER OF PROPERTY												
·		Monmouth	County Hi	sto	rical	Society				STATE			
ш	STREET AN	STREET AND NUMBER: 70 Court Street											
S	CITY OR TO	Freehold	-			STATE:	New Jersey		34 v				
		OF LEGAL DESC											
	COURTHOUS	Monmouth	County Ha	11 (	of Rec	ords				NOUN			
	STREET AN	STREET AND NUMBER: Court and Main Sts.											
	CITY OR TO	Freehold STATE CODE STATE STAT									-		
		6. REPRESENTATION IN EXISTING SURVEYS TITLE OF SURVEY: HABS #228											
		DATE OF SURVEY: 1/25/37 X Federal State County DEPOSITORY FOR SURVEY RECORDS:											
	DEPOSITOR	Library		K OS	ENTRY NUMBER								
	STREET AN	D NUMBER:							19	ň	וח		
	CITY OR TO	Washingt	on ·		<u> </u>	STATE:	D.C.	c	ODE	┡ 「	<		
	<b>I</b>									DATE			

•

.

DESCRIPTION										
CONDITION	(Check One)									
	∑ Excellent	🗌 Good	🔲 Fair	🗋 De	teri ora te d	🗌 Ruins	Unexposed			
		(Check Or	ne)		(Check One)					
	Alter	ed	Unaltered			Moved	XX Original Site			
	DESCRIPTION	CONDITION	CONDITION X Excellent Good	CONDITION	(Che CONDITION	(Check One) CONDITION CONDITION (Check One) (Check One)	(Check One) CONDITION CONDITION (Check One) (Check One) (Check One) (Check One) (Check One)	(Check One)  CONDITION  CONDITION CONDITION CONDITION CONDITION CONDITION CONDITION CONDITION CONDITION CONDITION CONDITI		

DESCRIBE THE PRESENT AND ORIGINAL (if known) PHYSICAL APPEARANCE

The Allen House was built sometime after 1670 and before 1688 by Judah Allen with a kitchen wing and milk room added at a later date. The house suffered many additions and alterations, particularly during the Victorian era. These have been rmoved and the house restored to its mid-18th C. app<sup>e</sup>arance when it was a tavern known as the Sign of the Blue Ball.

**EXTERIOR** The main portion of the house faces south. It is a  $2\frac{1}{2}$  story with a full gambrel roof with a curved overhang rear. The roof is newly wooden shingled and the sides are covered with round-butt shingles made of redwood, 3 ft. long with 14" to the weather. The original shingles were Jersey white cedar, but were changed to redwood for durability.

The kitchen wing, or west wing, is one story with a gable roof of new wooden shingles. In the front there is an overhanging eave which is sheathed beneath with a boxed wooden cornice. The wing is covered with clapboarding witha beadededge, sme of which is old (probably original) on the south wall. In the rear, a leanto was added at a later date to enclose a milkroom and a woodshed.

S

ᆔ

C

C

Ο

z

 $\boldsymbol{\sim}$ 

There are two chimneys in the house, one in the center of the interior at the west gable and and one at the west gable end of the kitchen wing. The middle chimney has been restored from the roof line up and the kitchen chimney has been heavily altered. The back of the kitchen fireplace is exposed on the outside wall and theback of the middle fireplace, originally outside, is exposed as the eastern interior wall of the kitchen. A beenive oven has been restored from openings in the original kitchen fireplace to protrude beyond the puter wall of the west gable end of the wing.

All window frames and sash have been restored. 12/12 on the first floor of the main structure, 12/8 on the second, and 6/6 in the kitchen wing. Panelled shutters have been restored on all ground floor windows on the south, east and north sides.

**INTERIOR** The first two stories of the main house have two rooms of identical size on the first and second floors and an open attic which was partitioned off in the early 19th century. The front door opens directly into the main room on the first floor. A stair hall is enclosed in the northeast corner, access being gained from the main room. The small rear room opens directly into the main room. The arrangement is the same on the second floor.

The massive chimney at the west gable end of the main structure supports four fireplaces, two down and two up. The fireplace in the main room measures  $7\frac{1}{2}$  ft. and has . round sides and plastered interior. The hearth is composed of old square bricks not original to the house. The fireplace

(cont. page 2)

	A		
PERIOD (Check One or More as	s Appropriate)		
• Pre-Columbian	16th Century	👷 18th Century	20th Century
15th Century	17th Century	19th Century	
SPECIFIC DATE(S) (If Applica	ble and Known)	•	ę
AREAS OF SIGNIFICANCE (CI	neck One or More as Appropri	ate)	
Abor iginal	Education	Political	📋 Urban Planning
Prehistoric	Engineering	Religion/Phi-	Other (Specify)
Historic	Industry	. losophy	
Agriculture	Invention	Science	6
XX Architecture	Landscape	Sculpture	
Art	Architecture	Social/Human-	
Commerce	Literature	itarian	•
Communications	XX Military	Theater	
Conservation	Music	Transportation	

The Allen House is significent architecturally because it is one of the earliest remaining pre-Revolutionary houses still standing in Monmouth County. It is a unigue local example of the combination of English and Dutch building styles. Essentially Georgian in style, it has a number of details which illustrate the Dutch influence prevelant in northeastern New Jersey. The size and proportions of the two and a half story house are quite remarkable for its early date, making it perhaps one of the most substantial and pretentious survivals of this early time.

The house is an intergral part of a group of buildings known as the historic Four Corners of Shrewsbury. The town is one of the earliest settlements in New Jersey and was settled under the terms of the Monmouth Patent granted by Governor Nicobls of New York in April, 1665. Judah Allen is listed as a patentee in Shrewsbury in 1670, receiving 272 acres. The house was built prior to 1688, as it is mentioned in the Shrewsbury Friends' Records as a scene of a family wedding.

On or about 1754, after intervening owners, the property was acquired by Josiah Halstead who operated it as a tavern for twenty years. It is to this period the house has been restored.

It is significent militarily because in 1779 it was the scene of a famous local massacre. A guard of 12 men were quartered in the house for the protection of the village. hand of 5 Tory refugees from Sandy Hook hid among the tombstones  $\phi$ f Christ Church and suprised the troops in the house. They killed three of them and took the other 9 prisoner.

> NATIONAI REGISTEF



S

لغا

S

9. MJ	JOR	BIBLIOGI	RAPHICA	LR	FERE	NCES										
В	Bailey, Rosalie, <u>Pre-Revolutionary</u> Sutch Houses and Families in Northern New Jersey and Southern New York, Dover, N.J., 1968.															
E N	Northern New Jersey and Southern New York, Dover, N.J., 1968. Ellis, Franklin, <u>History of Monmouth County. N.J.</u> , P.T. Peck & co.															
P	hila	adelph on, Wi	nia, l	.88	5.											
0	f N	.J F	ress	Pri	ntir	g and	l Pu	bl.		Pat	terso	n. 190	01.			
							Eas	te	rr	n New	Jers	ev. 10	509-1	702,	Prir	nceton
		ersity pson,		-			len	0	ne	s T.in	eof	Their	Desc	ender	nte i	n
		.with													105 1	<u> </u>
10. C	EOG	RAPHICA	L DATA						•							
		IATIJUDE			,		-	0 - R			NING TH	AND LONG	POINT	OF A PRO		
co	RNER	LA	TITUDE		L	ONGITU	DE		L		ATITUDE			LONGIT		
	NW	Degrees Mi o	nutes Sec	onds #	Degrees	s Minutes	Second #	s		Degrees 40 o	Minutes 19,	Seconds 20 #	Degree 74	s Minute	s Seco	nds
1	NE	o	•			• •					-,					
	SE	0	•		. c	•	-									
	SW PROXI	MATE ACF	REAGE OF	NOM		PROPE	• • • • • • •	<u> </u> 1호	1	acres			1		_	
IL IS	TALL	STATES	AND COU	NTIES	FOR PI	ROPERTI	ESOVE	RLA	AP	PING ST	ATEOR	OUNTY BO	DUNDAR	ÈS		
ST	ATE:	,					COD	E	cc	UNTY	1	> · REC	ÊIVE[]	(j)		
STA	ATE:		-	÷		•	COD	E	cc	DUNTY:	1-1	. * pi _	J 19	74 5		
, ST/	TE:						COD	E	cc	DUNTY:	17	NATI REGI	ONAL		co	
STA	ATE:						COD	E	cc	DUNTY:	<u> </u>		<u>012.</u>	$\bigcirc$	c	
					•		[	]				VII.	TIV.	*_^		ス
		PREPARE	EDBY													c
		М	Irs. M	ary	r Lou	Stro	ong.	Tru	us	stee:	Char	les Lj	vle.	Direc	tor	
OR													рат Ма	rch 2	28. 1	978 -
STR	MO	AND NUMB	Coun	lty	Hist	orica	1 S	oci	ie	ety						
		70 C	ourt	St.												z
СІТ		TOWN:						5	ST.	ATE	New	Jerse	∋у	<b>i</b>	-34	
112 8	Fre	eehold Liaison	OFFICE		RTIFIC	ATION				N	ATIONA	REGIST	ER VER	IFICAT		r i
	<u>, 4</u> , r	LIAISUN	011101									- NC 0101				
	As the	designate	ed State I	Liaiso	on Offic	er for th	e Na-									
		Historic F						.		-	-	hat this p	roperty i	is includ	ed in th	e
		), I hereby			•	-				Nationa.	l Registe	r. ',				
		National I	0		•				1 R							<i>.</i>
		ited accorç ov the Nati				-		- 11			ur	u	Del	aced	ee	
	forth by the National Park Service. The recommended level of significance of this nomination is:								Director,	Office of	Archeology	and Hist	toric Pres	servation		
	National State Local XX										- 10 - 0	/				
							Date 578/24						_			
r	Name	100	gri			n				ATTEST	·.					
		/Joseph	n'T. Ba	arbe	r						1		11		/	
	Title Acting Comm., Dept. of Env.											///	1		<u> </u>	
		Protec			<u></u> 0			-			Keepe	r of The I	VVV Vational	Registe	7b	•
	_		•	071						Tr = A =		[m	, 7	V	•	
	Date _	ahutt	. 16, 1	.714				-		Date		5 /	<u> </u>	7		

☆ U.S. GOVERNMENT PRINTING OFFICE : 1973-729-147/1442 3-1

• 1

RECEIVE ATIONAL	STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE . REGISTER OF HISTORIC PLACES	STATE New Jersey County Monmouth	
NATIONAL E	INVENTORY - NOMINATION FORM	FOR NPS USE ONL	Y DATE
REGISTER OF	(Continuation Sheet)	MAY 8 1974	
(Number ell entries) 7. continued	Allen House Monmouth 025		

in the rear chamber is diagonal on the west inner wall with an arched opening. The woodwork, floorboards, chair rail and doors on the first floor have been restored and the walls and ceilings replastered.

New Jersey 34

The front upstairs chamber contains a mid 18th century panelled room-end with a central fireplace. To the left of the fireplace is a panelled closet door. The rear chamber has a diagonal fireplace corresponding to the room beneath witha simple mantlepiece, c. 1800. In the rear chamber some panelling and a panelled closet door with Queen Ann hinges remains to the right of the fireplace. On the east wall original vertical sheathing with tongue and groove construction remains. The floorboards, chair rail, doors, baseboard, doorway and window moldings have been restored in both rooms and the ceilings and walls have been replasterd.

The stairs are an original feature, rising to the second floor with one landing and continuing to the attic from a small second floor stairhall. The handrail and balusters rise directly from the stringer, not the threads. The downstairs stair hall has a wall seperating it from the rear chamber which contains the original partition of wide vertical boards with a beaded edge and still retaining their old red stain.

In the kitchen wing a large hearth is located on the west wall with a hewn lintel (mostly original)  $9\frac{1}{2}$  ft. long. Two bake oven openings were discovered and restored in the hearth, one on the back wall and the other on the right side. The To the ... hearth has been res tored with old square brick. left is a door opening to a boxed stairway leading to an open The original beams are exposed on the ceiling and attic. the floorboards; baseboards, door and window moldings have been restored on the west, south and east walls. Two door openings are located on the north wall leading to a leanto addition with a milk room, constructed 3 ft. below ground level and woodshed ( now used as a kitchen and toilet).

<u>OUTBUILDINGS</u> A short distance to the west of the kitchen wing is a brick smokehouse covered with a gable roof with **new** wooden shingles. The south wall has a double door constructed of vertical boards with beaded edge. Two of the four strap hinges appear to be the original. There is a small window on the east gable end which is a later addition. Three small ventilating holes can been seen high on the same east wall and one in the middle of the north wall.

Restoration of the house began in 1970. The house will be a museum.