Iowa Site Inventory
Office of Historic Preservation
Iowa State Historical Department
East 12th & Grand Avenue
Des Moines, Iowa 50319

T-86 N

Site Number	14	
District Name		
Man Reference #	14	

Des Moines, Iowa 50319			Ma	p Reference #	14	
Identification						
	Round Bar	n, Bruce Townsh	vin Sactio	n 6 Bonton	Caumbaa	
1. Site Name						
2. Village/Town/City_		Porte Townshi West of US			ountyBe	nton
3. Street Address		86 N	210	12 W	6 NW	½ of SE ½
4. Legal Location	Urban:	subdivision		block	DNW_ parcel	<u> 古 OT St </u>
	Rural:	township		range	section	% section of % section
	15	. 559 310	. / 681	660 .	logg who	
		easting 559,310 (northing 4,001	,000; Acreage_	iess thai	n one acre
6. Owner(s) Name _	D D #2		- C:+-		50(51	
7. Owner(s) Address	R. R. #3		te City (City)	l owa		(Zip)
						•
8. Use: Present	nog barn		Original	Gen'i purpo	se parn	
_						
Description	1011					
9. Date of Constructi	ion_1914	Architect/Buil	der			
10. Building Type: single-family dw] industrial	□ oth	er institutional	О.	aligious
multiple-family		educational	othi			eligious gricultural
commercial [-	-				-
		ne 🗌 brick 📋 board a	nd batten 📋 sh	ingles 🗌 stucco		
other <u>Cla</u>						·
2. Structural System:	wood frame wi	ith interlocking joints [wood frame wit	h light members (balloon frame)	•
		on frame 🔲 steel fram		valls Ureinforce	d concrete	
other						
		fair deteriorated				
14. Integrity: porig	inal site 🔲 move	d—if so, when? dates and architect, if k			(1, 11, 11, 11, 11, 11, 11, 11, 11, 11,	1 1
		dates and architect, if k	nown) and any o	ther notable teatu	res of building	and site:
See reverse	d side.					
15. Related Outbuildi	ngs and Property:	🔲 barn 🕍 other farm	structures 🔲 o	arriage house 🔲	garage 🗌 pri	vy
_						
16. Is the building end	langered? 💥 no	ges—if so, why?				
						
		oen land				commercial [
🗌 industrial 📋 re	sidential 🗌 othe	r				
18. Map	B-121	NORTH	19. Photo	92_ Frame2		
·	R-12 V	(110)	Roll_6	92 Frame2	View	
		HORTHER LA POR	TE _##			
			75			
M V37 5	4 - 4		VBD:	A circle of	70' diam	neter using
#	740		<u>.</u>			ference point
			户	including t	wo adiace	nt connected
$\mathfrak{M}(A)$	1, 1			silos, excl	uding oth	er nearby
) IR	ا F ارتبر ا		buildings.	daring oth	let Healby
n			Č	barrarngs.		
2	Y 1 39		9 ·			
10 17	16	15 14 11 13				
1	• • • • • •		1			
			1.			
20	· fr u	u u u 1 / u	4 . {			
1-1			8.1			
V371	1					
30 - 1	78	20 = 25	8:1			
	· ` \$] [1]			
division of the same of the sa			} -			
The man			Ŋ.			MAY OF
31 -0-15 37	7° . H 33′ H	JT 11 35 11 45				MAY 27

Significance (Indicate source	ces of information for all statements)
20. Architectural significance	
 □ a. Key structure/individually may quali □ b. Contributing structure □ c. Not eligible/intrusion 	fy for the National Register
N/A	
Continuation of 14. Integ	grity.
with wood shingles. Orig	ouble horse stalls facing central silo Conical roof inal cupola. Diameter - 50' silo - clay tile. 12' s removed. May have been sold by J. G. McQuilkin.
21 Historical Significance	True-Round; lowa/King type; Johnston Bros. Theme(s) True-Round; Specialty Contractor; Clay Tile Supplier.
 a. Key structure individually may quali b. Contributing structure c. Not eligible intrusion 	
representative of the Johns characterized as a Johnston tile in the lower story and another common feature of the silo wall generally classification.	t to have been sold by J.G. McQuilkin in his role as a ton Brothers' Clay Works. This barn is specifically Brothers' sub-type by its exterior wall of "small red clay larger tile above" (Soike 1983). The conical roof is he Johnston Brothers' design. The clay tile exterior wall and y this barn as an lowa Agricultural Experiment Station / Matt use of structural clay tile was one of the later improvements ns.
22 Sources (for primary and secondary source	es, give complete facts of publication: author, title, place of publication, date, etc.):
Don Casbon, RR 3, La Porte	City, IA 50651 <pre>ght Angles. Des Moines, Iowa: Iowa State Historical Department,</pre>
Prepared by	Date
•	Telephone
Organization.	
For Office of Historia	c Preservation Use Only
Office Information Sources on this Proportion County Resource File	erty Review and Compliance Project:
☐ Windshield Survey	Other
☐ National Register	Other
☐ Grants-In-Aid:	Other
Determination of Engionity	3. Photo Images
2. Subject Traces	
a	
b	
d	