United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number _____ Page ____

	STING RECORD	
NRIS Reference Number: 90000657	Date Listed: 4	130/90
Model Laundry and Apartments Property Name	<u>Missoula</u> County	MT State
Historic Resources of Missoula, 180 Multiple Name	54-1940, MPS	
This property is listed in the Nat: Places in accordance with the attac subject to the following exceptions	ched nomination docu	
notwithstanding the National Park and the nomination documentation.	• •	-
	• •	-
in the nomination documentation.	Service certificatio	-

This information was confirmed with Pat Bick of the Montana SHPO.

· · · · ·	

United States Department of the Interior National Park Service

National Register of Historic Places Registration Form

This form is for use in nominating or requesting determinations of eligibility for individual properties or districts. See instructions in Guidelines for Completing National Register Forms (National Register Bulletin 16). Complete each item by marking "x" in the appropriate box or by entering the requested information. If an item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, styles, materials, and areas of significance, enter only the categories and subcategories listed in the instructions. For additional space use continuation sheets (Eorm 10-900a). Type all entries

a son ro-socal. Type an entries.			
1. Name of Property			
ristoric name Model Laundry	and Apartments		
	y Apartments		
2. Location			
street & number 131 West Alde	n Ctnoot	n/2	not for publication
sty town Missoula	I_SLIPEL		vicinity
	030 county Missoula	code 063	
sizie Montana code		COUE 003	zip code 59802
3. Classification	· · · · · · · · · · · · · · · · · · ·		
The second se			
Cwnership of Property	Category of Property	Number of Resource	
X_private	X building(s)		oncontributing
=== public-local	district	1	buildings
public-State	site		sites
public-Federal	structure		structures
	object		objects
		1	Total
Name of related multiple property list	ling:	Number of contributi	ing resources previously
Hame of related multiple property list Historical Resources in M	issoula, 1864-1940	listed in the National	
4. State/Federal Agency Certific	cation		
Signature of certifying official State or Federal agency and bureau	MT SHPU		<u>3 - 14 90</u> Date
In my opinion, the property me	eets does not meet the National Reg	ister criteria. 🗌 See cont	inuation sheet.
Signature of commenting or other offic	cial		Date
State or Federal agency and bureau			
5. National Park Service Certifi	cation		
I. ngreby, certify that this property is:			<u></u>
dentered in the National Register.	latick &		11/2.100
See continuation sheet.		naus	
determined eligible for the Nation			•
Register See continuation sheel	t		
determined not eligible for the			
National Register.			
emoved from the National Regist			
· · · · · · · · · · · · · · · · · · ·	far Signature of t	he Keeper	Date of Action

15

MAR 1 91990

NATIONAL REGISTER Same

6. Function or Use		
Historic Functions (enter categories from instructions)	Current Fund Apartment	ctions (enter categories from instructions)
Apartments		
7. Description		ر ۱۹۹۵ - ۲۰۰۰ - ۲۰۰۰ - ۲۰۰۰ - ۲۰۰۰ - ۲۰۰۰ - ۲۰۰۰ - ۲۰۰۰ - ۲۰۰۰ - ۲۰۰۰ - ۲۰۰۰ - ۲۰۰۰ - ۲۰۰۰ - ۲۰۰۰ - ۲۰۰۰ - ۲۰۰۰
Architectural Classification (enter categories from instructions)	Materials (en	ter categories from instructions)
	foundation	concrete
Western Commercial	walls	brick
	roof	asphalt
	other	wood

Describe present and historic physical appearance.

The Model Laundry and Apartments is a rectangular, two-story, stretcher bond brick commercial building with a flat roof and wooden cornice. The windows are wood frame, double-hung eight-over-one and one-over-one units. A projecting two-story, rear stairway was added in 1931. The building is located at the north end of the central business district of Missoula near the area of the old Northern Pacific Railroad tracks and at the west end of a block with adjoining one-story brick commercial buildings, most of which were built during the historic period.

The roofline of the building has an overhanging wooden cornice with brick dentilation under the eaves. A horizontal brick frieze consists of inset ornamentation over two raised stretcher belt courses. Upstairs windows are wood frame, double-hung, one-over-one units with a continuous, rusticated sandstone sill. The first floor consists of two major bays, the east side one consisting of four, wood frame, doublehung, eight-over-one windows with metal-frame storm windows set in a band. It is likely that these windows were put in place during the early 1930s to fill in an open-glazed storefront. The entryway consists of wood frame casement windows including a wood door with full-length window, flanking wood frame, multi-light panels and screened-in fixed transom light. A fixed canopy separates the door from the multi-light transom panel. The canopy is wood frame (1x10) with a molded metal cornice. It is suspended from the side of the building by chains anchored in the front facade.

The side of the building features full-length brick pilasters toward the north and south ends of the building. All windows are wood frame, doublehung, one-over-one units and have sandstone sills. The frieze evident on the front facade runs the length of the west side of the building. The west side of the building has three window wells located in the side walk. The front well only is accessed by a concrete stairway and consists of a concrete wall and wood-framed, double-hung, one-over-one window and what was once a full length door. Both openings have alternating vertical header and stretcher arches. The wells are fenced in by pipe railings. Glass blocks on the sidewalk are located between the wells and next to the top of arches, indicating the location of basement windows that have been filled in.

X See continuation sheet

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Section number _____ Page 1 Model Laundry and Apartments

The rear of the building has an exterior, three-story, square brick chimney that extends above the roof line of the building. The rear of the building features three-tiered header relief arches over wood frame, double-hung, one-over-one windows, which flank a central wooden door. A two-story porch with a "Z"-shaped, wooden, two-story stairway enclosed by stucco walls projects from the rear of the building. An outside concrete stairway leads to the rear basement entryway (doors are oneover-two upper pane and one-over-two lower wood panels) with a threetiered header relief arch above the doors.

This historic commercial building has good integrity of design, materials, workmanship, and association. It has experienced some loss of integrity with the addition of the rear, exterior stuccoed porch, which was added by 1931. First floor integrity of the building is unusually good for a commercial building of this age.

8. Statement of Significance		
Certifying official has considered the significance of this prop	perty in relation to other properties:	
Applicable National Register Criteria A B XC	D	
Criteria Considerations (Exceptions)		
Areas of Significance (enter categories from instructions) Architecture	Period of Significance 1909-1940 	ates
	Cultural Affiliation n/a	
Significant Person n/a	Architect/Builder Oke Bakke (attributed), 1915 remodelir	ng

State significance of property, and justify criteria, criteria considerations, and areas and periods of significance noted above.

The Model Laundry and Apartments is eligible for listing in the National Register of Historic Places under criterion C as it is an excellent example of early twentieth century commercial architecture with its rectilinear commercial design, ornamental frieze work, and regularly spaced fenestration. The large rear chimney stands as evidence of the historic use of the building as a laundry. Basement entryways, window well and glass blocks, over what probably were vaults under the sidewalks, also remain from the time when the laundry occupied the building.

The building was constructed ca. 1909, when the property was owned by either Ole and Paul Bakke or James H. T. Ryman. Subsequent owners included W. E. Wheeler (1912), Ole Bakke (1922); Caroline Dixon, W. C. Murphy, and W. M. Allen, Trustees (1934), and Chris Lemke (1938). The building originally was the Model Laundry, with Joseph Hagen, President and General Manager. In 1915, Hagen moved his business to his new building at 111 East Spruce, and the first floor space of this building was likely converted into apartments. Local architect, Ole Bakke, lived at this address in 1915 and may have been responsible for overseeing the renovation of the laundry space. The primary entrance and first floor window band of the facade were probably installed at this time. These alterations are judged to add to the significance of the building. The building became known as the Dorothy Apartments by 1929. Constructed during the second major building boom following the completion of the railroad to Missoula, this was one of several commercial, multi-family buildings built during that period in the central business district.

9. Major Bibliographical References

McDonald, James, and Gary Williams, <u>Missoula Historical Resource Survey</u>. Missoula: Porky Press, 1980.

	See continuation sheet
Previous documentation on file (NPS):	
preliminary determination of individual listing (36 CFR 67)	Primary location of additional data:
has been requested	X State historic preservation office
previously listed in the National Register	Other State agency
previously determined eligible by the National Register	E Federal agency
designated a National Historic Landmark	Local government
recorded by Historic American Buildings	University
] Other
recorded by Historic American Engineering	Specify repository: Second Sec
Record #	
10. Geographical Data	<u> </u>
Acreage of property <u>less than one acre</u>	
Acceage of property	
UTM References	
<u>A 1 2 2 7 1 9 7 0 5 1 9 5 9 3 0</u>	B L I I I I I I I I I I I I I I I I I I
Zone Easting Northing	Zone Easting Northing
	See continuation sheet
Verbal Boundary Description	
C.P. Higgins Addition, Block 10, W 10' of lot	10, all of lot 11.
	See continuation sheet
Boundary Justification	
The boundary includes the city lots upon which	n the historic building was erected.
	See continuation sheet
11. Form Prepared By	· · · · · · · · · · · · · · · · · · ·
	coric Preservation Officer
organization <u>City</u> of Missoula	date August 1989
street & number 201 West Spruce St.	telephone 406/721-4700 ext 250
city or town Missoula	state Montana zip code 59802