



91-19-18

Woodbury Town Hall

Woodbury, Vermont (Washington County)

Credit: Elizabeth Pritchett

Date: March, 1991

Negative Filed at the Vermont Division  
for Historic Preservation

View looking Northwest  
(Woodbury Center)

Photograph #1



WOODBURY TOWN HALL

91-19-21

Woodbury Town Hall

Woodbury, Vermont (Washington County)

Credit: Elizabeth Pritchett

March, 1991

Negative filed at Vermont Division  
for Historic Preservation

View looking Southwest (front/east facade and north  
Photograph #2. facade)





Woodbury Town Hall

Woodbury, Vermont (Washington County)

Credit: Elizabeth Pritchett

March, 1991

Negative filed at the Vermont

Division for Historic Preservation

View looking Northeast

(rear/west facade and south facade)

Photograph # 3.



**OFFICIAL  
POLLING  
PLACE**



Woodbury Town Hall

Woodbury, Vermont (Washington County) 91-19-5

Credit: Elizabeth Pritchett

March, 1991

Negative filed at the Vermont Division  
for Historic Preservation

View looking west (exterior detail of entrance door)

Photograph # 4.





Woodbury Town Hall  
Woodbury, Vermont (Washington County)

91-19-11

Credit: Elizabeth Pritchett

March, 1991

Negative filed at Vermont Division for  
Historic Preservation.

View looking west (interior detail of hall and stage)

Photograph # 5.