



#1 and 5

Brook Farm

Windsor Co., VT

Credit: Thomas D. Visser

April 1993

Negative at VT Div. for Hist. Pres.

View of Bates Mansion + Cow Barn,
looking W.

93-52-10

Photo 1



1

Brook Farm

Windsor Co., VT

Thomas D. Visser

April 1993

Negative: VT Div. for Historic Preservation

View looking N of Bates Mansion

93-52-8

Photo 2



1

Brook Farm

Windsor Co, VT

Thomas D. Visser

August 1986

Negative: VT Div for Historic Preservation

View looking SE of Bates Mansion

93-51-3

Photo 3



1

Brook Farm
Windsor Co, VT
Thomas D. Visser
March 1987

Negative: VT Div for Historic Preservation
View looking N, main hall of Bates Mansion

Photo 4

93-52-1



2

Brook Farm

Windsor Co, VT

Thomas D. Visser

August 1986

Negative: VT Div for Historic Preservation

View looking N to horse stable

93-51-2

Photo 5



#s 2, 3

Brook Farm

Windsor Co, VT

Thomas D. Visser


Aug. 1986

Negative: VT Div. for Historic Preservation

looking S, at horse stable (#2) and Equipment Shed + Work Shop (#3)

Photo 6

93-51-7



2

Brook Farm

Windsor Co, VT

Thomas D. Visser

August 1986

Negative: VT Div. for Historic Preservation

Looking SE, inside Horse Stable

93-51-24A

photo 7



#3

Brook Farm

Windsor Co, VT

Thomas D. Visser

August 1986

Negative: VT Div for Historic Preservation

View looking NE

93-51-5

Photo 8



4

Brook Farm

Windsor Co, VT

Thomas D. Visser

Negative - VT Div. for Historic Preservation

April 1993

Looking NW, old barn site

photo 9

93-52-0



Brook Farm

Windsor Co, VT

Thomas D. Visser

Negative: VT Div. for Historic Preservation

August 1986

Looking SE, old barn (now gone)

93-51-23

Photo 10



Brook Farm
Windsor Co, VT
Thomas D. Visser
August 1986

Negative: VT Div. for Historic Preservation
Looking S, interior old barn (now gone)

93-51-22

Photo 11



5

Brook Farm
Windsor Co, VT

Thomas D. Visser

Nov. 1986

Negative: VT Division for Historic Preservation
Looking N, Cow barn

Photo 12

93-52-12



5

Brook Farm

Windsor Co, Vermont

Thomas D. Visser

Nov. 1986

Negative: VT Div. for Historic Preservation

Looking N, stanchions Cow Barn

93-52-14

Photo 13



s 5, 6

Brook Farm

Windsor Co, VT

Thomas D. Visser

Nov. 1986

Negative: VT Div. for Historic Preservation

Looking SE, Cow Barn + Granary

Photo 14

93-52-14



6

Brook Farm

Windsor Co, VT

Thomas D. Visser

Dec. 1986

Negative: VT Div. for Historic Preservation

Looking W, Granary

93-53-12

photo 15



#. 6

Brook Farm

Windsor Co, VT

Thomas D. Visser

Dec. 1986

Negative: VT Div. for Historic Preservation

Looking E, inside Granary

Photo 16

93-52.4



#s 10, 9, 7

Brook Farm
Windsor Co., VT
Thomas D. Visser


August 1986

Negative: VT Div. for Historic Preservation

Looking W, creamery, farm manager's house, piggery

photo 17

93-51-6



58, 7, 5

Brook Farm
Windsor Co, VT
Thomas D. Visser

August 1986

Negative: VT Div. for Historic Preservation

looking E, chicken coop, piggery, cow barn

Photo 18

93-51-9



#10, 9

Brook Farm

Windsor Co. VT

Thomas D. Visser

Nov. 1986

Negative: VT Div. for Historic Preservation

Looking W, creamery + farm manager's house

Photo 19

93-52-20



9

Brook Farm
Windsor Co, VT
Thomas D. Visser

Aug. 1986

Negative: VT Div. for Historic Preservation

looking SE, dining room + entry hall of
farm manager's house

Photo 20

93-51-18



#10

Brook Farm

Windsor Co, VT

Thomas D. Visser

August 1986

Negative: VT Div. for Historic Preservation

looking NW, inside creamery

photo 21

93-51-17



11

Brook Farm

Windsor Co, VT

Thomas D. Visser

Nov. 1986

Negative: VT Div. for Historic Preservation

Looking E, sugar house ruins

photo 22

93-52-16



12

Brook Farm

Windsor Co, VT

Thomas D. Visser

December 1986

Negative: VT Div. for Historic Preservation

looking SW, garden house + greenhouse

photo 23

93-52-6



Brook Farm

Windsor Co, VT

Thomas D. Visser

1986 of c. 1900 view

Negative: VT Div. for Historic Preservation

Looking W of Brook Farm

93-52-20

Photo 24