

MAR 25 1977

H. B. Littel November 1973 Public Information Frankfort, Kentucky

AUG 1 2 1977

Photo 1. Photo taken from the northwest. The brick outbuilding is in the background on the right.



Mary Cronan OppelAUG 12 1977 November 1976 Kentucky Heritage Commission Frankfort, Kentucky

Photo 2. Photo taken from the northwest showing the facade of the house.




H. B. Littel November 1973 Public Information Frankfort, Kentucky

MAR 25 1977

Photo 3. Photo taken from the east.

AUG 1 2 1977



Mary Cronan Oppel November 1976

Kentucky Heritage Commission Frankfort, Kentucky

Photo 4. Photo taken from the north showing the brick outbuilding.

AUG 12 1977



Mary Cronan Oppel November 1976 AUG 12 1977 Kentucky Heritage Commission Frankfort, Kentucky

Photo 5. Photo taken from the northwest showing the entrance to the dry cellar which is believed to date from 1790.



MAR 25 1977

Mary Cronan Oppel November 1976 AUG 1 2 19// Kentucky Heritage Commission Frankfort, Kentucky

Photo 6. Photo taken from the southwest showing the south entrance to the stone outbuilding.



Mary Cronan Oppel November 1976 Kentucky Heritage Commission Frankfort, Kentucky

Photo 7.% Interior photo showing the detail of the stringers of the staircase in the central hall.

AUG 1 2 1977



Mary Cronan Oppel
November 1976
Kentucky Heritage Commission
Frankfort, Kentucky AUG 1 2 1977

Photo 8 Interior photo showing the full landing of the staircase in the central hall. Notice the woodwork around door.