



Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 1 -- from the west.  
James Sexton      May 5, 2005



Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 2 -- from the northwest.  
James Sexton      February 3, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 3 -- western wall south of the main entry from the northwest.  
James Sexton February 3, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 4 - The southern part of the Sunday school room wall from the south.  
James Sexton February 3, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 5 - The southern entry from the west.  
James Sexton May 5, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 6 - The open porch of the tower from the southwest.  
James Sexton May 5, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 7 - The foliate capitals of the grouped engaged columns to the north of the secondary entrance from the southwest.

James Sexton February 3, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 8 - The secondary entrance from the west.  
James Sexton February 3, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 9 - The roof of the secondary entrance from the west.  
James Sexton February 3, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 10 - The main entry from the west.  
James Sexton February 3, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 11 - The secondary entrance from the west.  
James Sexton February 3, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 12 - The ceiling at the southwestern corner of the sanctuary from the northeast.  
James Sexton February 4, 2006





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 13 - Graining on the northern cast iron pilaster in the western wall from  
the southeast.

James Sexton February 4, 2006





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 14 - The capital of the southern pilaster in the western wall from the west.  
James Sexton May 5, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 15 - The chancel from the west.  
James Sexton May 5, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 16 - The partitioned room at the northeastern corner of the auditorium  
from the southwest.

James Sexton February 3, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 17 - The doors separating the sanctuary and the Sunday school room from the east.  
James Sexton February 4, 2006





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 18 - The sanctuary with the doors to the Sunday school room open from the east.  
James Sexton May 5, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 19 - The stained glass windows in the northern wall of the sanctuary from the southeast.  
James Sexton February 4, 2006





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 20 - A panoramic photomontage of the sanctuary from the east.  
James Sexton May 5, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 21 - The seating in the auditorium from the north.  
James Sexton February 3, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 22 - One of the lanterns in the sanctuary from the east.  
James Sexton February 3, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 23 - The southern stairs up to the balcony from the northwest.  
James Sexton February 3, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 24 - The Sunday school room from the east.  
James Sexton May 5, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 25 - The elaborate oak trim in the eastern office from the northwest.  
James Sexton February 3, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 26 - The stairs to the second floor from the northeast.  
James Sexton February 3, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 27 - The gas-electric sconce on the landing between the first and second floors from the northeast.  
James Sexton February 3, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 28 - The stairs to the second floor from the northwest.  
James Sexton February 3, 2005





Trinity Methodist Episcopal Church  
Hartford County, Connecticut

Photo 29 - The plaster cornice in the western room on the second floor from the south.

James Sexton February 3, 2005