

Photo No. 1
By: George R. Adams, AASLH
Negative at: HSS, NPS
Date: February 1977

View: Buildings 18, 19, 20, 21. From south, showing west facades.



By: George R. Adams, AASLH Negative at: HSS, NPS Date: February 1977

Photo No. 2

View: Buildings 53 and 52. From southwest, showing west ends and south facades.



Photo No. 3

By: George R. Adams, AASLH Negative at: HSS, NPS Date: February 1977

View: Buildings 55 and 54. South (front) facades.



Photo No. 4
By: George R. Adams, AASLH
Negative at: HSS, NPS
Date: February 1977

View: Buildings 39, 37, 64, and 52. From north, showing north end of number 39 and east facades of all.



Photo No. 5
By: George R. Adams, AASLH
Negative at: HSS, NPS
Date: February 1977

View: Buildings 24 to 26A and 21. From northeast showing north ends of numbers 24 to 26A and east side of number 21.




Photo No. 6
By: George R. Adams, AASLH
Negative at: HSS, NPS
Date: February 1977

View: From east, showing smokestack No. 1 and portions of north facades of buildings 62 (center) and 53 (behind stack).



Photo No. 7
By: George R. Adams, AASLH
Negative at: HSS, NPS
Date: February 1977

View: From southwest, showing west and south facades of buildings 30 and 31. Stack No. 2 is in background.



Photo No. 8
By: George R. Adams, AASLH
Negative at: HSS, NPS
Date: February 1977

View: Building 57. Interior. Fourth floor.