



NAME: Ranger Station (176)--Swiftcurrent
Ranger Station Historic District
LOCATION: Glacier National Park, MT
PHOTOGRAPHER: Lance Williams *mla*
DATE OF PHOTOGRAPH: August 1975
LOCATION OF NEGATIVE: Rocky Mountain
Regional Office, National Park Service,
Denver, CO
PHOTO NUMBER: 1



NAME: Ranger Station (176)--Swiftcurrent
Ranger Station Historic District
LOCATION: Glacier National Park, MT
PHOTOGRAPHER: Lance Williams
DATE OF PHOTOGRAPH: August 1975
LOCATION OF NEGATIVE: Rocky Mountain
Regional Office, National Park Service,
Denver, CO
PHOTO NUMBER: 2



NAME: Cabin (177)-- Swiftcurrent Ranger
Station Historic District *NRA*
LOCATION: Glacier National Park, MT
PHOTOGRAPHER: Lance Williams
DATE OF PHOTOGRAPH: August 1975
LOCATION OF NEGATIVE: Rocky Mountain
Regional Office, National Park Service,
Denver, CO
PHOTO NUMBER: 3



NAME: Cabin (178)--Swiftcurrent Ranger
Station Historic District
LOCATION: Glacier National Park, MT *NRB*
PHOTOGRAPHER: Lance Williams
DATE OF PHOTOGRAPH: August 1975
LOCATION OF NEGATIVE: Rocky Mountain
Regional Office, National Park Service,
Denver, CO
PHOTO NUMBER: 4



NAME: Cabin (179)--Swiftcurrent Ranger
Station Historic District
LOCATION: Glacier National Park, MT ^{NRA}
PHOTOGRAPHER: Lance Williams
DATE OF PHOTOGRAPH: August 1975
LOCATION OF NEGATIVE: Rocky Mountain
Regional Office, National Park Service,
Denver, CO
PHOTO NUMBER: 5



NAME: Cabin (180) Swiftcurrent Ranger
Station Historic District
LOCATION: Glacier National Park, MT ^{MRA}
PHOTOGRAPHER: Lance Williams
DATE OF PHOTOGRAPH: August 1975
LOCATION OF NEGATIVE: Rocky Mountain
Regional Office, National Park Service,
Denver, CO
PHOTO NUMBER: 6a



NAME: Cabin (181)--Swiftcurrent Ranger
Station Historic District
LOCATION: Glacier National Park, MT
PHOTOGRAPHER: Lance Williams
DATE OF PHOTOGRAPH: August 1975
LOCATION OF NEGATIVE: Rocky Mountain
Regional Office, National Park Service,
Denver, CO
PHOTO NUMBER: 7



NAME: Cabin (182)--Swiftcurrent Ranger
Station Historic District *NRA*
LOCATION: Glacier National Park, MT
PHOTOGRAPHER: Lance Williams
DATE OF PHOTOGRAPH: August 1975
LOCATION OF NEGATIVE: Rocky Mountain
Regional Office, National Park Service,
Denver, CO
PHOTO NUMBER: 7



NAME: Woodshed (483)--Swiftcurrent Ranger
Station Historic District
LOCATION: Glacier National Park, MT
PHOTOGRAPHER: Lance Williams
DATE OF PHOTOGRAPH: August 1975
LOCATION OF NEGATIVE: Rocky Mountain
Regional Office, National Park Service,
Denver, CO
PHOTO NUMBER: 8



NAME: Woodshed (484)--Swiftcurrent Ranger
Station Historic District

LOCATION: Glacier National Park, MT

PHOTOGRAPHER: lance Williams

DATE OF PHOTOGRAPH: August 1975

LOCATION OF NEGATIVE: Rocky Mountain
Regional Office, National Park Service,
Denver, CO

PHOTO NUMBER: 9



NAME: Woodshed (485)--Swiftcurrent Ranger
Station Historic District *NRA*
LOCATION: Glacier National Park, MT
PHOTOGRAPHER: Lance Williams
DATE OF PHOTOGRAPH: August 1975
LOCATION OF NEGATIVE: Rocky Mountain
Regional Office, National Park Service
Denver, CO
PHOTO NUMBER: 10



NAME: Garage/Trails Office (482)--
Swiftcurrent Ranger Station Historic
District

LOCATION: Glacier National Park, MT

PHOTOGRAPHER: Lance Williams

DATE OF PHOTOGRAPH: August 1975

LOCATION OF NEGATIVE: Rocky Mountain
Regional Office, National Park Service,
Denver, CO

PHOTO NUMBER: 11



NAME: Garage/Trails Office (482)--
Swiftcurrent Ranger Station Historic
District

LOCATION: Glacier National Park, MT

PHOTOGRAPHER: Lance Williams

DATE OF PHOTOGRAPH: August 1975

LOCATION OF NEGATIVE: Rocky Mountain
Regional Office, National Park Service,
Denver, CO

PHOTO NUMBER: 12



NAME: Fire cache (488)--Swiftcurrent
Ranger Station Historic District

LOCATION: Glacier National Park, MT

PHOTOGRAPHER: Lance Williams *mt*

DATE OF PHOTOGRAPH: August 1975

LOCATION OF NEGATIVE: Rocky Mountain
Regional Office, National Park Service,
Denver, CO

PHOTO NUMBER: 13



Swift Current Ranger Station HS 170

Interior

Entry / Front Office

Swiftcurrent RSHD

Glacier Co., MT, Glacier NP

Photo #1



JANUARY 1961

1	2	3	4	5	6	7
8	9	10	11	12	13	14
15	16	17	18	19	20	21
22	23	24	25	26	27	28
29	30	31				

FEBRUARY 1961

1	2	3	4	5	6	7
8	9	10	11	12	13	14
15	16	17	18	19	20	21
22	23	24	25	26	27	28
29						

MARCH 1961

1	2	3	4	5	6	7
8	9	10	11	12	13	14
15	16	17	18	19	20	21
22	23	24	25	26	27	28
29	30	31				

APRIL 1961

1	2	3	4	5	6	7
8	9	10	11	12	13	14
15	16	17	18	19	20	21
22	23	24	25	26	27	28
29	30					

A large bulletin board on the right wall is densely packed with various documents. At the top, there are several newspaper clippings and photographs. Below these, there are numerous sheets of paper, some of which appear to be maps or technical drawings. The board is organized into sections, with papers pinned in a somewhat haphazard but systematic manner. Some papers have titles or headings, though they are difficult to read due to the image quality.

A dark wooden desk in the foreground is cluttered with various items. On the left side of the desk, there are several sheets of paper and a small object. In the center, a large, irregularly shaped rock specimen is prominently displayed. To the right of the rock, there is a dark, rectangular box or container. The desk surface is dark, and the items on it are scattered, suggesting an active workspace.

A small, light-colored table stands against the wall, partially obscured by a dark wooden chair. On the table, there is a large, dark, rectangular object, possibly a bag or a container. The chair is a simple wooden chair with a curved back and a seat. The table is positioned in the corner of the room, near the bulletin board.

A dark wooden desk is located on the left side of the room, near a window. A dark wooden chair is tucked under the desk. The desk is mostly empty, with a few small items on it. The window has a floral patterned valance and a dark frame. The wall behind the desk is covered in white paneling.

Swiftcurrent Ranger Station
AS 176

Interior

SE office

Swiftcurrent RSHD

Glacier Co., MT, Glacier NP

Photo #2



Surfcurrent Ranger Station
HS176

Interior

Seasonal Housing

Surfcurrent RS #10

Glacier Co, MT, Glacier NP

Photo #3



Cabin HS 177

Interior

Surfcurrent RS HD

Glacier Co. MT, Glacier NP

Photo # 4



Cabin HS 177

Interior

Door detail

Sniffrurrent RSHD

Glacier Co., MT, Glacier NP

Photo #5



Cabin 14577

Interior

Kitchen

Swiftcurrent RS HD


Glacier Co, MT, Glacier NP

Photo # 6



Garage/Trails Office
H5 482

Interior
Sunflower 28HD
Glacier Co., MT, Glacier NP
Photo #7



Garage/Trails Office

HS482

Interior

Surfturrent RSHD

Glacier Co. MT, Glacier NP

Photo #8



Woodshed HS 483
Interior
Laundry
Surft current RS HD
Glacier Co. UT, Glacier NP
Photo #9

**SLEEPING
BAGS**

LIFE VESTS



Fire Cache HS 488

Interior

Swiftcurrent RS HD

Glacier Co. MT, Glacier NP

Photo #10

BLANKETS

TENT

BACK PACKS



Fire Cache Its 488

Interior

Swiftcurrent BSHD

Glacier Co, MT, Glacier NP

Photo #11