



82-A-239

Royalton Mill Complex

Royalton, Vermont

Credit: John P. Dumville

Date: July 1982

Negative filed at Vermont Division for
Historic Preservation

Description: (R) Millhouse (after restoration)
and (L) Barn, View northwest

Photo #1



82A.254



Royalton Mill Complex
Royalton, Vermont
Credit: John P. Dumville
Date: November 1981
Negative filed at Vermont Division for
Historic Preservation
Description: Millhouse (prior to restoration)
View northwest
Photo #2



Royalton Mill Complex
Royalton, Vermont
Credit: Margaret DeLaittre

Date: December 1981

Negative filed at Vermont Division for
Historic Preservation

Description: Tenant House, View north
Photo #3

81-A-375



81-A-375

Royalton Mill Complex

Royalton, Vermont

Credit: Margaret DeLaittre

Date: December 1981

Negative filed at Vermont Division for
Historic Preservation

Description: Front gable end of Barn, View west
Photo #4



81-A-375

Royalton Mill Complex
Royalton, Vermont
Credit: Margaret DeLaittre
Date: December 1981
Negative filed at Vermont Division for
Historic Preservation
Description: South wall of Barn, View north
Photo #5