



GOLD POINT MILL

IDAHO COUNTY, IDAHO

PHOTOGRAPHER: KATHY MCKAY

MAY 22, 1998

ORIGINAL NEGATIVES ON FILE AT IDAHO SHPO

GOLD POINT MILL - LOOKING NORTH

PHOTO # 1 (OF 6)



GOLD POINT MILL

IDAHO COUNTY, IDAHO

PHOTOGRAPHER: KATHY MCKAY

MAY 22, 1998

ORIGINAL NEGATIVES ON FILE AT IDAHO-SHPO

TOP OF MILL-HOPPER FOR COARSE ORE BIN,

LOOKING SOUTHEAST

PHOTO # 2 (OF 6)



GOLD POINT MILL

IDAHO COUNTY, IDAHO

PHOTOGRAPHER: KATHY MCKAY

MAY 22, 1998

ORIGINAL NEGATIVES ON FILE AT IDAHO SHPO
(COARSE ORE BIN (LEFT) AND JAWBREAKER
LEVEL (RIGHT) - LOOKING NORTH

PHOTO #3 (OF 6)



GOLD POINT MILL

IDAHO COUNTY, IDAHO

PHOTOGRAPHER: KATHY MCKAY

MAY 22, 1998

ORIGINAL NEGATIVES ON FILE AT IDAHO-SHPO

SHAKER TABLE LEVEL (BOTTOM) OF MILL, LOOKING
NORTHWEST

PHOTO #4 (OF 6)



GOLD POINT MILL

IDAHO COUNTY, IDAHO


PHOTOGRAPHER; KATHY MCKAY

MAY 22, 1998

ORIGINAL NEGATIVES ON FILE AT IDAHO SHPO

CHUTE LEADING FROM COARSE ORE BIN (LEFT) TO
JAW BREAKER - LOOKING NORTHWEST

PHOTO # 5 (OF 6)



GOLD POINT MILL

IDAHO COUNTY, IDAHO

PHOTOGRAPHER: KATHY MCKAY

MAY 22, 1998

ORIGINAL NEGATIVES ON FILE AT IDAHO SHPO

LOWER END OF RAKE CLASSIFIER - LOOKING
SOUTHEAST

PHOTO # 6 (OF 6)