



CHRISTMAS
CENTER GARDEN

WILLIAM GEDAMKE RESIDENCE
1304 EAST POWELL BLVD
GRESHAM
MULTNOMAH CTY.
OREGON

By CHRISTINA CHRISTENSEN
1988

NEGATIVE AVAILABLE AT
ABOVE ADDRESS FROM
PHOTOGRAPHER

VIEW IS TO SOUTH



Gedamke House as viewed from the North-west
corner of property.

Gresham, Multnomah Co.

GEDAMKE, WILLIAM, HOUSE

1304 EAST POWELL BLVD.

GRESHAM, MULTNOMAH COUNTY, OREGON

CHRISTINA CHRISTIAN SAN IPIRO, 1988

NEGATIVE AT ABOVE ADDRESS

SOUTH AND WEST ELEVATIONS

2 OF 11



Gedamke House upper story fishscales &
and decorative window.

Gresham, Multnomah Co.

GEDAMKE, WILLIAM, HOUSE
1304 EAST POWELL BLVD.
GRESHAM, MULTNOMAH COUNTY, OREGON

CHRISTINA CHRISTANSEN PHOTO, 1988
NEGATIVE AT ABOVE ADDRESS

DETAIL, WEST GABLE

3 OF 11



Sedauke House Chimney

Gresham, Multnomah Co.

GRANHAM, WILLIAM, HOUSE

1304 EAST POWELL BLVD.

GRANHAM, MULTNOMAH CO., OREGON

CHRISTINA CHRISTANSEN PHOTO, 1988

NEGATIVE AT ABOVE ADDRESS

CLOSE VIEW OF CHIMNEY

4 OF 11



Gedauke House Graham, Multnomah Co.

detail front jetty

GRANDMOTHER, WILLIAM, HOUSE

1304 EAST POWELL BLVD.


GRAHAM, MULTNOMAH COUNTY, OREGON

CHRISTINA CHRISTIANSON PHOTO, 1988

NEGATIVE AT ABOVE ADDRESS

DETAIL OF FRONT WINDOW BAY JETTY

5 OF 11



EMPLOYEES

ONLY



Gedamke House Stairway Banister
Lower floor

Gresham, Multnomah Co.

GEDAMKE, WILLIAM, HOUSE -

1304 EAST POWELL BLVD.

GRESHAM, MULTNOMAH CO., OREGON

CHRISTINA CHRISTENSEN PHOTO, 1988

NEGATIVE AT ABOVE ADDRESS

STAIRCASE, PANTRY STAIRWELL

6 OF 11



Gedauke House Upper Floor
Stairway Banister

Gresham, Multnomah Co.

GEDAUKE, WILLIAM, HOUSE

1304 EAST POWELL BLVD.

GRESHAM, MULTNOMAH CO., OREGON

CHRISTINA CHRISTANSON PHOTO, 1988

NEGATIVE AT ABOVE ADDRESS

STAIRCASE LANDING

7 OF 11



gedanke House Upper floor window above
stairs.

Gresham, Multnomah Co.

CHRISTINA, WILLIAM, HOUSE -

1304 EAST POWELL BLVD.

GRESHAM, MULTNOMAH COUNTY, OREGON

CHRISTINA CHRISTANSON PHOTO, 1988

NEGATIVE AT ABOVE ADDRESS

STAIR LANDING WINDOW

8 OF 11



Gedamke House Front Bedroom (now office) East
Octagonal window

Gresham, Multnomah Co.

GEDAMKE, WILLIAM, HOUSE
1304 EAST POWELL BLVD.

GRESHAM, MULTNOMAH COUNTY, OREGON

CHRISTINA CHRISTANSON PIKOTO, 1988

NEGATIVE AT ABOVE ADDRESS

FRONT
BED CHAMBER WINDOW

9 OF 11



Gedanke House Arch

Gresham, Multnomah Co.

Notice moulding and corner blocks

GEDANKE, WILLIAM, HOUSE

1304 EAST DONALD BLVD.

GRESHAM, MULTNOMAH COUNTY, OREGON

CHRISTINA CHRISTANSEN PHOTO, 1988

NEGATIVE AT ABOVE ADDRESS

TYPICAL DOORWAY TRIM AND

PICTURE MOLDING

10 OF 11



Gedamke House one of
many original doors.

Gresham, Multnomah Co.

GEDAMKE, WILLIAM, House
1304 EAST DONALL BLVD.

GRESHAM, MULTNOMAH CO., OREGON

CHRISTINA EHNISTANSON PHOTO,
1958
NEGATIVE AT ABOVE ADDRESS

TYPICAL INTERIOR 4-PANEL DOOR