

KENTUCKY HISTORIC RESOURCES INVENTORY

Site No. Sc 270

1. Historic Name(s) <u>Charles Whitaker house</u>		22. ADD/County <u>Bluegrass Scott</u> 105	
Original Owner <u>Charles Whitaker</u>		23. U.S.G.S. Quadrant (15'/75') <u>Georgetown v. 5</u> G.I.S. Mod. 	
2. Present Name <u>Charles Whitaker house</u>		24. UTM Reference 16 718720 4235140	
3. Location <u>8/10 mi off State Rd Oxford Road; gate 2 mi N of 460</u>		Zone Easting Northing	
4. Owner's Name <u>Mrs. Warren Nash</u>		25. Coordinate Accuracy 	
5. Owner's Address <u>Main Street, Georgetown 40324</u>		26. Prehistoric Site Object Historic Site Structure Building <input checked="" type="checkbox"/> Other	
6. Open to Public Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	7. Visible from road Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	8. Ownership <input checked="" type="checkbox"/> Private <input type="checkbox"/> Local <input type="checkbox"/> State <input type="checkbox"/> Federal	
9. Local Contact/Organization		27. National Register District Name: 	
10. Site Plan with North Arrow <u>see attached boundary form</u>		28. Significance Evaluation 	
11. Architect		29. Status Date	
12. Builder		National Landmark 	
13. Date <u>late 18th C</u> A. <input checked="" type="checkbox"/> B. <input type="checkbox"/>		National Register 	
14. Style A. <u>Federal</u> <input checked="" type="checkbox"/> B. <input type="checkbox"/>		Landmark Certificate 	
15. Original Use <u>residence</u> <input checked="" type="checkbox"/> A. <input type="checkbox"/> B. <input type="checkbox"/>		Kentucky Survey <input checked="" type="checkbox"/>	
16. Present use <u>vacant</u>		Local Landmark 	
17. Condition <u>fair</u> <input checked="" type="checkbox"/> C. <input type="checkbox"/>		HABS/HAER 	
18. Description <u>5 bay 2 story central passage dry stone house w 1 story 1 room wing on E end. Very good stonework; large interior chimneys each end and on wing. shallow shoulders; 9 stone poussoirs w steps including cellar</u> (Continue on Back) (over)		30. Historic Theme Primary <u>architecture</u> C Secondary <u>settlement</u> K Other 	
No. Stories <u>2</u> <input checked="" type="checkbox"/> C. <input type="checkbox"/>		31. Endangered <u>by neglect</u> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Single Pile <input checked="" type="checkbox"/> NA <input type="checkbox"/>		32. Preservation Project Status 	
Double Pile <input type="checkbox"/>		Actual Cost in \$1,000s 	
Floor Plan <u>center passage</u> <input checked="" type="checkbox"/> D. <input type="checkbox"/>		33. ATTACH PHOTO <u>in attached envelope</u>	
Structural Fabric <u>stone</u> A. <input checked="" type="checkbox"/> B. <input type="checkbox"/>		Roll No. _____	
Decorative Fabric <u>no stairs</u> A. <input checked="" type="checkbox"/> B. <input type="checkbox"/>		Picture No. _____	
Roof Form <u>gable</u>		Direction _____	
19. History <u>Built by Charles Whitaker on land grant of Abraham Whitaker; similar to house built by his brother on other side of the creek; sold to Joseph Herndon. Has been in family of present owner since purchased by John Corrick in 1862.</u>		34. Prepared by: <u>C.M. Worley</u>	
20. Significance <u>Excellent example of large central passage dry stone house. not modernized.</u>		35. Organization _____	
21. Source of Information <u>18. inspection</u> <u>19. Deans. Hist Scott Co. 71-2</u>		36. Date <u>1982</u>	
		37. Revision Dates _____ 38. Staff Review _____	

18. cont.:

windows in each bay. Pegged frames, arched trim, roused sills; horizontal ^{diagonal} bars on cellar windows, small attic windows beside chimneys.

Interior has open stairway w closed stringer, panelled banister, square banisters (photo 4) & newell; fine ~~att~~ mantel from 1st floor in attic, has reeded pilasters, panelled frieze (photo 8) and dentilled trim; other mantels are shelf (photos 6, 7) type, one w panelled frieze also; panelled doors - 8 panel double doors on front entrance; panelled jambs; enclosed corner stair to attic. Rafters are unshewn logs, pegged at ridge, no collar beams. Better door to cellar w. end, pegged frame, large strap hinges.

Front porch gone; porch in front of kitchen wing enclosed w concrete block and frame; frame ill added on center rear of house.

Located away from road, on Miller's Run. Very similar to Sc 4 (NR.).

19. cont.:

Other owners: Shannon, Nash.

VERBAL BOUNDARY DESCRIPTION & JUSTIFICATION

Beginning at A at the SW fence corner of the yard, thence N 100 ft to B, E 200 ft to C, leaving fence at right angle, 100 ft S to D, and with fence 200 ft W to the beginning containing the stone house, about 1 acre. (Does not show; see sketch) about orientation. C. W.

SKETCH MAP OF SITE SHOWING BOUNDARIES AND KEY BUILDINGS AND FEATURES WITH NORTH ARROW.

