



Walnut Canyon Dam JAN 8 1979 Arizona Looking east COCONINO COUNTY Dark area in lower left corner of dam is portion damaged by dynamite Date: 1977 Negative at ASPB

JAN 2 9 1979



- Walnut Canyon Dam Arizona
- Looking east Showing depth of canyon Date: 1977
- Negative at ASPB










Walnut Canyon Dam Arizona Looking southeast



#3

- Showing dam before dynamite damage Date: 1935
- Negative at Walnut Canyon National Monument





Walnut Canyon Dam JAN 8 1979 Arizona COCONINO CO. Looking north Showing construction detail & sediment accumulation on masonry Date: 1935 Negative at Walnut Canyon National Monument

#Δ

JAN 2 9 1979




Malnut Canyon Dam Arizona Looking southwest Showing face of dam Date: 1968 Negative: Dave Rees


JAN 8 1979 COCONIONOCO.

JAN 2 9 1979





Walnut Canyon Dam Arizona



Looking southeast UUUN Showing reservoir side of dam Date: 1968 Negative: Dave Rees

JAN 29 1979

