
### National Register of Historic Places Registration Form



NATIONAL REGISTER

This form is for use in nominating or requesting determinations of eligibility for individual properties or districts. See instructions in *Guidelines* for Completing National Register Forms (National Register Builetin 16). Complete each item by marking "x" in the appropriate box or by entering the requested information. If an item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, styles, materials, and areas of significance, enter only the categories and subcategories listed in the instructions. For additional space use continuation sheets (Form 10-900a). Type all entries.

(Pottit To-socia). Type all entitles.			
1. Name of Property			
historic name Newell A. Whi	iting house		
other names/site number John			
2. Location			
street & number 1105 Iowa .	Avenue		not for publication
city, town Onawa			vicinity
	ode IA county Honona	code 133	zip code51040
3. Classification			
Ownership of Property	Category of Property	Number of Resource	s within Property
X private	X building(s)	Contributing No.	oncontributing
public-local	district	1	1buildings
public-State	site		sites
public-Federal	structure		structures
	object	1	objects
			1Total
Name of related multiple property	/ listing:	Number of contribution	ng resources previously
N/A		listed in the National	
4. State/Federal Agency Car	rification	· · · · · · · · · · · · · · · · · · ·	
Signature of certifying official			Date
State Historical Sc	ociety of lowa		
State or Federal agency and bure	AU .		
In my opinion, the property	meets does not meet the National R	egister criteria. 🔲 See contir	nuation sheet.
Signature of commenting or other	official		Date
State or Federal agency and bure			- A - A - A - A - A - A - A - A - A - A
5. National Park Service Cer	tification		
, hereby, certify that this property		antered in the	/
entered in the National Regist		Wational Regis	ten a
See continuation sheet.	Telloues)	Ker Harrison Lines	8/10/90
determined eligible for the Na	tional	<del></del>	
		•	
Register. See continuation s		·	
determined not eligible for the National Register.			
removed from the National Re	gister.		
other, (explain:)			
	Signature o	f the Keeper	Date of Action
	X	•	

6. Function or Use	
Historic Functions (enter categories from instructions)	Current Functions (enter categories from instructions)
Domestic/single dwelling	Domestic/single dwelling
7. Description	
Architectural Classification (enter categories from instructions)	Materials (enter categories from instructions)
	foundation <u>Brick</u>
Late Victorian/Italianate	walls _Brick
	roof Other/Composition shingles
	other <u>Metal</u>

#### Describe present and historic physical appearance.

Attractively sited on a large corner lot in one of Onawa's oldest residential neighborhoods, the Newell A. Whiting house is a 2 1/2 story edifice, constructed of locally produced pinkish-toned brick laid in running bond that rests on foundations of the same material, and is capped with a medium-pitched gable roof that features a square-shaped metal-clad cupola at its apex and flanked by interior end, decorative chimney stacks with stone caps. Stylistically, the house is Italianate and is virtually a textbook example of the center-gable subtype of that mode.

#### Italianate details include:

overnanging eaves with decorative metal brackets (styled to look like stone); modillion; cupola, clad with metal molded to look like stone; hip roof.

tall, thin (2 light) windows, shallow arched with metal hood moldings; some paired. one story long porch on east side of house, supported by cast metal Corinthian columns. double walnut front doors with etched glass panels and transom, heavy moldings, brass hardware.

facade symmetry--central entrance is flanked by matching bay windows; house is rectangular (nearly square) with an ell at the rear.

anacones and cornices.

The stylistic elements are consistent on all four sides of the building. There is some evidence of the designer's consciousness of the house's corner location, as dominant elements such as bay windows, porches and entrances are located on the two sides which face the streets. The front of the house has a very formal, symmetrical arrangement of windows and entrances, while the other sides are less formal.

Facade (south side): The double front doors of walnut with etched and beveled glass windows and transom are centered between two identical 5' x 9' bays, each with three tall two-light windows, with formed metal hood molding and sills. A narrow, flat bracketed roof extends across the first floor, forming the roof of the bays and roof for the entrance. Originally, two metal Corinthian columns supported the roof on either side of the entrance. The six windows on the second story are grouped. Two align with each bay and are the same size and type as the first floor windows. Two narrower windows are paired over the front doors. The third story features a large central gable. Two small, narrow two-light windows are paired under a heavy hood molding and centered in the gable and over the central windows on the second floor and the entry on the first floor. The bottom of the windows aligns with the bottom of the facia on the main roofline.

East wall: Windows in this wall are the same sizes and type as in facade. A single window is near the front corner of the house. A second identical window shown in old photos was filled in when a fireplace was added to the living room. A 4' x 9' bay fills

#### National Register of Historic Places Continuation Sheet

Section number	Page1	
		CFN-259-1116

It differs from the front bays in its slightly smaller size and square shape. It has one tall, narrow window on each side and two identical paired windows on the outer side. The roofline of this bay aligns with the front bays. An ell at the rear of the house forms a second wall on this side. A 10' x 24' covered porch extends almost the full length of the 28' ell. Three cast metal Corinthian columns support the roof. Two windows flank a door on the long wall of the porch. Another door (to the living room) is in the short wall of the porch. Windows on the second floor of the main wall are stacked over those on the first floor--two single windows with a pair of windows over the bay. The ell is only two stories tall with a similar roofline as the main part of the house. Most of the second story wall on the ell is the central gable with a pair of short, narrow windows centered in the gable.

North wall: Ell and porch extend almost full width of house. First floor of ell on the north side had only one door near the northeast corner (originally to the summer kitchen) and no windows. Second story has large central gable with one arched window. The third story is part of the main structure, with the same large central gable and pair of small windows as other sides of the house.

The west wall of the main structure is similar to the east wall, with two single windows stacked on the first and second floors. Instead of a bay, as on the east wall, there are a pair of windows on both the first and second floors. The same large central gable on the third floor has the same pair of small windows centered. The west wall of the ell has been altered somewhat. On the first story near the northwest corner, a garage door that was cut through the brick wall in the 1930s has been filled with a large window, consisting of four panes of plain and one long antique pane laced with diamonds with circles of beveled glass. A tall, narrow window of the same size and type as most of the other windows is slightly off-center in the west wall. To the right of it is a door which, judging from the size, molding and glass panel, may originally have been a window. The second floor of the ell has the same large central gable and pair of small windows as the other walls.

The interior of the house is highly compatible with the exterior, and remains substantially the same as originally built. The woodwork, doors, hardware, floors, and windows are all original. The high ceilings, ornate staircase and long central hallway flanked by the living room and parlor (now dining room) are typical of the period.

Feature Staircase	Location Front hall	Discussion  Carved walnut newelpost and cherry banister, turned and carved spindles, paneled inlays of burl walnut in newelpost with carvings of beadwork, acanthus leaves, ivy and floral; continues from first to third story
Double interior doors	Living room, dining room, kitchen	Paneled with heavy woodwork; painted white since 1934; dark varnish before then.
Curved wall	Rear of entry	Follows curve of first stair landing above.
Curved wall	West bedroom	Forms closet wall.

# National Register of Historic Places Continuation Sheet

Section number7	Page2	CFN-259-1116
Alteration	Date	Discussion
Following changes were m	ade by Charl	es and Esther Murphy:
Front porch columns removed	1934	
Front porch surface and steps changed to brick	1934	
Side porch screened	1934	
Shutters added	c. 1950	Wooden louvered shutters
Chimney removed	between 1934-1950	
Summer kitchen removed	1934	Frame building at rear of house.
Carriage house removed	1934?	Was made of same brick as house.
Portion of west wall removed on first floor	1934	Original kitchen was made into garage (door opening)
Following alteration was	made by Joh	n E. Murphy:
Frame garage added	1983	Garage in rear of house made into family room
Interior alterations: Following alterations we	re made by C	harles and Esther Murphy:
Original parlor and dining room joined to make larger living room	1934	Steel beam added to ceiling to replace interior wall which was removed.
Brick heatilator fire- place	1934	Added at the insistence of Charles Murphy over resistance by interior designer. Virtually the only elemen not true to the style of the house.
Music room was remodeled into kitchen	1934	
Original kitchen remodeled into garage	1934	Wainscoting, flooring and windows remained.
Stairway from original kitchen to rear of second story removed	1934	Evidence of stairway was found during 1983 remodeling.
Stairway from original kitchen to root cellar removed	1934	Evidence of stairway can be seen in root cellar.
Bathroom added to second floor from portion or large central ballway	1934	Original windows and flooring remain; vertical space for pipes carved out of brick interior wall in


# National Register of Historic Places Continuation Sheet

Page <u>3</u>	CFN-259-1116
<u>Date</u> 1934	Discussion Wall removed, two clothes closets and small cedar closet added.
1934	White wooden mantel faced with blue, white and yellow painted Italian tiles; directly above living room fireplace.
made by Joh	n E. Murphy:
1983	Floors had to be replaced; original wainscoting, windows, doors and woodwork retained; some wainscoting duplicated; garage door space filled with plain glass and antique beveled glass window.
	Date 1934 1934 made by Joh

The house dominates the south end of four adjacent flat lots paralleling Eleventh Street on the east. Iowa Avenue, the town's main street, offers a close view to passers-by. On the south and east sides, a wrought iron fence installed in 1884 adds its Victorian charm. The yards surrounding the house are elaborately landscaped with a wide variety of trees, shrubs and flowering plants. A red rock curved driveway off the alley to the west coordinates with the rose colored brick of the house. A single garage of rose-stained wood (1983) sit: next to the alley and the driveway. Extending east from the garage and designed around a large hard maple, an elevated patio, made from square bricks, is bordered with a hosta hedge. Originally a carriage house (its foundation is still underground) sat in the vicinity of the present garage. It is said that it had a cupola just like that of the main house, although no pictures have been located to document its appearance. A frame summer kitchen was attached to the north end of the house. The Sanborn maps of early years show other buildings attached to or adjacent to the carriage house along the alley. They are supposed to be a barn and sheds for animals, etc. Cistern remains -- to the west and east of the ell on the north of the main house -- fed underground to the main kitchen. Cement walkways (now underground) led to the carriage house.

### National Register of Historic Places Continuation Sheet


Section number \_\_\_7 Page \_\_4 \_\_\_\_



### National Register of Historic Places Continuation Sheet

Section number 7 Page 5


CFN-259-1116



### National Register of Historic Places Continuation Sheet

Section number \_\_\_\_7 Page \_\_6


CFN-259-1116



### National Register of Historic Places Continuation Sheet

Section number \_\_\_\_\_\_\_ Page \_\_\_\_\_\_\_

CFN-259-1115



HEWELL WHITING RESIDENCE 1106 IOWA AVENUE ONAWA, IOWA


### United States Department of the Interior

National Park Service

### National Register of Historic Places Continuation Sheet

Section number 7 Page 8

CFN-259-1115





ORIGINAL SECOND FLOOR

### National Register of Historic Places Continuation Sheet

Section number \_\_\_\_\_\_ Page \_\_\_\_9

CFN-259-1116





THIRD FLOOR (UNCHANGED)
NEWELL WHITING RESIDENCE
1106 10WA AVENUE
OMNWA, 10WA

8. Statement of Significance		
Certifying official has considered the significance of this pro	perty in relation to other properties:  statewide X locally	
Applicable National Register Criteria A B X C	□D	
Criteria Considerations (Exceptions)	□D □E □F □G	
Areas of Significance (enter categories from instructions) Architecture	Period of Significance c. 1880-1882	Significant Dates N/A
	Cultural Affiliation	
Significant Person	Architect/BuilderUn! <nown td="" unknown<=""><td></td></nown>	

State significance of property, and justify criteria, criteria considerations, and areas and periods of significance noted above.

The Newell A. Whiting house, constructed between 1880 and 1882, is the best preserved example of the Italianate style in Onawa and one of the best in Monona County. The property is significant under Criterion C: properties that embody the distinctive characteristics of an architectural style and that possess high artistic values, in this case being virtually a textbook example of that style. Although Onawa and Monona County have not been intensively surveyed, the results of a recent reconnaissance survey conducted by Bureau of Historic Preservation staff indicate that the claims for significance are valid.

The house is a fairly pure, if simple, interpretation of the Italianate style popular in the middle of the 19th century. The dominant architectural attributes and detailing are all Italianate; missing are string courses, quoins and arcading found in more elaborate buildings of the style. Foundation and all walls, exterior and interior, are of pressed local brick from the Turin Brickyard (about seven miles from Onawa). Newell Whiting, who had the house built in his later years for his second wife, was a hardware merchant and owned a sawmill. The woodwork and fine brass hardware reflect the best that was obtainable at that time and place. With few exceptions, all materials in the house are original. Some of the furniture was purchased from Whiting's widow by John R. Murphy; other pieces are antiques from the Murphy family. Thus, the house and its contents remain quite true to the period of construction.

9. Major Bibliographical References	
Field Guide to American Architecture, A, Carole	Rifkind, New American Library, New York, 1980
Historic Architecture Sourcebook, April M. Harr	is, editor; McGraw-Hill, New York, 1977
Identifying American Architecture, John JG. B Local History, Nashville, Tennessee, 1977	lumenson, American Association for State and
What Style Is It? A Guide to American Architec	tumo John C. Donailiana C. Allas Chambana
Jr., Nancy B. Schwartz, Preservation Press, Nat	
Washington, D.C., 1983	ional liado los miscollo liacocivación,
History of Monona County, Iowa National publish Newell A. Whiting biography, page 617; John R. B. Pullen biography, pages 408-409 (woodworker	Murphy biography, pages 450-451; Nalden
Onawa Gazette, articles about progress of const	ruction of Newell Whiting home, June 17, 1880;
Previous documentation on file (NPS):	Dalman, legation of additional data.
preliminary determination of individual listing (36 CFR 67) has been requested	Primary location of additional data:  State historic preservation office
previously listed in the National Register	Other State agency
previously determined eligible by the National Register	Federal agency
designated a National Historic Landmark	Local government
recorded by Historic American Buildings	University
Survey #	Other
recorded by Historic American Engineering	Specify repository:
Record #	
10. Geographical Data	
Acreage of property Less than one.	
UTM References  A 1.5 7 4.0 1.7.0 4.6.5.6 6.2.0  Zone Easting Northing  C	B Zone Easting Northing D
	See continuation sheet
Verbal Boundary Description	
Lots 3, 4, 5, and 6, Block 67, Onawa, Monona Com	unty, Iowa
	See continuation sheet
Boundary Justification	
The boundary includes the four city lots that hat the property.	ave historically been associated with
	See continuation sheet
11. Form Prepared By	
name/title Carol Murphy (Mrs. John E. Murphy), w	
organization	date January, 1990
street & number 7614 Sandy Point Road N.E.	telephone (206) 491-7678
city or town <u>Olympia</u>	state <u>Washington</u> zip code <u>98506</u>

#### National Register of Historic Places Continuation Sheet

Section number9	Page _1
-----------------	---------

CFN-259-1116

Onawa Gazette, October 14, 1880; March 24, 1881; May 26, 1881; October 27, 1881; February 2, 1882; May 4, 1882; May 11, 1882; May 26, 1882; available at Onawa Public Library.

Onawa Gazette, articles about wrought iron fence around property; July 24, 1884; August 14, 1884; available at Onawa Public Library.

Onava Gazette, article about new plaster relief work and interior decor, July 11, 1889; available at Onawa Public Library.

Onawa Gazette, Newell A. Whiting obituary; October 1, 1891; available at Onawa Public Library

Onawa Gazette, article concerning purchase of property by John R. Murphy; March 15, 1894; availabale at Onawa Public Library

Onawa Gazette, John R. Murphy obituary; November 19, 1931; available at Onawa Public Library

Sioux City Journal, May 11, 1969, Section D, page 1, history of Whiting brothers and descendants, with photos of Whiting properties

Probate records, Newell A. Whiting, filed April 1, 1892; available at Monona County Courthouse

Interview with Ruth Evans (sister of Mrs. Charles Murphy and resident of the Whiting-Murphy house for over 35 years), by Carol Murphy, summer of 1978, verifying history of all antique furnishings in the house.

Interview with Jane McNeill (neighbor of John R. Murphy family and lifelong Onawa resident), by John E. and Carol Murphy, summer of 1980.

Letters from Jeanne M. Reistrup (interior designer for Esther Murphy from 1934-1976) to John and Carol Murphy, August 11, 1979, and January 20, 1980; verifying information on 1934 remodeling and on furnishings.

Notes from Charles and Joan Petersen (caretakers from 1979 to 1989), concerning land-scaping and clues to original architectural details discovered during remodeling in 1983.

#### National Register of Historic Places Continuation Sheet

Section number photo Page 1

CFN-259-1116

Since these photos were taken, repairs have been made to the roof of the house. Some roof joists had to be replaced because of rot, copper valleys replaced old galvanized ones, and composition shingles were replaced. No architectural details were changed and the overall appearance of the roof is virtually identical.

1. Newell A. Whiting house, Onawa, Monona County, Iowa

Photographer unknown

Date: 1980-1982

Negative location unknown, probably one of Onawa newspapers (photo was used in article about house)

South facade of home from sidewalk, showing detail of wrought iron fence.

2. Newell A. Whiting house, Onawa, Monona County, Iowa

Photographer: John E. Murphy

Date: June 1986

Negative location: John E. Murphy

South facade of property from Iowa Avenue

3. Newell A. Whiting house, Onawa, Monona County, Iowa

Photographer: John E. Murphy

Date: June 1986

Negative location: John E. Murphy

East side of home, showing screened porch and rear ell.

4. Newell A. Whiting house, Onawa, Monona County, Iowa

Photographer: John E. Murphy

Date: June 1986

Negative location: John E. Murphy

North side of home (rear) from back yard, showing chimneys, cupola and rear ell.

5. Newell A. Whiting house, Onawa, Monona County, Iowa

Photographer: John E. Murphy

Date: June 1986

Negative location: John E. Murphy

West side of house from alley, showing rear ell with kitchen door and large window created from former garage door opening.

6. Newell A. Whiting house, Onawa, Monona County, Iowa

Photographer: John E. Murphy

Date: June 1986

Negative location: John E. Murphy

Garage with adjoining patio and garden, looking northwest.

7. Newell A. Whiting house, Onawa, Monona County, Iowa

Photographer: John E. Murphy

Date: June 1986

Negative location: John E. Murphy

Detail of eaves, showing formed metal modillions and hood moldings.

#### National Register of Historic Places Continuation Sheet

Section number photo Page 2

CFN-259-1116

8. Newell A. Whiting house, Onawa, Monona County, Iowa

Photographer: John E. Murphy

Date: June 1986

Negative location: John E. Murphy

South facade, showing front porch roof, windows and roof detailing, and pressed brick wall.

9. Newell A. Whiting house, Onawa, Monona County, Iowa

Photographer: John E. Murphy

Date: June 1986

Negative location: John E. Murphy

Double front doors (south facade) viewed from front porch; walnut with original brass hardware and etched glass panes. Transom above doors with etched glass pane not visible.

10. Newell A. Whiting house, Onawa, Monona County, Iowa

Photographer: John E. Murphy

Date: June 1986

Negative location: John E. Murphy

Double front doors (south facade) from entry hall; walnut painted white, with etched glass panes, etched glass transom and original brass hardware.

11. Newell A. Whiting house, Onawa, Monona County, Iowa

Photographer: John E. Murphy

Date: June 1986

Negative location: John E. Murphy

Entry hall looking north, showing staircase with carved bannister and newelpost and archway.

12. Newell A. Whiting house, Onawa, Monona County, Iowa

Photographer: John E. Murphy

Date: June 1986

Negative location: John E. Murphy

Detail of stairway from second to third story.

13. Newell A. Whiting house, Onawa, Monona County, Iowa

Photographer: John E. Murphy

Date: June 1986

Negative location: John E. Murphy

East wall of living room looking southeast, showing fireplace.

#### **National Register of Historic Places Continuation Sheet**

Section number photo Page 3	3	e	Page	_photo_	r _	number	tion	Sec
-----------------------------	---	---	------	---------	-----	--------	------	-----

CFN-259-1116

14. Newell A. Whiting house, Onawa, Monona County, Iowa

Photographer: John E. Murphy

Date: June 1986

Negative location: John E. Murphy

Detail of southwest bedroom on second floor, showing curved wall, woodwork, and wide board softwood floor.

Newell A. Whiting house, Onawa, Monona County, Iowa

Photographer: Unknown

Date: Unknown; before 1934

Negative location: Unknown

View of property from southeast intersection of Iowa Avenue and Eleventh Street; copy of historic photo belonging to Murphy family

Newell A. Whiting house, Onawa, Monona County, Iowa

Photographer: Unknown

Date: Unknown; date of November 1956 on snapshot is not accurate. Apparently a copy of an earlier photo.

Negative location: Unknown

View of east side of house. Photo taken prior to 1934 remodeling; showing frame summer kitchen at rear, side porch is unscreened and fireplace not yet added to living room and master bedroom (requiring bricking up of windows).

Newell A. Whiting house, Onawa, Monona County, Iowa

Photographer: Unknown

Date: Sometime between 1894 and 1931 (the time home was occupied by John R. Murphy)

Negative location: Unknown

View of south and east sides of house from Iowa Avenue. Copy of postcard owned by Murphy family.