

KENTUCKY HISTORIC RESOURCES INVENTORY

Site No. Mr 82

1. Historic Name(s) <u>Smith house</u>		22. ADD/County <u>Bluegrass / Harrison</u> <input type="checkbox"/> <u>049</u>	
Original Owner <u>Smith</u>		23. U.S.G.S. Quadrant (15'/75') <u>Shawhan vic</u> G.I.S. Mod. <u>138</u>	
2. Present Name		24. UTM Reference	
3. Location <u>abn. mi. off White Old Fair Road on lane commencing across from Cook Road</u>		<u>16</u> <u>737700</u> <u>4248540</u>	
4. Owner's Name <u>Mrs. George Midden age 92</u>		Zone Easting Northing	
5. Owner's Address <u>204 N. Church St., Cynthiana, Ky. 41031</u>		25. Coordinate Accuracy <input type="checkbox"/>	
6. Open to Public Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		26. Prehistoric Site Object	
7. Visible from road Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		Historic Site Structure	
8. Ownership Private <input type="checkbox"/> Local <input type="checkbox"/> State <input type="checkbox"/> Federal <input type="checkbox"/>		Building <input checked="" type="checkbox"/> Other	
9. Local Contact/Organization <u>Joe Midden, son 234-4766</u>		27. National Register District Name:	
10. Site Plan with North Arrow <u>see attached boundary plan</u>		28. Significance Evaluation <input type="checkbox"/>	
11. Architect		29. Status Date	
12. Builder		National Landmark <input type="checkbox"/>	
13. Date <u>c. Civil War</u> A. <input checked="" type="checkbox"/> B. <input type="checkbox"/>		National Register <input type="checkbox"/>	
14. Style A. <u>Greek R.</u> <input checked="" type="checkbox"/> B. <input type="checkbox"/>		Landmark Certificate <input type="checkbox"/>	
15. Original Use <u>residence</u> <input checked="" type="checkbox"/>		Kentucky Survey <input type="checkbox"/>	
16. Present use <u>residence</u>		Local Landmark <input type="checkbox"/>	
17. Condition <u>excellent</u> <input checked="" type="checkbox"/>		HABS/HAER <input type="checkbox"/>	
18. Description <u>Small 2 story 3 bay stone house probably of later period if window frames original (did not see inside woodwork). Exterior shouldered chimney on E end; wood (ph.4) lintels, narrow milled-corner frames, 2/2 bask, wide eaves (if original),</u> (Continue on Back) <u>(over)</u>		30. Historic Theme Primary <u>Architecture</u> <input checked="" type="checkbox"/> Secondary <input type="checkbox"/> Other <input type="checkbox"/>	
No. Stories <u>2</u> <input checked="" type="checkbox"/>		31. Endangered Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
Single Pile <input checked="" type="checkbox"/> NA <input type="checkbox"/>		32. Preservation Project Status <input type="checkbox"/>	
Double Pile <input type="checkbox"/>		Actual Cost in \$1,000s <input type="checkbox"/>	
Floor Plan <u>single cell, rec.</u> <input checked="" type="checkbox"/>		33. ATTACH PHOTO <u>in attached envelope</u>	
Structural Fabric <u>stone</u> A. <input checked="" type="checkbox"/> B. <input type="checkbox"/>		Roll No. _____	
Decorative Fabric <u>—</u> A. <input type="checkbox"/> B. <input type="checkbox"/>		Picture No. _____	
Roof Form <u>gable</u>		Direction _____	
19. History <u>Built by Smith family</u>		34. Prepared by: <u>C.M. Woolley</u>	
20. Significance <u>Nice example of late day stone house in beautiful location.</u>		35. Organization _____	
21. Source of Information <u>18: inspection</u>		36. Date <u>1982</u>	
<u>19: Mrs Joe Midden, dec in law</u>		37. Revision Dates _____	
<u>13: " " "</u>		38. Staff Review _____	

18 cont.:

~~masonry repainted~~; 2 bays on
2nd floor; small attic windows
covered. 1 story 2 bay stone
room on rear the full width of
house, having frame shed roof -
back half of main house roof
continues down to rear of rear,
creating salt box shape; wood
lintel match front, 6/6 sash,
2 bays. House once had stone
wing on W end, now has new
frame wing on entire E end.

May have been built
w. concrete mortar?

(photo 3)

Located on knoll in wide
valley of Licking River.

Has dug well in yard, rock
wall along front and side of yard,
remains of stone spring house in
lower front corner; a frame meat? (photo 5)
house to E side. Outside the yard
is a 2 story log pen with stone
foundation, surrounded by a frame
barn.

Since report written info received
that house ^{partially} burned and has been
in part replaced including roof.
Original iron mantel survives. C.W.
An old road ran past house to
a ford of the Licking - a direct
route to Cynthia.

VERBAL BOUNDARY DESCRIPTION & JUSTIFICATION

Beginning at A at the SE corner of the spring house, thence with rock fence W 165 ft to B, thence N 210 ft along wire fence to C, thence E across yard, past fence row ^{165 ft} to D, thence S with rock fence 210 ft to the beginning, containing the stone house, meat house and stone spring house - about .8 acre.
 (Probably showing govt. land records for town.)

SKETCH MAP OF SITE SHOWING BOUNDARIES AND KEY BUILDINGS AND FEATURES WITH NORTH ARROW.

