

NAME: Entrance (LCS-171) Sherburne Ranger Station Historic District LOCATION: Glacier National Parkmet. mt PHOTOGRAPHER: Glacier National Park DATE: 9/25/83 VIEW: SE Side LOCATION OF NEGATIVES: Rocky Mountain Regional Office, National Park Service, Denver, CO



NAME: Ranger Cabin--Sherburne Ranger Station Historic District LOCATION: Glacier National Park, MT PHOTOGRAPHER: Lance Olivieri DATE OF PHOTOGRAPH: August 1975 LOCATION OF NEGATIVE: Rocky Mountain Regional Office, National Park Service, Denver, CO PHOTO NUMBER: 2



NAME: Entrance (LCS-171) Sherburne Ranger Station Historic District LOCATION: Glacier National Park

PHOTOGRAPHER: Glacier National Park DATE: 9/25/83 VIEW: South side LOCATION OF NEGATIVES: Rocky Mountain Regional Office, National Park Service, Denver. CO



NAME: Entrance (LCS-171) Sherburne Ranger Station Historic District LOCATION: Glacier National Park MAT PHOTOGRAPHER: Glacier National Park DATE: 9/25/83 VIEW: West side LOCATION OF NEGATIVE: Rocky Mountain Regional Office, National Park Service, Denver, CO



NAME: Barn (LCS-473) Sherburne Ranger Station Historic District LOCATION: Glacier National Park MRA MT PHOTOGRAPHER: Glacier National Park DATE: 9/23/83 VIEW: SE side LOCATION OF NEGATIVE: Rocky Mountain Regional Office, National Park Service, Denver, CO



NAME: Barn (LCS-473) Sherburne Ranger Station Historic District LOCATION: Glacier National Park MARA MIT PHOTOGRAPHER: Glacier National Park DATE: 9/25/83 VIFW: NF LOCATION OF NEGATIVE: Rocky Mountain Regional Office, National Park Service. Denver, CO



NAME: Barn (LCS-473) Sherburne Ranger Station Historic District LOCATION: Glacier National Park MAT PHOTOGRAPHER: Glacier National Park DATE: 9/25/83 VIFW: West LOCATION OF NEGATIVE: Rocky Mountain Regional Office, National Park Service, Denver, CO



NAME: Barn--Sherburne Ranger Station Historic District LOCATION: Glacier National Park, MT PHOTOGRAPHER: Lance Olivieri DATE OF PHOTOGRAPH: August 1975 LOCATION OF NEGATIVE: Rocky Mountain

Regional Office, National Park Service,
Denver, CO

PHOTO NUMBER: 4



NAME: Garage (LCS-474) Sherburne Ranger Station Historic District LOCATION: Glacier National Park Met MT PHOTOGRAPHER: Glacier National Park DATE: 9/25/83 VIEW: SE corner LOCATION OF NEGATIVES: Rocky Mountain Regional Office, National Park Service, Denver, CO



NAME: Employee Garage (474) -- Sherburne Ranger Station Historic District LOCATION: Glacier National Park, MT PHOTOGRAPHER: Lance Olivieri DATE OF PHOTOGRAPH: August 1975

LOCATION OF NEGATIVE: Rocky Mountain
Regional Office, National Park Service,
Denver, CO
PHOTO NUMBER: 3



NAME: Entrance Checking Station--Sherburne Ranger Station Historic District LOCATION: Glacier National Park, MT PHOTOGRAPHER: Lance Olivieri DATE OF PHOTOGRAPH: August 1975 LOCATION OF NEGATIVE: Rocky Mountain . Regional Office, National Park

Service, Denver, CO

PHOTO NUMBER: 1



NAME: Entrance (LCS-476) Sherburne Ranger Station Historic District LOCATION: Glacier National Park MRA, MT PHOTOGRAPHER: Glacier National Park DATE: 9/25/83 VIEW: NW LOCATION OF NEGATIVE: Rocky Mountain Regional

Office, National Park Service, Denver, Co



NAME: Entrance (LCS-476) Sherburne Ranger Station Historic District LOCATION: Glacier National Parkmet, MT PHOTOGRAPHER: Glacier National Park DATE: 9/25/83 VIEW: SW corner LOCATION OF NEGATIVE: Rocky Mountain Regional Office National Park Service, Denver, 60



NAME: Entrance (LCS-476) Sherburne Ranger Station Historic District LOCATION: Glacier National Park MAP, MT PHOTOGRAPHER: Glacier National Park DATE: 9/25/83 VIEW: NF LOCATION OF NEGATIVE: Rocky Mountain Regional Office National Park Service, Denver, CO PHOTO #: 4



NAME: Outhouse (LCS-601) Sherburne Ranger Station Historic District LOCATION: Glacier National Park MAA MT PHOTOGRAPHER: Glacier National Park DATE: 9/25/83 VIFW: SW LOCATION OF NEGATIVE: Rocky Mountain Regional Office, National Park Service, Denver, CO



NAME: Out-house Sherburne Ranger Station Historic District (LCS-651) LOCATION: Glacier National Park MRA MT PHOTOGRAPHER: Glacier National Park DATE: 9/25/83

LOCATION OF NEGATIVE: Rocky Mountain Regional Office, National Park Service, Denver, CO



Emp. Residence HS-171 Int. lenter room N wall Sherburne RSHD Glacier Co, UT, Glacier NP Pho ho #1



Emp. Residence HS-171 Onterior Kitchen E wall Sherburne RSHD Glacier Co, MT, Glacier NP Photo #2



Emp. Residence HS-171 Interior - Sw bedroom E Wall Sherburne RSHD Glacier Co UT, Glacur NP Photo #3



Emp. Residence 46-171 Interior - NW bedroom E wall door Sherburne RSHD Glacur Co, UT, Glacur NP Phoho #4



Mess Hull HS-173 Interior Kitchen fucing N Shuburne BHD Blacur Co, MT, Glacur NP Phoh#5



Mess Hull HS-173 Interior Kitchen Sherbure RSHD Glacier Co, MT, Glacier NP Photo #6



Barn HS-473 Interior Facing W Therhuma RSHD. Glacier Co. MT GLAC. Photo # 7



Barn HS-473 Interior Facing N Sherbune RSHO GlACIE CO, NOT GLAC Proto 8



woodshed HS-474 Interior - South NW corner Sherbune RS HD GLACLER CO, MT GLAC Photo 9



HS-474 wood Shed Interior N S wall Sherburne RS 40

Claver CO, MT GLAC

Photo 10



wood Shed HS - 474 Interior N N.W Corner RSHO Sherbune Clacer Co, MT GLAC Photo #11



Checkung Station- HS 476 Sherbur RSHD. Clarento MT GLAC Photo 12



Checking Station HS 4760 Surbure RSHD Glacia Co, MT GLAC Photo 13



Checkung Stahon HS 4760 Interum Therbune RS HD Classi Co. MT GLAL Photo 14