



Holmes Beach Bridge Farm
Lanes, Delaware

Photographer: Susan W. Holmes
May 1970

Location of Negative: 34.00
View from east of sample

1 of 15



Walter Owen Edge Farm
Lotts, Nevada

Photographed by Susan Littlejohn
July 1996

Location of vegetation at ST 30.

View from west of house
E. of ST 30



Hickory Covered Bridge Farm

Lowell, Delaware

Photographer: Sara Bonclaire

July 1992

Location of Negative: SHFD

View from South of center passage, main block

3 of 15



Hopkins' Covered Bridge Farm
Lewes, Delaware

Photographer: Susan Bizzolara

July 1990

Location of Negative: S.H.P.O.

Dining room, view from SW

4 of 15



Hydroponic Growth Bridge Farm

Loice, Delaware

Photographer: Susan Brzezina

July 1960

Location of Negative: S.H.F.O.

View shows W. of entrance to glass storage house

S. of 10



Hughes Covered Bridge Farm

Leeds, Vermont

Photographer: John Brantley

July 1990

Location of Negative: S.F.P.O.

Area: 100' SE of millhouse

6 of 15



Hockers Covered Bridge Farm
Lewes, Delaware

Photographer Susan Brice
July 1990

Location of Negroes, S.H. P.
Farm & Park, near Dover
1 of 15



Hoptons' Covered Bridge Farm

Lewes, Delaware


Photographer: Susan Brizzolara

July 1990

Location of Negative: S.H.P.O.

View from SW of 1925 barn and 1936 O'Neill wing

8 of 15



Highland's Covered Bridge Farm

Louisa, Delaware

Photographed by S. Del Sordo

July 1990

Location of Negative: SHARD.

New Horn 2 of 1st Year, 1925 barn

9 of 15



Hopkins' Covered Bridge Farm
Lewes, Delaware

Photographer: S. DelSordo

July 1990

Location of Negative: S.H.P.O.

View from east of 1936 wing

10 of 15



Hopkins' Covered Bridge Farm
Lewes, Delaware

Photographer: S. Del Sardo

July 1990

Location of Negative: S.H.P.O.

View from W. of O'Neill Barn loft

11 of 15



Map of Lower Bridge Farm

Lower, Delaware

Prepared by E. C. Sells

July 1912

Location of - Deyaher's S.H.P. Co.

View from NE of D'Veil Run 1817

12-15



Worms' Creek Bridge Farm

Leeds, Delaware

Photographer: S. Del Rio

July 1950

Location of Negatives: 24.90

Yeast from worm at bridge, Old Barn 10/20

13 24 10



Hopkins' Covered Bridge Farm
Lewes, Delaware

Photographer: S. Del Sordo

July 1990

Location of Negative: S.H.P.O.

O'Neill Barn loft, view from NW looking toward 1925 barn

14 of 15



Huttons' Covered Bridge Farm

Leicester, Delaware

Photographer: E. Col. Siro

July 1940

Location of negative: SH, 70.

Small barn with detail of pitch and construction.

15 of 15