



J.I. GARDNER STORE Prescott/Yavapai/Arizona Photo Date: August, 1984 Photographer: William Otwell Negative filed: William Otwell & Assoc. Prescott, AZ View: Camera facing east. Streetscape southeast corner of north Cortez (front) and Willis (side) Streets.



J.I. GARDNER STORE Prescott/Yavapai/Arizona Photo Date: August, 1984 Photographer: William Otwell Negative filed: William Otwell & Associates Prescott, Arizona View: Camera facing east. West elevation showing glass storefront, cast iron pilasters, pressed metal cornice and corrugated steel awning.



J.I. GARDNER STORE Prescott/Yavapai/Arizona Photo Date: August, 1984 Photographer: William Otwell Negative filed: William Otwell & Associates Prescott, Arizona View: From center of retail space facing to rear, interior stair and mezzanine.



J.I. GARDNER STORE Prescott/Yavapai/Arizona Photo Date: August, 1984 Photographer: William Otwell Negative filed: William Otwell & Associates Prescott, Arizona View: Camera facing northwest. Retail space interior from center to front showing glazing, ceiling and shelving.




J.I. GARDNER STORE Prescott/Yavapai/Arizona Photo Date: August, 1984 Photographer: William Otwell Negative filed: William Otwell & Associates Prescott, Arizona View: Camera facing east. Front third of retail space.



J.I. GARDNER STORE Prescott/Yavapai/Arizona Photo Date: August, 1984 Photographer: William Otwell Negative at: William Otwell & Associates Prescott, Arizona View: Detail of interior stairway.



J.I. GARDNER STORE Prescott/Yavapai/Arizona Photo Date: August, 1984 Photographer: William Otwell Negative filed: William Otwell & Associates Prescott, Arizona View: Skylight in mezzanine.



J.I. GARDNER STORE Prescott/Yavapai/Arizona Photo Date: August, 1984 Photographer: William Otwell Negative filed: William Otwell & Associates Prescott, Arizona View: Scale in receiving area of warehouse.



J.I. GARDNER STORE Prescott/Yavapai/Arizona Photo Date: August, 1984 Photographer: William Otwell Negative filed: William Otwell & Associates Prescott, Arizona


View: Front door




J.I. GARDNER STORE Prescott/Yavapai/Arizona Photo Date: August, 1984 Photographer: William Otwell Negative filed: William Otwell & Associates Prescott, Arizona View: Front door. Detail of original hardware.




J.I. GARDNER STORE Prescott/Yavapai/Arizona Photo Date: August, 1984 Photographer: William Otwell Negative filed: William Otwell & Associates Prescott, Arizona View: Detail of cast iron pilaster base front facade.



J.I. GARDNER STORE Prescott/Yavapai/Arizona Photo Date: August, 1984 Photographer: William Otwell Negative filed: William Otwell & Associates Prescott, Arizona View: Camera facing northwest. East elevation showing warehouse entry with shed roof and star washer on tie rods.



J.I. GARDNER STORE Prescott/Yavapai/Arizona Photo Date: August, 1984 Photographer: William Otwell Negative filed: William Otwell & Associates Prescott, Arizona View: Door in east elevation.



J.I. GARDNER STORE Prescott/Yavapai/Arizona Photo Date: August, 1984 Photographer: William Otwell Negative filed: William Otwell & Associates Prescott, Arizona View: Camera facing northwest. Rear elevation. Showing loading dock and hay barn.



J. I. GARDNER'S STORE-HISTORIC PHOTO Sharlot Hall Museum Archives Bu-B-8155 PA (camera facing northeast)



J. I. GARDNER'S STORE-HISTORIC PHOTO Sharlot Hall Museum Archives Bu-I-111PC (north wall interior)