


Schnull-Rauch House
Indianapolis, Indiana
Marion County, Indiana
Photographer unknown
Photograph published in 1908
Source:

Art Work of Indianapolis, Indiana Chicago: Gravure Illustration Co., 1908.


Negative on file at Indianapolis
Historic Preservation Commission
South and east elevations
are shown
Photograph # 15 of 15

DOE

OCT 3 1979




Schnull-Rauch House Indianapolis, Indiana MARION County 14 1979 Photographer: Tina Connor, Director of publications, Historic Landmarks 1979 Foundation of Indiana ect 3 Photo taken October 2, 1978 - Negative on file at Indianapolis Historic Preservation Commission East elevation is shown Photograph # 1 of 15



Schnull - Rauch House Indianapolis Indiana / 1979 MARION County Photographer: Tina Connor, 1979 Director of Publications, OCT 3 Historic Landmarks Foundation of Indiana photo taken October 2, 1978 Negative on file at Indianapolis Historic Preservation Commission Entryway, east elevation Photograph #2 of 15



Schnull -Rauch House Indianapolis Indiana MARION COUNTY, NOV 1 & 1979 Photographer: Tina Connor, 1979 Director of Publications, Historic Landmarks Foundation of Indiana Photo taken on October 2, 197 Negative on file at Indianapolis Historic Preservation Commission South elevation, seen from the Photograph #3 of 15 south west



```
673
    1 A 1979
Schnull - Rauch House
           Indianapolis Indiana
                                             Marion County
OCT 3 1978hotographer: Tina Connor, Director of Publications,
               Historic Landmarks
     Foundation of Indiana
     Photo taken October 2, 1972
     Negative on file at Indianapolis
    Historic Preservation Commission
  North elevation, seen from the
```

Photograph #4 of 15 northwest



Schnull - Rauch House Indianapolis Indiana MARion County
Photographer: Tina Connor, Director of Publications, Historic Landmarks Foundation of Indiana Photo taken on October 2, 1978 Negative on file at Indianapolis Historic Preservation Commission

Historic Preservation Commission West (rear) e(evatron.

Photograph #5 of /5



Schnull - Rauch House 1979
Indianapolis Indiana
MARION County
Photographer: Tina Connor,
1979 Director of Publications,

Historic Landmarks

Foundation of Indiana

Photo taken October 2, 1978
Negative on file at Indianapolis
Historic Preservation Commissin

- Carriage house garage, seen from Photograph #6 of 15 the east



Schnull - Rauch House Indianapolis Indiana 9 Historic Landmarks Foundation of Indiana Photo taken November 1, 1978 Negative on file at Indianaplois Historic Preservation Commission Reception hall and Stairway hall,

Photographer #7, Seen from the cast



Schnull - Rauch House Indianapolis Indiana MARION COUNTY Photographer: Tina Connor, Director of Publications, Historic Landmarks Foundation of Indiana Photo taken November 1, 1972 Negative on file at Indianapolis

Historic Preservation Commission
West wall of the Drawing Room.
Photograph #8 of 15



Schnull - Ranch House
Indianapolis Indiana

MARION County
Photographer: Tina Connor
Director of Publications,
Historic Landmarks

Photo taken November 1, 1975 3
Negative on file at Indianapolis
Historic Preservation Commission
Looking north, up the main
Photograph #9 of 5 Stairway

Foundation of Indiana



Schnull - Rauch House Indianapolis Indiana MARION COUNTY
Photographer: Tina Connor,
Director of Publications, Historic Landmarks Foundation of Indiana Photo taken November 1, 1978 Negative on file at Indianapolis

Historic Preservation Commission Dining Room, looking north-Photograph #10 of 15 East



Schnull - Rauch House Indianapolis Indiana MARION County
Photographer: Tina Connor,
Director of Publications, Historic Landmarks Foundation of Indiana Photo taken November 1, 1978 Negative on file at Indianapolis

Historic Preservation Commission

Main corridor, Second floor,
Photograph #11 looking east



Schnull - Rauch House Indianapolis Indiana MARION COUNTY
Photographer: Tina Connor, Director of Publications. Historic Landmarks Foundation of Indiana Photo taken November 1, 1979 3 Negative on file at Indianpolis Historic Preservation Commission Tower Bedroom, second floor Photograph #12 of 15 100 King north



Schnull - Rauch House Indianapolis Indiana Photographer: Tina Connor, Director of Publications. Historic Landmarks Marion County, Indiana Foundation of Indiana Photo taken November 1, 1978 Negative on file at Indianapolis

Historic Preservation Commission

- Rallroom, third floor, looking

Photograph #13 of 15 southwest



Schnu'll - Rauch House Indianapolis Indiana Photographer: Tina Connor Director of Publications, Historic Landmarks Marion County, Indiana Foundation of Indiana 197 Photo taken November 1, 1978 Negative on file at Indianpolis Historic Preservation Commission Billiard Room, basement looking. Photograph #14 of/5 northwest