



Taken in 1920's

Samuel Kraemer Building

76 S. Claudina St. Orange County

Anaheim, Ca. 92805

Photographer: Unknown

Negatives stored: Anaheim Public Library

500 W. Broadway

Anaheim, Ca. 92805

Bank building taken from across Lincoln,
looking at south and west facades. (1 of 14)



FEB 1982

Samuel Kraemer Building

76 S. Claudina St.

Anaheim, Ca. 92805

Orange County

Photographer: D. Marsh

Negatives stored. 321 N. Philadelphia

Anaheim, Ca. 92805

South (front) and west facades from
across the street. Taken when demolition
was completed of the altered parts. Dark
areas are where metal screen and arches
were.

(02 of 14)



FEB 1982

Samuel Kraemer Building
76 S. Claudina St. Orange County
Anaheim, Ca. 92805

Photographer: D. Marsh

Negatives Stored: 321 N. Philadelphia St.
Anaheim, Ca. 92805

Window in west facade after demolition of altered parts, reavealing original tiles and brick. Transom window will be a wood sashed replica of the original. Lower window original. (3 of 14)



FEB 1982

Samuel Kraemer Building
76 S. Claudina St. Orange County
Anaheim, Ca. 92805

Photographer: D. Marsh

Negatives stored: 321 N Philadelphia
Anaheim, Ca. 92805

West facade after demolition of altered
parts (except for floors 4 and 5 which will
be done later). Transom windows and windows
on floors 2 through 6 will duplicate the
original wood sashes. (4 of 14)



FEB 1982

Samuel Kraemer Building
76 S. Claudina St. Orange County
Anaheim, Ca. 92805

Photographer: D. Marsh

Negatives stored: 321 N. Philadelphia
Anaheim, Ca. 92805

Details of panels of terra cotta tiles on
entry to rear lobby. Twisted metal columns
can be seen bordering the sidelight in the
door frame.

(5 of 14)



FEB 1982

Samuel Kraemer Building
76 S. Claudina St. Orange County
Anaheim, Ca. 92805

Photographer: D. Marsh

Negatives stored: 321 N. Philadelphia
Anaheim, Ca. 92805

Top of building after demolition of altered
parts. Brown areas denote where the metal
arches and screens covered the building.
West facade and north side (rear).

(6 of 14)




FEB 1982

Samuel Kraemer Building
76 S. Claudina St. Orange County
Anaheim, Ca. 92805

Photographer: D. Marsh

Negatives stored: 321 N. Philadelphia
Anaheim, Ca. 92805

Top of windows in lower floor in the west
facade. Cornice at top of lower floor.
columns and frieze revealed when stucco
was removed. (7 of 14)

A black and white photograph of a highly ornate doorway. The doorway is set within a decorative frame with intricate carvings. Above the door is a large, light-colored panel with the number '203' mounted on it. The door itself is dark and appears to be slightly ajar, revealing a dark interior. The surrounding wall is light-colored with visible masonry lines. A small, light-colored rectangular object is visible on the wall above the door.

203

FEB 1982

Samuel Kraemer Building
76 S Claudina St. Orange County
Anaheim, Ca. 92805

Photographer: D. Marsh

Negatives stored: 321 N Philadelphia
Anaheim, Ca. 92805

Stamped metal door and window frame is
original and will be retained. Film will
be stripped from side lights and center
uncovered. South facade. (8 of 14)

EL CAMIN



FEB 1982

Samuel Kraemer Building

76 S. Claudina St. Orange Co. Anaheim, Ca.

Photographer: D. Marsh
Taken February 1982

Negative: 321 N. Philadelphia St.
Anaheim, Ca. 92805

West facade facing Claudina St. Windows and cornice above lower floor. Columns and frieze were revealed when stucco was removed. Transom is ready for reinstallation of replicas of the original wood sash windows. (9 of 14)



FEB 1982

Samuel Kraemer Building
76 S. Claudina St. Orange County
Anaheim, Ca. 92805

Photographer: D. Marsh

Negatives stored: 321 N. Philadelphia
Anaheim, Ca. 92805

Cornice, first floor transom, and upper
floors on the west facade, looking straight
up.

(10 of 14)



FEB 1982

Samuel Kraemer Building
76 S. Claudina St. Orange County
Anaheim, Ca. 92805

Photographer: D. Marsh
Negatives stored: 321 N. Philadelphia
Anaheim, Ca. 92805

Ceiling in bank area on lower floor. It
was revealed when the acoustical ceiling
was removed. Colors are green and cream
with gold accents. (11 of 14)



Samuel Kraemer Building

FEB 1982

76 S. Claudina St. Orange Co. Anaheim, Ca.

Photographer: D. Marsh' 92805

Negatives Stored: 321 N. Philadelphia
Anaheim, Ca. 92805

North facade facing alley. The trim from
the west and south facades is wrapped
around the end of the building. The col-
umns and capitals match those on the
front. (2 of 14)



FEB 1982

Samuel Kraemer Building
76 S. Claudina St. Orange County
Anaheim, Ca. 92805

Photographer: D. Marsh
Negatives stored: 321 N. Philadelphia
Anaheim, Ca. 92805

Stamped metal door and window frame in
main entrance on south facade.

(13 of 14)



FEB 1982

Samuel Kraemer building
76 S. Claudina St Orange County
Anaheim, Ca. 92805

Photographer: D. Marsh

Negatives stored: 321 N. Philadelphia
Anaheim, Ca. 92805

Rear lobby to upper floors. All original
except for elevator doors.

(14 of 15)