



The Crows Nest / Sturgis-Goodman Property

Wilmington, Windham Co., VT

Credit: Paula Sagerman

March 1997

Negative filed at Vermont Division for Historic Preservation

Looking east at property setting: barns and rear of farmhouse

Photograph #1

Buildings 4, 3, 5, 2 - Description

Buildings D, C, B, A - Sketch map





The Crows Nest / Sturgis - Goodman Property  
Wilmington, Windham Co., Vermont

Credit: Paula Sagerman

June 1997

Negative filed at Vermont Division for Historic Preservation

Looking northwest at farmhouse

Photograph #2

Building 2 - Description

Building A - Sketch map





The Crows Nest / Sturgis - Goodman Property  
Wilmington, Windham County, Vermont

Credit: Paula Sagerman

March 1997

Negative filed at Vermont Division for Historic Preservation

Looking southeast at farmhouse and shed

Photograph # 3

Building ~~2~~ 5 from Description

Building ~~A~~ B from Sketch map





The Crows Nest / Sturgis-Goodman Property  
Wilmington, Windham County, Vermont

Credit: Paula Sagerman

March 1997

Negative filed at Vermont Division for Historic Preservation

Viewing of east wall of rear central room of farmhouse

Photograph #4

Building 2 from Description

Building A from Sketch Map







The Crows Nest/Sturgis-Goodman Property  
Wilmington, Windham County, Vermont  
Credit: Paula Sagerman

March 1997

Negative filed at Vermont Division for Historic Preservation  
Looking north at large barn and small barn

Photograph #5

Buildings 3, 4 from Description

Buildings D, C from Sketch map