The Crows Nest / Sturgis-Goodman Property
Wilmington, Windham Co., VT
Credit: Paula Sagerman
March 1997
Negative filed at Vermont Division for Historic Preservation
Looking east at property setting: barns and rear of farmhouse
Photograph #1
Buildings 4, 3, 5, 2 — Description
Buildings D, C, B, A - Sketch map

The Crows Nest / Sturgis-Goodman Property
Wilmington, Windham Co., Vermont
Credit: Paula Sagerman
June 1997
Negative filed at Vermont Division for Historic Preservation
Looking northwest at farmhouse
Photograph #2
Building 2 - Description
Building A - Sketch map

The Crows Nest / Sturgis-Goodman Property
Wilmington, Windham County, Vermont
Credit: Paula Sagerman
March 1997
Negative filed at Vermont Division for Historic Preservation
Looking southeast at farmhouse and shed
Photograph # 3
Building 2, 5 from Description
Building A, B from Sketch map

The Crows Nest / Sturgis-Goodman Property
Wilmington, Windham County, Vermont
Credit: Paula Sagerman
March 1997
Negative filed at Vermont Division for Historic Preservation
View of east wall of rear central room of farmhouse
Photograph #4
Building 2 from Description
Building A from Sketch Map

The Crows Nest/Sturgis-Goodman Property
Wilmington, Windham County, Vermont
Credit: Paula Sagerman

March 1997
Negative filed at Vermont Division for Historic Preservation
Looking north at large barn and small barn

Photograph #5
Buildings 3, 4 from Description
Buildings D, C from Sketch map