



Burlington Breakwater

Burlington, Chittenden, Vermont

Credit: Ann Cousins

August 1999

Negative filed at US ARMY CORPS OF ENGINEERS, NEW YORK DISTRICT

view looking north; harbor side of breakwater

Photograph # 1



Burlington Breakwater

Burlington, Chittenden, Vermont

Credit: Ann Cousins

August 1999

Negative filed at U.S. ARMY CORPS OF ENGINEERS, NEW YORK DISTRICT

View looking south; Northern end of the main section of Breakwater

Photo #2





Burlington Breakwater  
Burlington, Chittenden, Vermont

Credit: Ann Cousins

August 1999

Negative filed at US ARMY CORPS OF ENGINEERS, NEW YORK DISTRICT

View looking North, Redstone Patch

Photograph #3



Burlington Breakwater

Burlington, Chittenden, Vermont

Credit: Ann Cousins

August 1999

Negative filed at US ARMY CORPS OF ENGINEERS, NEW YORK DISTRICT  
View looking Northwest, Navigational beacon at North  
end.

Photograph #4