



BENJAMIN SHOTWELL HOUSE # 1/13  
Edison Twp., Middlesex Co., N.J.  
Photo 1986, by Arthur Brecknell  
(negatives in photographer's file)

Facing northeasterly, front facade  
of house.

26 Runyon's Lane



BENJAMIN SHOTWELL HOUSE # 2/13  
Edison Twp., Middlesex Co., N.J.  
Photo 1986 by Arthur Brecknell  
(negatives in photographer's file)

Facing easterly, close-up of  
shingled west gable and front  
facade of house

26 Runyon's Lane



BENJAMIN SHOTWELL HOUSE # 3 / 13  
Edison Twp., Middlesex Co., N.J.  
Photo 1986, by Arthur Brecknell  
(negatives in photographer's file)

Facing southerly, view of rear  
wall of house, showing 1840s  
section (left) attached to house,  
low stone rubble foundation, and  
water table

26 Runyon's Lane



BENJAMIN SHOTWELL HOUSE... # 4/13  
Edison Twp., Middlesex Co., N.J.

Photo 1986, by Arthur Brecknell  
(negatives in photographer's file)

Facing south, close-up of wall of  
original house, showing small  
grilled window to lower level  
milk room and 9/6 sash in rear  
room

*26 Runyon's Lane*






BENJAMIN SHOTWELL HOUSE # 5/13

Edison Twp., Middlesex Co., N.J.

Photographer, Arthur Brecknell  
(negatives in his file) 1986

Facing east, close-up of west  
gable wall showing surviving old  
shingles and low foundation

*26 Rungon's Lane*



BENJAMIN SHOTWELL HOUSE # 6/13  
Edison Twp., Middlesex Co., N.J.  
Photo 1986, by Arthur Brecknell  
(negatives in photographer's file)

Close-up detail of course of  
shingled west gable wall, showing  
size and age of shingles

26 Rensselaer's Lane



BENJAMIN SHOTWELL HOUSE # 7/13  
Edison Twp., Middlesex Co., N.J.  
Photo 1986, by Arthur Brecknell  
(negatives in photographer's file)

Facing northwesterly, corner fire-  
place in original dwelling room  
(southwest room)

*26 Reardon's Lane*



BENJAMIN SHOTWELL HOUSE # 8/13  
Edison Twp., Middlesex Co., N.J.  
Photo 1986, by Arthur Brecknell  
(negatives in photographer's file)

Facing easterly, looking across  
front room of 1840s addition to  
den created out of original kitchen  
leanto. (Fireplace opening  
has been closed.)

*26 Runyon's house*





BENJAMIN SHOTWELL HOUSE # 9/13  
Edison Twp., Middlesex Co., N.J.  
Photo 1986, by Arthur Brecknell  
(negatives in photographer's file)

Facing south, corner of sunken  
milk room, showing stone walls,  
step down, and rear face of pan-  
eled door


26 Runyon's Lane



BENJAMIN SHOTWELL HOUSE # 10/13  
Edison Twp., Middlesex Co., N.J.  
Photo 1986, by Arthur Brecknell  
(negatives in photographer's file)

Facing south, another view of  
corner of sunken milk room,  
showing paneled face of door  
leading to under-stairs area

26 Rensselaer's Lane



BENJAMIN SHOTWELL HOUSE # 11/13

Edison Twp., Middlesex Co., N.J.

Photo 1986, by Arthur Brecknell  
(negatives in photographer's file)

Detail: H-L hinge on rear flush  
face of paneled door between  
front and rear rooms of original  
house

*26 Rensselaer House*



BENJAMIN SHOTWELL HOUSE # 12/13

Edison Twp., Middlesex Co., N.J.

Photo 1986, by Arthur Brecknell

(negatives in photographer's file)

Facing northwesterly, rear garret room, showing original half-height of wall and how it was raised in 1840s.

*26 Runyon's Lane*





BENJAMIN SHOTWELL HOUSE # 13 of 13  
Edison Twp., Middlesex Co., N.J.  
Photo 1986, by Arthur Brecknell  
(negatives in photographer's file)

Facing southerly, front garret  
room of 1840s addition, reached  
by a step down from original  
section

*26 Rensselaer's Lane*