14. CONDITION ☐ EXCELLENT ☐ GOOD ☐ FAIR ☐ DETERIORATED ☐ RUINS: IS, DANGER OF DEMOLITION ☐ YES ☐ NO MUNKNOWN

16. SIGNIFICANCE

Built and designed in the era when the Park Service was producing its distinctive, rustic style architecture, this structure is a typical example of the comfort stations built with the form, materials, and detailing characteristic of that style. It is one of four extant stations of that style in the park and, despite its alterations, would contribute to a nomination of the park's rustic architecture to the National Register of Historic Places.

