



Pawtucket Congregational Church  
Pawtucket, Rhode Island *Providence County.*

Photographer unknown c. 1880 (?)  
Copy negative: Rhode Island Historical  
Preservation Commission

General view of auditorium looking east,  
showing original gallery front trim, pul-  
pit, and Serlian treatment of organ pipe  
casings; also, original stencilled ceiling.

10/6

APR 12 1978

*D.O.C*  
SEP 18 1978

**PROPERTY OF THE NATIONAL REGISTER**



Pawtucket Congregational Church  
Pawtucket, Rhode Island

*Providence County*

Warren Jagger, Photographer      February, 1978  
Negative: Rhode Island Historical Preservation  
Commission

View from the northwest, from Slater Mill Historic  
Site on the west bank of the Blackstone River,  
with Slater Mill in left foreground.

APR 12 1978

DOE  
SEP 18 1978

2 of 6

PROPERTY OF THE NATIONAL REGISTER



Pawtucket Congregational Church  
Pawtucket, Rhode Island *Providence County*

Warren Jagger, Photographer February, 1978  
Negative: Rhode Island Historical Preservation  
Commission

General view of narthex, looking north, showing  
original balustrade in middle ground and Federal  
Revival balustrades in foreground and background.

APR 12 1978 *DOE* 376  
SEP 18 1978

PROPERTY OF THE NATIONAL REGISTER



Pawtucket Congregational Church  
Pawtucket, Rhode Island, *Providence County.*

Warren Jagger, Photographer February, 1978  
Negative: Rhode Island Historical Preservation  
Commission

View from the southwest, showing hyphen and  
1936 Federal Revival parish house addition at  
far right.

APR 12 1978

DOE

SEP 18 1978

*2486*

PROPERTY OF THE NATIONAL REGISTER





Pawtucket Congregational Church  
Pawtucket, Rhode Island

*Providence County*

Warren Jagger, Photographer      February, 1978  
Negative: Rhode Island Historical Preservation  
Commission

General view of auditorium, looking toward the  
eastern, pulpit end.

APR 12 1978

*DOE*  
SEP 18 1978

*516*

PROPERTY OF THE NATIONAL REGISTER



Pawtucket Congregational Church  
Pawtucket, Rhode Island

*Providence County*

Warren Jagger, Photographer                      February, 1978  
Negative: Rhode Island Historical Preservation  
Commission

Detail of gallery staircase at pulpit end, showing  
original solid panel rail with thin applied Federal  
Revival moulding strips and original newel minus  
its heavy ball finial.

APR 12 1978

*DOE*

SEP 18 1978

*676*

PROPERTY OF THE NATIONAL REGISTER