



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

Ralph Hull Collection

Photographers: Air Graphics, Inc. Milwaukie, Ore.

Negative at Hull-Oakes Lumber Co.

23837 Dawson Road

Monroe, Ore. 97456

June 1980

1980 aerial view of Hull-Oakes Lumber Co., looking west (left) to east.

1 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

View of Hull-Oakes Lumber Co., looking east
to west and showing general setting.

2 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

Close-up view of Hull-Oakes Lumber Co. as shown from east to west,

3 of 78 photos



Ralph Hull Lumber Co, (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

View of Hull-Oakes Lumber Co. sawmill and lumber storage yard as seen from east to west.

4 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

George Wisner Photo

25124 Alpine Road

Monroe, Ore. 97456

Negative owned by George Wisner

January 1994

Hull-Oakes Lumber Co. main sawmill, north elevation.

5 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

George Wisner's Photo

25124 Alpine Road

Monroe, Ore. 97456

Negative owned by George Wisner

January 1994

West end of main sawmill at Hull-Oakes Lumber Co. showing north elevation of debarking shed, conveyor and entry to sawmill carriage.
6 of 78 photos



Ralph Hull Lumber Co. (Hull-Dakes Lumber Co.)

Benton County, Oregon

George Wisner's Photo

25124 Alpine Road


Monroe Ore. 97456

Negative owned by George Wisner

January 1994

South elevation of Hull-Dakes Lumber Co. main sawmill and west elevation of sawmill "green chain" for handling fresh-cut lumber.

7 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

View of Hull-Oakes Lumber Co. planing shed and lumber-storage buildings looking from northwest to southeast.

84 78 photos



Ralph Hull Lumber Co. (Hull-Oates Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Caldwell Hill Road


Wren, Ore, 97370

Negative owned by John Bragg

May 1993

Close-up of east elevation of lumber storage and
planing shed at Hull-Oates Lumber Co.

9 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg PHOTO

24004 Caldwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

Views of south side of planing mill at Hull-Oakes Lumber Co.

10 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

Ralph Hull Collection

Photographer Unknown

Negative at Hull-Oakes Lumber Co.

23837 Dawson Road

Monroe, Ore. 97456

Circa 1942

View of steam operated log hoist to put un-coming logs into
Hull-Oakes Lumber Co. log pond, looking east to west.

11 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

"A" frame for off-loading logs to log pond at Hull-Oakes
Lumber Co., looking EAST TO WEST.

12 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg PHOTO

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

In-feed conveyor to debarking machine at Hull-Oakes
Lumber Co., looking east to west.

13 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road

Wren Ore. 97370

Negative owned by John Bragg

May 1993

Looking from south to north at debarking shed on
log pond at the Hull-Oakes Lumber Co.

14 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg PHOTO

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

North elevation of boiler house at Hull-Oakes Lumber Co.
15 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

West elevation of boiler house at Hull-Oakes Lumber Co.

16 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cartwell Hill Road

Wren, Ore, 97370

Negative owned by John Bragg

May 1993

East and North elevations of boiler house at Hull-Oakes Lumber Co.
17 of 78 photos



Ralph Hull Lumber Co. (Hull-Oates Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

East elevation of boiler house at Hull-Oates Lumber Co.

18 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

North and west elevations of boiler house at Hull-Oakes Lumber Co.

19 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

East and North elevations of boiler house at Hull-Oakes Lumber Co.,
showing bark chipping shed and former refuse burner in background.

20478 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Caldwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

Interior of boiler house at Hull-Oakes Lumber Co. showing east-face boilers.

21 of 78 photos



Ralph Hull Lumber Co. (Hull-Oates Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

Basement view of boiler house at Hull-Oates Lumber Co. showing firebox doors.
22 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

November 1994

Fireman Jerry King pours fuel oil to fire the boilers at the Hull-Oakes Lumber Co.

23 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

November 1994

Fireman Jerry King touches the fire in fireboxes in the basement area of the boiler house at the Hull-Oakes Lumber Co.

24 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road


Wren, Ore, 97370

Negative owned by John Bragg

November 1994

Fireman Jerry King shovels sawdust fuel into the fireboxes beneath the Hull-Oakes Lumber Co. boiler house. George Wisner in background.

25 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)
Benton County, Oregon
John Bragg Photo
24004 Caldwell Hill Road
Wren, Ore. 97370
Negative owned by John Bragg
November 1994
Close-up of piping and gauges associated with the
boilers at the Hull-Oakes Lumber Co.
26 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

East elevation of the debarking shed at the Hull-Oakes Lumber Co.,
showing outflow conveyor!

27 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

Close-up of debarking mechanism at the Hull-Oakes Lumber Co.

28 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road


Wren, Ore. 97370

Negative owned by John Bragg

May 1993

Chain conveyor to main sawmill carriage at the Hull-Oakes Lumber Co., north elevation

29 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg PHOTO

24004 Cardwell Hill Road


Wren, Ore. 97370

Negative owned by John Bragg

May 1993

View showing log carriage "dogs" and other carriage operating controls at the Hull-Oakes Lumber Co.

30 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo


24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

View of carriage controls at the Hull-Oakes Lumber Co.
31 of 78 photos



Ralph Hull Lumber Co. (Hull-Dakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road


Wren, Ore. 97370

Negative owned by John Bragg

May 1993

Close-up of "dial" used to size lumber at the Hull-Dakes Lumber Co.
The "dial" is on the sawmill's carriage.

32 of 78 photos



Ralph Hull Lumber Co. (Hull-Cakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

Interior of Hull-Cakes Lumber Co. main sawmill, showing east-west end of carriage and head-rig bandsaw used to make primary lumber cuts.

33 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road


Wren, Ore. 97370

Negative owned by John Bragg

May 1993

Control seat for the head-rig bandsaw at the Hull-Oakes Lumber Co.,
just north of sawmill carriage and west of bandsaw.

34 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road


Wren, Ore. 97370

Negative owned by John Bragg

May 1993

Close-up of head-rig bandsaw at the Hull-Oakes Lumber Co.

35 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

November 1994

View of head-rig bandsaw being sharpened in saw-filing room at Hull-Oakes Lumber Co.

The saw filing room is just north of the bandsaw and carriage in the main sawmill.

36 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg photo


24004 Caldwell Hill Road

Wren Ore. 97370

Negative owned by John Bragg

November 1994

Close-up of nomenclature plate on the head-rig bandsaw at the Hull-Oakes Lumber Co.
37 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

November 1995

Bandsaw used as a resaw at the Hull-Oakes Lumber Co.,
and part of the main sawmill.

38 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg photo

24004 Cardwell Hill Road

Wren Ore. 97370

Negative owned by John Bragg

November 1995

Views of edger in the main sawmill at the Hull-Oakes Lumber Co.

39 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo


24004 Cardwell Hill Road

Wren, Ore, 97370

November 1995

Views of large timber saws at the Hull-Oakes Lumber Co. main sawmill.

40 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg PHOTO

24004 Caldwell Hill Road


Wren, Ore. 97370

Negative owned by John Bragg

May 1993

View of steam engine and setting under main sawmill at the Hull-Oakes Lumber Co.

41 of 78 photos



Ralph Hull Lumber Co. (Hull-Dakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

November 1994

View of operating steam engine at Hull-Dakes Lumber Co.,
with employee oiling the machinery and providing scale.

42 of 78 photos



Ralph Hull Lumber Co. (Hull-Dakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Caldwell Hill Road


Wren, Ore. 97370

Negative owned by John Bragg

November 1994

Employee oiling mechanisms on steam engine at the Hull-Dakes Lumber Co.

43 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road


Wren, Ore. 97370

Negative owned by John Bragg

May 1993

View of cylinder of steam engine at the Hull-Oakes Lumber Co.

44 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road


Wren, Ore, 97370

negative owned by John Bragg

May 1993

View of wheel on steam engine under the Hull-Oakes Lumber Co.

45 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road


Wren, Ore. 97370

Negative owned by John Bragg

May 1993

Views of governor on steam engine at the Hull-Oakes Lumber Co.

46 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Caldwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

Close-up of governor on steam engine at the Hull-Oakes Lumber Co.
47 of 78 photos



Ralph Hull Lumber Co. (Hull-Oates Lumber Co.)

Benton County, Oregon

John Bragg photo

24004 Cardwell Hill Road


Wren, Ore. 97370

Negative owned by John Bragg

June 1995

View of steam whistle mounted on auxiliary "steam engine"
for carriage at the Hull-Oates Lumber Co.

48478 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg PHOTO

24004 Cordwell Hill Road


Wren, Ore. 97370

Negative owned by John Bragg

June 1995

Wooden drive wheel at the Hull-Oakes Lumber Co. The wheel has been in operation at the mill since 1939.

49 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo


24004 Cardwell Hill Road

Wren, Ore, 97370

Negative owned by John Bragg

May 1993

Views of typical belting and gears on machinery at the Hull-Oakes Lumber Co.
50 of 78 photos



Ralph Hull Lumber Co. (Hull-Oates Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road


Wren, Ore. 97370

Negative owned by John Bragg

May 1993

Views of typical gearing and chain drives at the Hull-Oates Lumber Co.

51 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

View of AC/DC electric power system set up under the Hull-Oakes Lumber Co.
but never connected to operate the mill completely with electricity.

52 of 78 photos



Ralph Hull Lumber Co. (Hull-Oates Lumber Co.)

Benton County, Oregon

John Bragg photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

Views of the "wigwam" style refuse burner at the Hull-Oates Lumber Co.,
looking southwest from the sawmill carriage infeed.

53 of 78 photos



Ralph Hull Lumber Co. (Hull-Dakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

Views of "wigwam" style refuse burner at the Hull-Dakes Lumber Co.,
also showing log pond and west elevation of sawmill boiler house.

54 of 78 photos



Ralph Hull Lumber Co. (Hull-Dakes Lumber Co.)

Benton County, Oregon

John Bragg Photo

24004 Cardwell Hill Road

Wren, Ore. 97370

Negative owned by John Bragg

May 1993

Close-up of "wigwam" style refuse burner at the Hull-Dakes Lumber Co.

55 of 78 photos



HILL-OAKS
LUMBER CO.
MAIN OFFICE

Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

George Wisner Photo

25124 Alpine Road

Monroe, OR 97456

Negative owned by George Wisner

March 1994

Southwest elevation of business office at Hull-Oakes Lumber Co.

56 of 78 photos



Ralph Hull Lumber Co. (Hull-Dakes Lumber Co.)

Benton County, Oregon

George Wisner Photo

25124 Alpine Road

Monroe, Ore. 97456

Negative owned by George Wisner

March 1994

West elevation and entry to business office of Hull-Dakes Lumber Co.

57 of 78 photos



Ralph Hull Lumber Co. (Hull-Dakes Lumber Co.)

Benton County, Oregon

George Wisner Photo

25124 Alpine Road

Monroe, Ore. 97456

Negative owned by George Wisner

March 1994

South elevation of business office of Hull-Dakes Lumber Co.
58 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)
Benton County, Oregon
George Wisner Photo
25124 Alpine Road
Monroe, Ore. 97456
Negative owned by George Wisner
March 1994
Southeast elevation of business office of Hull-Oakes Lumber Co.
59 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

George Wisner Photo

25124 Alpine Road

Monroe, Ore. 97456

Negative owned by George Wisner

March 1994

Northeast elevation of business office of Hull-Oakes Lumber Co.
60 of 78 photos



Ralph Hull Lumber Co. (Hull-Dakes Lumber Co.)

Benton County, Oregon

George Wisner Photo

25124 Alpine Road

Monroe, Ore. 97456

Negative owned by George Wisner

March 1994

Northwest elevation of business office at Hull-Dakes Lumber Co.

1 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

Ralph Hull Collection

Ralph Hull Photo

Negative at Hull-Oakes Lumber Co.

23837 Dawson Road

Monroe, Ore. 97456

Circa 1939

View of former business office at Hull-Oakes Lumber Co.
with large timber and Margaret Hull in front.

62 of 78 photos



Ralph Hull Lumber Co. (Hull-Dakes Lumber Co.)

Benton County, Oregon

George Wisner Photo

25124 Alpine Road

Monroe, Ore. 97456

Negative owned by George Wisner

March 1994

Southeast elevation of former business office at Hull-Dakes Lumber Co.
63 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

George Wisner Photo

25124 Alpine Road

Monroe, Ore. 97456

Negative owned by George Wisner

March 1994

Southwest elevation of former business office at Hull-Oakes Lumber Co.

64 of 78 photos



Ralph Hull Lumber Co. (Hull-Dakes Lumber Co.)

Benton County, Oregon

George Wisner Photo

25124 Alpine Road

Monroe, Ore, 97456

Negative owned by George Wisner

March 1994

Southeast elevation of former business office at Hull-Dakes Lumber Co.,
showing fuel storage.

65 of 78 photos



Ralph Hull Lumber Co, (Hull-Dakes Lumber Co.)

Benton County, Oregon

George Wisner Photos

25124 Alpine Road

Monroe, Ore, 97456

Negative owned by George Wisner

March 1994

North elevation of former business office at Hull-Dakes Lumber Co.
by 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

George Wisner Photo

25124 Alpine Road

Monroe, Ore. 97456

Negative owned by George Wisner

March 1994

South elevation of truck maintenance garage at Hull-Oakes Lumber Co.
67 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

George Wisner Photos

25124 Alpine Road

Monroe, Ore. 97456

Negative owned by George Wisner

March 1994

East elevation of truck maintenance garage at Hull-Oakes Lumber Co.,
68 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

George Wisner Photo

25124 Alpine Road

Monroe, Ore. 97456

Negative owned by George Wisner

West elevation of truck maintenance garage at Hull-Oakes Lumber Co.
69 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

George Wisner Photo

25124 Alpine Road

Monroe, Ore, 97456

Negative owned by George Wisner

March 1994

Northwest elevation of truck maintenance garage at Hull-Oakes Lumber Co.,
70 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

Ralph Hull Collection

Photographer unknown

Negative at Hull-Oakes Lumber Co.,

23837 Dawson Road

Monroe, Ore. 97456

Circa 1938

Starting Reconstruction of Ralph Hull Lumber Co. sawmill following 1936 fire
that destroyed the W.J. Miller sawmill on the same site.

71 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

Ralph Hull Collection

Photographer unknown

Negative at Hull-Oakes Lumber Co.

23837 Dawson Road

Monroe, Ore, 97456

Circa 1938

Starting construction of main floor and supports for the Ralph Hull Lumber Co. sawmill.

72 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

Ralph Hull Collection

Photographer unknown

Negative at Hull-Oakes Lumber Co.

23837 Dawson Road

Monroe, Ore. 97456

Circa 1954

Concrete tunnel diverting Oliver Creek away from Hull-Oakes Lumber Co.,
shown under construction in 1954.

73 of 78 photos



Ralph Hull Lumber Co. (Hull-Cakes Lumber Co.)

Benton County, Oregon

Ralph Hull Collection

Photographer unknown

Negative at Hull-Cakes Lumber Co.

23837 Dawson Road

Monroe, Ore. 97456

Circa 1970

Frame for a log debarker under construction. View is looking west from main sawmill.

74 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

Ralph Hull Collection

Photographer Unknown

Negative at Hull-Oakes Lumber Co.,

23837 Dawson Road

Monroe, Ore. 97456

Circa 1959

Two forklifts carry a stack of long timbers at the Hull-Oakes Lumber Co.
Sawmills are no longer built to cut such long timbers.

75 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

Ralph Hull Collection

Photographer unknown

Negative at Hull-Oakes Lumber Co.

23837 Dawson Road

Monroe, Ore. 97456

Circa 1948

Largest timbers being pulled by straddle carrier from the Hull-Oakes Lumber Co.
76 of 78 photos



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)

Benton County, Oregon

Ralph Hull Collection

Photographer UNKNOWN

Negative at Hull-Oakes Lumber Co.


23837 Dawson Road

Monroe, Ore. 97456

Circa 1939

A young Ralph Hull sitting on porch of his Dawson home.

77 of 78 photographs



Ralph Hull Lumber Co. (Hull-Oakes Lumber Co.)
Benton County, Oregon
John Bragg Photo
24004 Cardwell Hill Road
Wren, Ore. 97370
Negative owned by John Bragg
November 1995
Ralph Hull at the Hull-Oakes Lumber Co.
78 of 78 photos