



Eck Larick home
The 13th and Lincoln Sts.
The Dalles, Oregon
Photo by Gladys Seufert
May, 1979

Moody (Malcolm A.) House
300 W. 13th St.
The Dalles, Wasco Co, Oregon
1 of 10 - North (front) eleva-
tion from W. 13th St.

Gladys Seufert photo, 1979
913 Laughlin Street
The Dalles, OR 97058

OCT 10 1980

AUG 13 1980



Detail of Eck Farick House

Thirteenth and Lincoln Sts.

The Dalles, Oregon

Photo by Gladys Seufert

May, 1979

Windows on front of house

Moody (Malcolm A.) House

300 W. 13th St.

The Dalles, Wasco Co., Oregon

2 of 10 - Detail of window bay
north elevation, probably

added in 1900-1915.

Gladys Seufert photo, 1979

913 Laughlin St.

The Dalles, OR 97058

OCT 10 1980

AUG 13 1980



Eck Rarick house
Thirteenth and Lincoln St.
The Dalles, Oregon Looking northwest

Photo by Gladys Seufert

May, 1979

Moody (Malcolm A.) House
300 W. 13th St.
The Dalles, Wasco Co, Oregon
3 of 10 - East (side) eleva-
tion, showing stone chimney
added c. 1900, and east bath-
room wing added 1915. South
wing incorporating original
kitchen area was extended to
present configuration in 1950.

AUG 13 1980

Gladys Seufert photo, 1979
913 Laughlin St.
The Dalles, OR 97058

OCT 10 1980



Eck Rarick House

Thirteenth and Lincoln Sts.

The Dalles, Oregon

Looking east

Photo by Gladys Seufert

May, 1979

Moody (Malcolm A.) House
300 W. 13th St.
The Dalles, Wasco Co, Oregon
4 of 10 - West elevation of
1950 kitchen extension.

OCT 10 1980

Gladys Seufert photo, 1979
913 Laughlin St.
The Dalles, OR 97058

AUG 12 1980



Eck Rosick home
Thirteenth and Lincoln Sts.
The Dalles, Oregon
Photo by Gladys Seufert
May, 1979

Looking northeast

Moody (Malcolm A.) House
300 W. 13th St.
The Dalles, Wasco Co, Oregon
5 of 10 - West and south elevations, showing gable-roofed main block and shed-roofed rear portion of original house. Bay window probably was added 1900-1915. Extension on west is bedroom added 1933.

AUG 13 1980

Gladys Seufert photo, 1979
913 Laughlin St.
The Dalles, OR 97058

OCT 10 1980



Front door

Eck Larick house

13^½ S Lincoln

The Dalles, Oregon

This is the original door
of the house when it
was built.

Photo by Gladys Seufert

Moody (Malcolm A.) House
300 W. 13th St.
The Dalles, Wasco Co., Oregon

6 of 10 - Front door, north
elevation, showing hand-finish
ed members. Glazing in upper
part of door is probably con-
temporary with other modifica-
tions of c. 1900-1915.

AUG 13 1980

Gladys Seufert photo, 1979
913 Laughlin St.
The Dalles, OR 97058

OCT 10 1980



Eck Larick house

Showing different level
from east end of living room
to west of living room and
bedroom.

Photo by Gladys Seufert

Jan. 1980

Moody (Malcolm A.) House
300 W. 13th St.
The Dalles, Wasco Co, Oregon

7 of 10 - Stone chimney piece,
east end of parlor, original

main block of house, added by
Malcolm Moody c. 1900.

Gladys Seufert photo, 1979
913 Laughlin St. AUG 13 1980
The Dalles, OR 97058



Window at east end of
living room.

Photo by Gladys Seufert
Jan, 1980

Eck Larick House

Moody (Malcolm A.) House
300 W. 13th St.
The Dalles, Wasco Co, Oregon

OCT 10 1980
8 of 10 - Detail view of
tongue and groove ceiling

cover and window in east end
wall of main block.

Gladys Seufert photo, 1979
913 Laughlin St. AUG 13 1980
The Dalles, OR 97058



Details of ceiling of living room (part of original house)

Eck Larick home

The tenth and Garrison Lincoln Sts.

The Dalles, Oregon

Photo by Gladys Seufert

May, 1979

Moody (Malcolm A.) House
300 W. 13th St.
The Dalles, Wasco Co., Oregon
9 of 10 - Detail view of one
of the set of scissors
trusses in original main
block of house AUG 13 1980

Gladys Seufert photo, 1979
913 Laughlin St.
The Dalles, OR 97058

0861 0 153



Windows in west end of living room

Eck Larick house

Photo by Gladys Seufert

Jan, 1980

1980
OCT 10 Moody (Malcolm A.) House
300 W. 13th St.
The Dalles, Wasco Co., Oregon

— 10 of 10 - Detail view of
— windows in the west end wall
of main block.

OCT 10 Gladys Seufert photo, 1979
913 Laughlin St.
The Dalles, OR 97058

AUG 13 1980