



10413

Gordonido/ Old Dawson Place  
Columbus, Muscogee County, Georgia  
Photographer: James R. Lockhart  
Negatives filed Dept. Natural Resources  
Photographer facing south  
Entrance hall, first floor  
August, 1978

NOV 20 1978

JAN 8 1979

PHOTOGRAPH BY  
JAMES R. LOCKHART FOR  
DEPT. OF NATURAL RESOURCES  
HISTORIC PRESERVATION SECTION  
CREDIT MUST BE GIVEN

GORDONIDO, MUSCOGEE CO. 8/78  
1ST FLOOR MAIN ENTRANCE  
FACING S.



Gordonido/ Old Dawson Place  
Columbus, Muscogee County, Georgia  
Photographer: James R. Lockhart  
Negatives filed Dept. Natural Resources  
Photographer facing west  
West front room, first floor  
August, 1978

*207/13*

NOV 20 1978

JAN 8 1979

PHOTOGRAPH BY  
JAMES R. LOCKHART FOR  
DEPT. OF NATURAL RESOURCES  
HISTORIC PRESERVATION SECTION  
CREDIT MUST BE GIVEN

*GORDONIDO, MUSCOGEE CO. 8/78  
1ST FLOOR WEST FRONT  
FACING W.*



Gordonido/Old Dawson Place  
Columbus, Muscogee County, Georgia  
Photographer: James R. Lockhart  
Negatives filed Dept. Natural Resources  
Photographer facing southwest  
Dining room, first floor  
August, 1978

30/13

NOV 20 1978

JAN 8 1979

PHOTOGRAPH BY  
JAMES R. LOCKHART FOR  
DEPT. OF NATURAL RESOURCES  
HISTORIC PRESERVATION SECTION  
CREDIT MUST BE GIVEN

GORDONIDO, MUSCOGEE CO. 8/78  
1ST FLOOR DINING ROOM  
FACING SW.



Gordonido/ Old Dawson Place  
Columbus, Muscogee County, Georgia  
Photographer: James R. Lockhart  
Negatives filed Dept. Natural Resources  
Photographer facing east  
First floor, east rooms  
August, 1978

40813

NOV 20 1978

JAN 8 1979

PHOTOGRAPH BY  
JAMES R. LOCKHART FOR  
DEPT. OF NATURAL RESOURCES  
HISTORIC PRESERVATION SECTION  
CREDIT MUST BE GIVEN.

GORDONIDO, MUSCOGEE CO.  
1ST FLOOR EAST REAR  
FACING E.





Gordonido/Old Dawson Place  
Columbus, Muscogee County, Georgia  
Photographer: James R. Lockhart  
Negatives filed Dept. Natural Resources  
Photographer facing north  
Entrance hall on first floor  
August, 1978

50713

NOV 20 1978

JAN 8 1979

PHOTOGRAPH BY  
JAMES R. LOCKHART FOR  
DEPT. OF NATURAL RESOURCES  
HISTORIC PRESERVATION SECTION  
CREDIT MUST BE GIVEN.

GORDONIDO, MUSCOGEE CO. 8/78  
1ST FLOOR MAIN ENTRANCE  
FACING N.



60713  
Gordonido/ Old Dawson Place  
Columbus, Muscogee County, Georgia  
Photographer: James R. Lockhart  
Negatives filed Dept. Natural Resources  
Photographer facing southeast  
Exterior, north and west facades  
August, 1978

NOV 20 1978

JAN 8 1979

PHOTOGRAPH BY  
JAMES R. LOCKHART FOR  
DEPT. OF NATURAL RESOURCES  
HISTORIC PRESERVATION SECTION  
CREDIT MUST BE GIVEN

GORDONIDO, MUSCOGEE Co. 8/78  
FACING S.E.



Gordonido/Old Dawson Place  
Columbus, Muscogee County, Georgia  
Photographer: James R. Lockhart  
Negatives filed Dept. Natural Resources  
Photographer facing southwest  
Rear facade  
August, 1978

70f/13

JAN 8 1979

NOV 20 1978

PHOTOGRAPH BY  
JAMES R. LOCKHART FOR  
DEPT. OF NATURAL RESOURCES  
HISTORIC PRESERVATION SECTION  
CREDIT MUST BE GIVEN

GORDONIDO, MUSCOGEE Co. 8/78  
REAR FACADE, FACING S.W.



Gordonido/ Old Dawson Place  
Columbus, Muscogee County, Georgia  
Photographer: James R. Lockhart  
Negatives filed Dept. Natural Resources  
Photographer facing north  
Second floor stair and hall  
August, 1978

87/13

JAN 8 1979

NOV 20 1978

PHOTOGRAPH BY  
JAMES R. LOCKHART FOR  
DEPT. OF NATURAL RESOURCES  
HISTORIC PRESERVATION SECTION  
CREDIT MUST BE GIVEN

GORDONIDO, MUSCOGEE CO. 8/78  
2ND FLOOR STAIRWAY  
FACING N.





1420

Gordonido/Old Dawson Place  
Columbus, Muscogee County, Georgia  
Photographer: James R. Lockhart  
Negatives filed Dept. Natural Resources  
Photographer facing north  
Front entrance  
August, 1978

90/13  
JAN 8 1979

NOV 20 1978

PHOTOGRAPH BY  
JAMES R. LOCKHART FOR  
DEPT. OF NATURAL RESOURCES  
HISTORIC PRESERVATION SECTION  
CREDIT MUST BE GIVEN

GORDONIDO, MUSCOGEE CO. 8/78  
FRONT ENTRANCE  
FACING N.



Gordonido/Old Dawson Place  
Columbus, Muscogee County, Georgia  
Photographer: James R. Lockhart  
Negatives filed Dept. Natural Resources  
Photographer facing north  
Front facade  
August, 1978

10 of 13

NOV 20 1978

JAN 8 1979

PHOTOGRAPH BY  
JAMES R. LOCKHART FOR  
DEPT. OF NATURAL RESOURCES  
HISTORIC PRESERVATION SECTION  
CREDIT MUST BE GIVEN

GORDONIDO, MUSCOGEE Co.  
FACING N.E.

8/78



Gordonids - probably 3000 years

11 of 13

"Gordonido"/Old Dawson Place

Columbus, Muscogee County, Georgia

Reproduced by James R. Lockhart

JAN 8 1979

Date: c. 1915-18

Negative filed: Georgia Department of  
Natural Resources

Photograph: Front and side view of  
structure; photographer facing northeast

NOV 20 1978



(c. 1870)

"Gordonido"/Old Dawson Place JAN 8 1979

Columbus, Muscogee County, Georgia

Reproduced by James R. Lockhart

Date: c. 1870

Negative filed: Georgia Department of  
Natural Resources

Photograph: Front facade; photographer  
facing north

NOV 20 1978

12 of 13





Gordonido/ Old Dawson Place  
Columbus, Muscogee County, Georgia  
Photographer: James R. Lockhart  
Negatives filed Dept. Natural Resources  
Photographer facing north  
Front elevation  
August, 1978

13 of 13

NOV 20 1978

JAN 8 1979

PHOTOGRAPH BY  
JAMES R. LOCKHART FOR  
DEPT. OF NATURAL RESOURCES  
HISTORIC PRESERVATION SECTION  
CREDIT MUST BE GIVEN

GORDONIDO, MUSCOGEE Co. 8/78  
FRONT ELEVATION FACING N.