



NAME: Vogl House

LOCATION: Masten's Corner, Delaware

Kent Co.

PHOTOGRAPHER: Ned Heite


DATE: March 1976

LOCATION OF NEG: Historic Preservation Section, Div. of
Historical & Cultural Affairs, Dover, DE

DESCRIPTION:

facade, from south west

PHOTOGRAPH NO: 1



PROPERTY OF THE NATIONAL REGISTER

NOV 7 1976



NAME: Vogl House

LOCATION: Masten's Corner, Delaware Kent Co.

PHOTOGRAPHER: Ned Heite


DATE: March 1976

LOCATION OF NEG: Historic Preservation Section, Div. of
Hist. & Cult. Affairs, Dover, Delaware

DESCRIPTION: Front Hall handpainted oak

PHOTOGRAPH NO.: 2

PROPERTY OF THE NATIONAL REGISTER





NAME: Vogl House

LOCATION: Masten's Corner, Delaware *Kent Co.*

PHOTOGRAPHER: Ned Heite

DATE: March 1976

LOCATION OF NEG: Historic Preservation Section, Div. of
Hist. & Cult. Affairs, Dover, Delaware

DESCRIPTION: *Gallery of Front Hall*

PHOTOGRAPH NO: *3*

PROPERTY OF THE NATIONAL REGISTER





NAME: Vogl House

LOCATION: Masten's Corner, Delaware *Kent Co.*

PHOTOGRAPHER: Ned Heite


DATE: March 1976

LOCATION OF NEG: Historic Preservation Section, Div. of
Hist. & Cult. Affairs, Dover, Delaware

DESCRIPTION: *Pod Room or former Dining Room*

PHOTOGRAPH NO: *4*

PROPERTY OF THE NATIONAL REGISTER





NAME: Vogl House

LOCATION: Masten's Corner, Delaware *Kent Co.*

PHOTOGRAPHER: Ned Heite

DATE: March 1976

LOCATION OF NEG: Historic Preservation Section, Div. of
Hist. & Cult. Affairs, Dover, Delaware

DESCRIPTION:

Facade, from southwest

PHOTOGRAPH NO: *5*

PROPERTY OF THE NATIONAL REGISTER



NOV 7 1976



NAME: Vogl House

LOCATION: Masten's Corner, Delaware *Kent Co.*

PHOTOGRAPHER: Ned Heite

DATE: March 1976

LOCATION OF NEG: Historic Preservation Section, Div. of
Hist. & Cult. Affairs, Dover, Delaware


DESCRIPTION:

*Front Hall
moulding*

showing interview

PHOTOGRAPH NO:

6



PROPERTY OF THE NATIONAL REGISTER NOV 7 1976



NAME: Vogl House

LOCATION: Masten's Corner, Delaware *Kent Co.*

PHOTOGRAPHER: Ned Heite

DATE: March 1976

LOCATION OF NEG: Historic Preservation Section, Div. of
Hist. & Cult. Affairs, Dover, Delaware

DESCRIPTION:

Rear of House from southwest

PHOTOGRAPH NO: *7*

PROPERTY OF THE NATIONAL REGISTER

NOV 7 1976





NAME: Vogl House

LOCATION: Masten's Corner, Delaware *Kent Co*

PHOTOGRAPHER: Ned Heite


DATE: March 1976

LOCATION OF NEG: Historic Preservation Section, Div. of
Hist. & Cult. Affairs, Dover, Delaware

DESCRIPTION:

PHOTOGRAPH NO: *8*

PROPERTY OF THE NATIONAL REGISTER



NOV 7 1976



NAME: Vogl House

LOCATION: Masten's Corner, Delaware *Kent Co.*

PHOTOGRAPHER: Ned Heite


DATE: March 1976

LOCATION OF NEG: Historic Preservation Section, Div. of
Historical & Cultural Affairs, Dover, DE

DESCRIPTION:

PHOTOGRAPH NO: *9*

PROPERTY OF THE NATIONAL REGISTER



NOV 7 1976