



Edgar Holloway Residence, Gilroy, CA

Darrel Shuck, 1980

7539 Egleberry St., Gilroy, CA (95020)

Facade & north elevations looking southwest.

JAN 28 1982

DEC 29 1981

1. of 6



Edgar Holloway Residence, Gilroy, CA  
Darrel Shuck, 1980  
7539 Egleberry St, Gilroy, CA (95020)  
South elevation looking northeast.

JAN 28 1982

DEC 29 1981



Edgar Holloway Residence, Gilroy, CA

Darrel Shuck, 1980

7539 Egleberry St., Gilroy, CA (95020)

South elevation showing attachment of rear  
addition to kitchen wing looking northeast.

JAN 28 1982

DEC 29 1981

3.016



Edgar Holloway Residence, Gilroy, CA  
Darrel Shuck, 1980  
7539 Egleberry St., Gilroy, CA (95020)  
West elevation, (rear) looking east.

JAN 28 1982

1991





Edgar Holloway Residence, Gilroy, CA  
Darrel Shuck, 1980  
7539 Eigleberry St., Gilroy, CA (95020)  
North elevation showing in-filled window  
in kitchen wing. & damaged chimney, (1979  
earthquake). Looking southeast.

DEC 29 1981

JAN 28 1982



Edgar Holloway Residence, Gilroy, CA  
Darrel Shuck, 1980  
7539 Egleberry St., Gilroy, CA (95020)  
Parlor divider w/Corinthian capitals  
looking northwest towards original living  
room.

DEC 29 1981



Edgar Holloway Residence, Gilroy, CA

Darrel Shuck, 1980

7539 Egleberry St., Gilroy, CA (95020)

Double sliding doors seperating dining  
from living room areas looking north from  
dining room.

JAN 28 1982

DEC 29 1981

7.07