



Waterman-Winsor Farm
Smithfield (Greenville), Rhode Island

Providence Co.

Photographer: Warren Jagger February 1980

Negative at: Rhode Island Historical Preservation Commission

MAY 28 1980

View of house from Austin Avenue, looking north
northeast; sugar maples frame the house along the
roadside; in the background is the barn.

Photo #1 *of 10*

JUN 27 1980



Waterman-Winsor Farm
Smithfield (Greenville), Rhode Island

Providence CO

Photographer: Warren Jagger February 1980
Negative at: Rhode Island Historical
Preservation Commission

MAY 28 1980

View of west flank of house; c. 1780 ell at left;
c. 1710 section at right; edge of cider mill wash-
house at far left.

Photo #2 *of 10*

JUN 27 1980



Waterman-Winsor Farm
Smithfield (Greenville), Rhode Island

providence co.

Photographer: Warren Jagger February 1980
Negative at : Rhode Island Historical
Preservation Commission

MAY 28 1980

View of fireplace in southwest parlor, undergoing
exploration.

Photo #3 *83*

JUN 27 1980



Waterman-Winsor Farm
Smithfield (Greenville), Rhode Island

Providence Co. **MAY 28 1980**

Photographer: Warren Jagger February 1980
Negative at: Rhode Island Historical
Preservation Commission

View of re-used stair-rail in back staircase, looking
west, showing bevel of rail and cut in rail and
stringcourse.

Photo #4

Photo #4 *2710*

JUN 27 1980



Waterman-Winsor Farm
Smithfield (Greenville), Rhode Island

Providence Co.

Photographer: Warren Jagger February 1980
Negative at: Rhode Island Historical
Preservation Commission

MAY 28 1980

View of Victorian porch post used at head of back
staircase; note also bevel chausfered haunch of gun-
stock post and, beside it, back side of two-panel door.

JUN 27 1980

Photo #5 of 10



Waterman-Winsor Farm
Smithfield (Greenville), Rhode Island

Providence Co.

Photographer: Warren Jagger February 1980

Negative at: Rhode Island Historical
Preservation Commission

MAY 28 1980

JUN 27 1980

View looking west in southeast chamber showing
fireplace at back of modern closet and narrow closet
or cupboard beside it.

Photo #6 of 10



Waterman-Winsor Farm
Smithfield (Greenville), Rhode Island

Providence Co.

Photographer: Warren Jagger February 1980
Negative at: Rhode Island Historical
Preservation Commission

MAY 28 1980

View looking northeast in rear ell, showing restored
kitchen fireplace and surround at left.

JUN 27 1980

Photo #7 *of 10*



Waterman-Winsor Farm
Smithfield (Greenville), Rhode Island

Providence Co.

Photographer: Warren Jagger February 1980
Negative at: Rhode Island Historical Preservation Commission

MAY 28 1980

View east behind house, showing wagon shed-wood shed
at left and barn at right.

Photo #8 *of 10*

JUN 21 1980



Waterman-Winsor Farm
Smithfield (Greenville), Rhode Island

Providence Co.

MAY 28 1980

Photographer: Warren Jagger February 1980
Negative at: Rhode Island Historical
Preservation Commission

View of cider-mill--wash house--feed-house looking
east. Former ice pond just visible behind building
at left.

Photo #9 *of 10*

JUN 27 1980



Waterman-Winsor Farm
Smithfield (Greenville), Rhode Island

Providence Co.

Copy Negative made February 1980

Negative at: Rhode Island Historical
Preservation Commission

MAY 28 1980

View of Winsor family and Winsor house c. 1911.
T. K. Winsor is seated holding son Stanley. His wife,
Fannie Ella (Sebillé) Winsor is seated at right and
daughter Martha is child in wicker rocker.

Photo #10710

JUN 27 1980