



SAINT JOSEPH'S 1930 HOSPITAL

Albuquerque, New Mexico

Main (south) facade, S.W. corner, view  
from Grand Avenue

Albuquerque Museum

Photographer unknown, 1935-1940.



SAINT JOSEPH'S 1930 HOSPITAL

Albuquerque, New Mexico

Main (south) facade, S.E. corner, view  
from Grande Avenue

Albuquerque Museum

Photographer unknown, early 1940's



SAINT JOSEPH'S 1930 HOSPITAL

Albuquerque, New Mexico

Main (south) facade, view from Grand Ave.

Albuquerque Historic Landmarks Survey

Chris Wilson, May 1978



SAINT JOSEPH'S 1930 HOSPITAL

Albuquerque, New Mexico

rear (north) facade, N.E. corner, view  
from north side parking lot

Albuquerque Historic Landmarks Survey

Chris Wilson, May 1978



ST. JOSEPH HOSPITAL

SAINT JOSEPH'S 1930 HOSPITAL

Albuquerque, New Mexico

Main entrance on south side, view from south.

Albuquerque Historic Landmarks Survey

Chris Wilson, May 1978



SAINT JOSEPH'S 1930 HOSPITAL

Albuquerque, New Mexico

detail, parapet on main entrance (southside)  
and tower behind, view from south side.

Albuquerque Historic Landmarks Survey

Chris Wilson, May 1978



SAINT JOSEPH'S 1930 HOSPITAL

Albuquerque, New Mexico

detail, brick work on west bay, view from  
south side.

Albuquerque Historic Landmarks Survey

Chris Wilson, May 1978