



MILLER
STATION

- 1) Name of Property: Musick Guard Station, #1027
- 2) City and State: Vicinity of Cottage Grove, OR
- 3) Photographer: Cindy Pack
- 4) Date: 6/85
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking northeasterly, view of main west-facing facade and south elevation of office/residence
- 7) Photograph Number: 15-01-1027-1



- 1) Name of Property: Musick Guard Station, #1027
- 2) City and State: Vicinity of Cottage Grove, OR
- 3) Photographer: Cindy Pack
- 4) Date: 6/85
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking northeasterly, view of main west-facing facade and south elevation of office/residence
- 7) Photograph Number: 15-01-1027-2



- 1) Name of Property: Musick Guard Station, Wood Storage #1606
- 2) City and State: Vicinity of Cottage Grove, OR
- 3) Photographer: Cindy Pack
- 4) Date: 6/85
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking northeasterly, view of west and south elevations of wood storage building.
- 7) Photograph Number: 15-01-1606



- 1) Name of Property: Musick Guard Station, Barn
#2404
- 2) City and State: Vicinity of Cottage Grove, OR
- 3) Photographer: Cindy Pack
- 4) Date: 6/85
- 5) Negative Location: USDA Forest Service, Regional
Office, Recreation Unit, CRM files.
- 6) Description: Looking northeasterly, view of west
and south elevations of barn
- 7) Photograph Number: 15-01-2404-2



- 1) Name of Property: Musick Guard Station, Barn
#2404
- 2) City and State: Vicinity of Cottage Grove, OR
- 3) Photographer: Cindy Pack
- 4) Date: 6/85
- 5) Negative Location: USDA Forest Service, Regional
Office, Recreation Unit, CRM files.
- 6) Description: Looking southwesterly, view of east
and north elevations of barn
- 7) Photograph Number: 15-01-2404-1



- 1) Name of Property: Musick Guard Station, Water Storage
- 2) City and State: Vicinity of Cottage Grove, OR
- 3) Photographer: Cindy Pack
- 4) Date: 6/85
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking northwesterly, view of south and east elevations of water storage structure
- 7) Photograph Number: 15-01-Mu-WS



- 1) Name of Property: Musick Guard Station, Pumphouse
- 2) City and State: Vicinity of Cottage Grove, OR
- 3) Photographer: Cindy Pack
- 4) Date: 6/85
- 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files.
- 6) Description: Looking west, view of east elevation of pumphouse
- 7) Photograph Number: 15-01-Mu-P