



Howard's Grist Mill  
26401 So. Highway 213  
Mulino, Clackamas County, Oregon

Dareth Lee Murray photo, 1980  
Route 4, Box 401  
Molalla OR 97042

1 of 13  
East and north elevations, looking SW  
from Highway 213.

DEC 1 1981

**DEC 10 1981**



Howard's Grist Mill  
26401 So. Highway 213  
Mulino, Clackamas County, Oregon

Dareth Lee Murray photo, 1980  
Route 4, Box 401  
Molalla, OR 97042

2 of 13

South and east elevations of mill as  
enlarged in 1890, showing lean-to  
warehouse addition on south end. Shake

clad hood over raised walkway is a  
recent reversible addition.

DEC 1 1981

DEC 10 1981



Howard's Grist Mill  
26401 So. Highway 213  
Mulino, Clackamas County, Oregon

Dareth Lee Murray photo, 1980  
Route 4, Box 401  
Molalla, OR 97042

3 of 13  
Detail of loading dock and second story  
overhang constructed 1890, east eleva-  
tion.

DEC 1 1981

DEC 10 1981





Howard's Grist Mill  
26401 So. Highway 213  
Mulino, Clackamas County, Oregon

Dareth Lee Murray photo, 1980  
Route 4, Box 401  
Molalla, OR 97042

4 of 13  
Detail of south elevation of warehouse  
addition.

DEC 1 1981

DEC 10 1981





Howard's Grist Mill  
26401 So. Highway 213  
Mulino, Clackamas County, Oregon

Dareth Lee Murray photo, 1980  
Route 4, Box 401  
Molalla, OR 97042

5 of 13  
West and south elevations from Milk  
Creek.

DEC 1 1981

DEC 10 1981



Howard's Grist Mill  
26401 So. Highway 213  
Mulino, Clackamas County, Oregon


Dareth Lee Murray photo, 1980  
Route 4, Box 401  
Molalla, OR 97042

6 of 13  
North and west elevations from Milk  
Creek.

DEC 1 1981

DEC 10 1981





DEC 10 1981


Howard's Grist Mill  
26401 So. Highway 213  
Mulino, Clackamas County, Oregon

Dareth Lee Murray photo, 1980  
Route 4, Box 401  
Molalla, OR 97042

7 of 13

DEC 1 1981

Detail of hewn timber framing in 1851  
core of mill, showing typical lamb's  
tongue chamfers on ground story posts.





DEC 1 0 1981

Howard's Grist Mill  
26401 So. Highway 213  
Mulino, Clackamas County, Oregon

Dareth Lee Murray photo, 1980  
Route 4, Box 401  
Molalla, OR 97042

8 of 13  
Weigh scale in ground story.

DEC 1 1981



Howard's Grist Mill  
26401 So. Highway 213  
Mulino, Clackamas County, Oregon

Dareth Lee Murray photo, 1980  
Route 4, Box 401  
Molalla, OR 97042

9 of 13

Detail of worm gear, or transfer auger  
believed to date from earliest period of  
Mill's use.

DEC 1 1981

DEC 10 1981



Howard's Grist Mill  
26401 So. Highway 213  
Mulino, Clackamas County, Oregon

Dareth Lee Murray photo, 1980  
Route 4, Box 401  
Molalla, OR 97042

10 of 13

Worm gear, or transfer auger believed  
to date from earliest period of Mill's  
use.

DEC 1 1981

DEC 10 1981



DEC 10 1981


Howard's Grist Mill  
26401 So. Highway 213  
Mulino, Clackamas County, Oregon

Dareth Lee Murray photo, 1980  
Route 4, Box 401  
Molalla, OR 97042

11 of 13  
Looking north in Mill's second story,  
showing original roof framing system.

DEC 1 1981





DEC 10 1981

Howard's Grist Mill  
26401 So. Highway 213  
Mulino, Clackamas County, Oregon

Dareth Lee Murray photo, 1980  
Route 4, Box 401  
Molalla, OR 97042

12 of 13  
Looking north at end wall in second  
story.

DEC 1 1981



Howard's Grist Mill  
26401 So. Highway 213  
Mulino, Clackamas County, Oregon

Dareth Lee Murray photo, 1980  
Route 4, Box 401  
Molalla, OR 97042

13 of 13

"Monitor Dustless Receiving Separator"  
in north end of Mill's second story.

DEC 1 1981

DEC 10 1981