

KROMER HOUSE Albuquerque, New Mexico Photograph by Harvey Hoshour 1962 Negative: Harvey Hoshour West wall of living room before restoration; camera faces E



KROMER HOUSE Albuquerque, New Mexico Photograph by Harvey Hoshour December, 1962 Negative: Harvey Hoshour West wall of living room and master bedroom after restoration; camera faces NE Photograph #2



KROMER HOUSE Albuquerque, New Mexico Photograph by Harvey Hoshour 1968 Negative: Harvey Hoshour East facade; camera faces W



KROMER HOUSE Albuquerque, New Mexico Photograph by Harvey Hoshour 1968 Negative: Harvey Hoshour Entry room on east facade; camera faces W




KROMER HOUSE Albuquerque, New Mexico Photograph by Kathleen Brooker July, 1980 Negative: Historic Landmarks Survey of Albuquerque

Living room interior, facing north. Photograph #5



KROMER HOUSE Albuquerque, New Mexico Photograph by Kathleen Brooker July, 1980 Negative: Historic Landmarks Survey of Albuquerque Living room, facing south



KROMER HOUSE Albuquerque, New Mexico Photograph by Kathleen Brooker July, 1980 Negative: Historic Landmarks Survey of

Albuquerque Dining room interior; camera faces SE



TOM KROMER HOUSE ALBLIO. NM CHRISTOPHER PAVIS JULY 24, 1980 HISTORIC LANDMARKS SURVEY - NEG. INTERIOR, FACING FAST, SITTING ROOM PHOTO # 15



TOM KROMER HOUSE ALBHO. NM HARVEY HOSHOUR HARDEY HOSHOUR - NEG. E ELEVATION; CAMERA FACING

PHOTO #9



TOM KROMER HOUSE ALBHO. NM HARVEY HOSHOUP. HARVEY HOSHOUR - NEG. Intersection of S.ELEVATION AND W. ELEVATION WINGS; CAMERA FACING NORTH. PHOTO # 10



Tom Kromer House ALBHQ. NM HARVEY HOSHOUR HARVEY HOSHOUR - NEG.S E-ELEVATION OF HOUSE; CAMERA. FACING SOUTH PHOTO #11



TOM KROMER HOUSE ACBLIQ. NM. KATHLEEN BROOKER JULY 24, 1980 HISTORIC CANDMARKS SURVEY - NEG SHED AND GARAGE EAST OF HOUSE; FACING EAST PHOTO #8

File 187, New 12




TOM KROMER HOUSE ALBHA. NM KATHLEEN BROOKER JULY 24, 1980 HISTORIC CANDMARKS SURDEY NEGATIVE FILE # 187, Neg # 10 SOUTH ELEVATION OF HOUSE (KITCHEN) CAMERA FACING NORTH

PHOTO #12



TOM KROMER HOUSE ACBHQ. NM. CHRIS DAVIS JULY 24, 1980 HISTORIC CANDMARKS SURVEY NEG. - File 187, Neg 9 PATIO WEST OF HOUSE AND SIELEVATIONS OF HOUSE; CAMERA FACING N. PHOTO #13



CHRIS PAUIS JULY 24, 1980 HISTORIC CANOMARKS SURVEY - NEG. INTERIOR, FACING S., SITTING ROOM PHOTO # 14 Neg · file 188 , Neg. 13A-14

TOM KROMER HOUSE

ALBHO. NM



ALBHQ. NM CHRIS DAVIS JULY 24, 1980 HISTORIC CANDMARKS SURVEY-NEG INTERIOR, FACING SE, SITTING ROOM PHOTO #16

NEG. FILE # 188, Neg 134-14

TOM KROMER



CHRIS DAVIS JULY 24, 1980 HISTORIC CANDMARKS SURVEY - NEG INTERIOR, ENTRY HALL, FACING E. PHOTO # 17 File 188, New 15A-16

TOM KROMER HOUSE

ALBHO. NM



KROMER HOUSE 1024 EL PUEBLO NW WEST SIDE > SOUTH North

1946

KROMER HOUSE

ALBHO. NM

PHOTOGRAPHER PROBABLY DRAPPOERHER

1946

NEGATIVE: H. HOISHOUR

CAMERA FACES SOUTH

PHOTO #19



KROMER HOUSE 1024 EL PUEBLONW EAST SIDE OLD PUMP HOUSE LEFT OF LADDER WAS STILL THERE IN 1962.

BUTTRESS ADDED in 1947 UNDER 2 Dining - ROOM WINDOWS.

FALL 1946

KROMER HOUSE
ACRHO NAM
PHOTOGRAPHER PROBABLY DRYPOUGHER
1946, FALL
NEGATIVE: H. HOSHOUR
CAMERA FACES SOUTH
PHOTO # 19



KROMER HOUSE 1024 EL PUEBLO NW WEST SIDE > NORTH MR. DRYPOLHER* by AWALL WHICH WAS NOT THERE IN 1962.

MR. SMRS COUIS DRYPOLCHER WERE TENANTS

PHOTO # 20

KROMER HOUSE

ACBLIQ. NM

PHOTOGRAPHER PROBABLY PRYCHOLCHER

1946

NEG.; H. HOSHOUR

CAMERA FAGING NORTH



KROMER HOUSE 1024 EL PUEBLONW MRS. DRYPOLLHER IN WHAT IS NOW DINING -ROOM.

XMAS 1946

KROMER HOUSE ACBHQ. NM PHOTOGRAPHER PROBABLY DRIVER 1946, xmas NEG. H HOSHOUR CAMERA FACING PHOTO #21

POLCHER



KROMER HOUSE 1024 EL PUEBLONW WEST SIDE LOOKing South WEEPING WILLOW in FOREGROUND HAD TO BE Removed because it WAS Decessed. HOSHNRS adoled MECHA. NICAL ROOM in corner WALL 1946

KROMER HOUSE
ALBILO. NM
PHOTOGRAPHER PROBABLY PRACROCERER
1946
NEGATIVE: H. HOSHOUR
CAMERA FACES SOUTH
PHOTO #1912