



NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

1. NAME COMMON		AND/OR HISTORIC	NUMERIC CODE (Assigned by NPS)
Alexander Bradford House		Same	JUN 27 1974
2. LOCATION STATE		COUNTY	TOWN
Kentucky		Scott	Stamping Ground
STREET AND NUMBER			
Main Street at Locust Fork Pike			
3. PHOTO REFERENCE PHOTO CREDIT		DATE	NEGATIVE FILED AT
Ann B. Bevins		April 9, 1974	Route # 4, Lexington Pike Georgetown, Kentucky
4. IDENTIFICATION DESCRIBE VIEW, DIRECTION, ETC.			



Front view of structure facing Main Street, showing damage done by tornado which struck the area April 3, 1974.



UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

1. NAME		
COMMON	AND/OR HISTORIC	NUMERIC CODE (Assigned by NPS)
Alexander Bradford House	Same	JUN 27 1974
2. LOCATION		
STATE	COUNTY	TOWN
Kentucky	Scott	Stamping Ground
STREET AND NUMBER		
Main Street at Locust Fork Pike		
3. PHOTO REFERENCE		
PHOTO CREDIT	DATE	NEGATIVE FILED AT
Ann B. Bevins	April 9, 1974	Route # 4, Lexington Pike Georgetown, Kentucky
4. IDENTIFICATION		
DESCRIBE VIEW, DIRECTION, ETC.		

View of interior doorway in later wing. Trim matches detail on mantel in other enclosed photograph.





NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

1. NAME		
COMMON	AND/OR HISTORIC	NUMERIC CODE (Assigned by NPS)
Alexander Bradford House	Same	JUN 27 1974
2. LOCATION		
STATE	COUNTY	TOWN
Kentucky	Scott	Stamping Ground
STREET AND NUMBER		
Main Street at Locust Fork Pike		
3. PHOTO REFERENCE		
PHOTO CREDIT	DATE	NEGATIVE FILED AT
Ann B. Bevins	April 9, 1974	Route # 4, Lexington Pike Georgetown, Kentucky
4. IDENTIFICATION		
DESCRIBE VIEW, DIRECTION, ETC.		

View of stairway in older portion of house.



