



Plantation House

Hermitage

Coral Bay Quarter, St. John, Virgin Islands

Photo credit F.C. Gjessing, Date of photo 11/25/75

Negative filed at Virgin Islands National Park

North entrance to ground floor of Plantation House
H-37,1 viewed from the interior (south).

JUN 8 1981



Cook House

Hermitage

Coral Bay Quarter, St. John, Virgin Islands

Photo credit: F. C. Gjessing, Date of photo 11/25/75
Negative filed at Virgin Islands National Park

Cook houlse (left) and cistern of plantation house
H-37,1 viewed from the east.

JUN 8 1981

JUL 23 1981 2 of 6



Plantation House

Hermitage

Coral Bay Quarter, St. John, Virgin Islands

Photo credit: F.C. Gjessing, Date of photo 7/6/76

Negative filed at Virgin Islands National Park

Plantation House H-37, 1 north side of building with a section of Cistern No. 1 showing to the left in the photo.



Bake Oven and Cook House ~~Big range~~

Hermitage

Coral Bay Quarter, St. John, Virgin Islands

Photo Credit F. C. Gjessing, Date of Photo 7/6/76
Negative filed at Virgin Islands National Park

The remains of the bake oven and masonry cooking range
in the cook house of the Plantation House viewed from
the west, H-37,1

JUL 23 1981 JUN 8 1981 4 of 6



Quarters No. 2

Hermitage

Coral Bay Quarter, St. John, Virgin Islands

Photo Credit: F. C. Gjessing Date of photo 7/6/76

Negative viled at Virgin Islands National Park

West wall of Quarters No. 2 (H-37,7) viewed from the south.



Quarters #4

Hermitage

Coral Bay, Quarter, St. John, Virgin Islands

Photo credit F. C. Gjessing Date of photo 7/6/76

Negative filed at Virgin Islands National Park

Quarters No. 4, H-37,9 viewed from the southwest, note the remains of the collapsed wood superstructure.