


Photo No. 1 - Routhland Natchez, Adams County, Mississippi AllG 2 2 1977 Mississippi Department of Archives and History FEB 15 1977

The landscaped park, viewed from the front drive, looking north up the hill to the southwest facade and the southeast side of the house.



Natchez, Adams County, Mississippi Ronald W. Miller AUG 2 2 1977 Mississippi Department of Archives and History FEB 1 5 1977 1976 The southwest facate of the house and one of the live oak prees original to the landscaped park, viewed from the lawn within the circular front drive, looking northeast

Photo No. 2 Routhland



Natchez, Adams County, Mississippi 2 2 1977 Ronald W. Miller Mississippi Department of Archives and History FEB 1 5 1977 1976

Photo No. 3 % Routhland

The back of the house with the original dormers and back gallery visible at the right and the side of the rear dining wing visible at the left, viewed from the side of the rear lawn, looking south-southeast.



Photo No. 4 % Routhland Natchez, Adams County, Mississippi 912 Main Street, Natchez, Ms. 39120 1976 FEB 1 5 1977 The double parlors in the first portion of the house. located to the northwest of the central hall and remodeled in the mid-nineteenth century, viewed from the front parlor, looking north.




Photo No. 5% Routhland Natchez, Adams County, Mississippi Ronald W. Miller Mississippi Department of Archives and History FEB 1 5 1977 1976 The room in the south corner of the present house, view looking north to the mantelpiece and woodwork which were moved in the midnineteenth century from the original portion

of the house to this newly-constructed wing.



Natchez, Adams County, Mississippi AUG 22 1977 Ronald W. Miller Mississippi Department of Archives and History FEB 1 5 1977 1976 The front doorway on the southwest facade

of the house, viewed from the paving at the foot of the front steps, looking northeast.

Photo No. 6 Routhland