



PHOTO 1

David Perry House

Bridgeport, Connecticut

FACADE AND SOUTH SIDE ELEVATION

LOOKING NORTHWEST

C. Brilvitch photo

February 1979

Negative on file Conn.

Historical Commission



EAST BRIDGEPORT
RESTORATION INC
366-6418

PHOTO 2

David Perry House

Bridgeport, Connecticut

FACADE AND SOUTH SIDE ELEVATION

DURING RESTORATION

C. Brilvitch photo

December 1980

Negative on file Conn.

Historical Commission



1826

PHOTO 3

David Perry House

Bridgeport, Connecticut

FACADE AND SOUTH SIDE ELEVATION

FOLLOWING RESTORATION

C. Brilvitch photo

September 1981

Negative on file Conn.

Historical Commission

EAST BRIDGEPORT
RESTORATION
co.
366-4648



PHOTO 4
David Perry House
Bridgeport, Connecticut
PORTICO UNDER CONSTRUCTION
C. Brilvitch photo
December 1980
Negative on file Conn.
Historical Commission



PHOTO 5

David Perry House

Bridgeport, Connecticut

SOUTH SIDE ELEVATION PRECEEDING
RESTORATION

C. Brilvitch photo

August 1979

Negative on file Conn.

Historical Commission



PHOTO 6
David Perry House
Bridgeport, Connecticut
SOUTH SIDE ELEVATION DURING
RESTORATION

C. Brilvitch photo

December 1980

Negative on file Conn.

Historical Commission



PHOTO 7

David Perry House

Bridgeport, Connecticut

SOUTH SIDE ELEVATION FOLLOWING
RESTORATION

C. Brilvitch photo

September 1981

Negative on file Conn.

Historical Commission



PHOTO 8

David Perry House

Bridgeport, Connecticut

NEWELL CAP DETAIL, MAIN STAIR-
CASE

Paul Chudy photo

August 1979

Negative on file Conn.

Historical Commission



PHOTO 9

David Perry House

Bridgeport, Connecticut

HALL ARCHWAY DETAIL

Paul Chudy photo

August 1979

Negative on file Conn.

Historical Commission



PHOTO 10

David Perry House

Bridgeport, Connecticut

PARLOR MANTELPIECE

Paul Chudy photo

August 1979

Negative on file Conn.

Historical Commission




PHOTO 11

David Perry House

Bridgeport, Connecticut

PARLOR MANTELPIECE DETAIL

Paul Chudy photo

August 1979

Negative on file Conn.

Historical Commission



PHOTO 12

David Perry House

Bridgeport, Connecticut

DINING ROOM MANTELPIECE

Paul Chudy photo

August 1979

Negative on file Conn.

Historical Commission




PHOTO 13

David Perry House

Bridgeport, Connecticut

SECOND-FLOOR BEDROOM MANTELPIECE

Paul Chudy photo

August 1979

Negative on file Conn.

Historical Commission





PHOTO 14

David Perry House

Bridgeport, Connecticut

ENTRY LEADED GLASS LIGHTS

C. Brilvitch photo

September 1981

Negative on file Conn.

Historical Commission